



AlteonOS

RELEASE NOTES

Version 32.2.14.0
September 30, 2022



TABLE OF CONTENTS

| | |
|---|-----------|
| CONTENT | 9 |
| RELEASE SUMMARY..... | 9 |
| SUPPORTED PLATFORMS AND MODULES | 9 |
| UPGRADE PATH | 10 |
| Before Upgrade – Important!..... | 10 |
| General Considerations..... | 10 |
| Downgrade | 11 |
| WHAT’S NEW IN 32.2.14.0 | 11 |
| WHAT’S NEW IN 32.2.13.0 | 11 |
| Integrated AppWall | 11 |
| Signature Operation Mode | 11 |
| WebSocket | 12 |
| Server-Side Request Forgery | 12 |
| WHAT’S NEW IN 32.2.12.0 | 13 |
| Integrated AppWall | 13 |
| WebSocket | 13 |
| API Security..... | 14 |
| Advanced Base64 Attack in HTTP Headers | 15 |
| WHAT’S NEW IN 32.2.11.0 | 15 |
| SameSite Cookie Attribute | 15 |
| Integrated AppWall | 15 |
| WebSocket | 15 |
| Base64 Heuristic Detection..... | 17 |
| Multiple Encoded Attacks..... | 17 |
| HTTP Header Inspection with the Database Filter | 17 |
| Maximum Active Connection Alert | 18 |
| WHAT’S NEW IN 32.2.10.0 | 19 |
| Integrated AppWall | 19 |
| WHAT’S NEW IN 32.2.9.0 | 19 |
| AppWall Features | 19 |
| WHAT’S NEW IN 32.2.8.0 | 21 |
| WHAT’S NEW IN 32.2.7.0 | 21 |

| | |
|--|-----------|
| DNS Nameserver (NS) Records Support..... | 21 |
| Secure Password Policy..... | 21 |
| WHAT'S NEW IN 32.2.6.0 | 22 |
| Integrated AppWall – API Security | 22 |
| Alteon VA – VMware ESXi 7.0 Support | 22 |
| SHA2 and AES-256 Support for SNMPv3 | 22 |
| TCP SACK Control on Management Port | 22 |
| WHAT'S NEW IN 32.2.5.0 | 23 |
| Synchronization of Cluster Persistent Data (first introduced in version 32.2.4.60) | 23 |
| WHAT'S NEW IN 32.2.4.0 | 23 |
| High Availability Enhancements | 23 |
| AppShape++ Enhancements | 24 |
| AppWall Enhancements | 24 |
| Anti-Scraping Thresholds per URI | 24 |
| Forensics Filters..... | 24 |
| WHAT'S NEW IN 32.2.3.0 | 25 |
| Smart Session Table Adjustment | 25 |
| New SLB Metric – Highest Random Weights (HRW)..... | 26 |
| WHAT'S NEW IN 32.2.2.0 | 26 |
| Documentation in HTML Format | 26 |
| Management Login with SSH Key..... | 27 |
| OpenSSL Upgrade | 27 |
| OCSP Multiple Servers | 27 |
| WHAT'S NEW IN 32.2.1.0 | 27 |
| Virtual Service Traffic Events | 27 |
| ADC Analytics: System and Network Dashboard and Reports..... | 28 |
| System and Network Dashboard Main Screen | 28 |
| System Dashboard Screen | 29 |
| Network Dashboard Screen | 30 |
| SSL Enhancements..... | 30 |
| OCSP Enhancements | 30 |
| Support Subject Alternative Name Field..... | 30 |
| Display Certificate Serial Number in Certificate Repository..... | 31 |
| ICAP Enhancements | 31 |
| AppWall Enhancements | 32 |
| HTTP Strict Transport Security Support | 32 |

| | |
|---|-----------|
| Cookie Security Enhancement..... | 32 |
| Security Page Enhancement..... | 32 |
| New Web UI | 33 |
| Logging Enhancements..... | 33 |
| Logs per Health Check..... | 33 |
| Alteon Session Logs via Management Port | 33 |
| Keys Import on Alteon 6024 FIPS | 33 |
| WHAT'S NEW IN 32.2.0.0 | 34 |
| Application Dashboard and Reporting | 34 |
| Application Dashboard Main Screen..... | 34 |
| Per Application – Analytics..... | 35 |
| Per Application – SSL | 36 |
| Alteon Cluster on Azure | 36 |
| Real Servers Auto Scaling support on AWS | 38 |
| Real Servers Auto Scaling Support on VMware | 38 |
| New Alteon Platform Series (9800) | 38 |
| Alteon 6024 NEBS Certification | 39 |
| SSL | 39 |
| TLS 1.2 Session Tickets Support..... | 39 |
| Session Ticket Key Mirroring | 40 |
| OCSP Stapling | 40 |
| AppWall | 41 |
| New Fingerprint-based Tracking Mechanism | 41 |
| WebSocket Support | 42 |
| New Web UI Interface | 42 |
| New AS++ Command – whereis | 43 |
| Hardware Health Monitor | 43 |
| WHAT'S CHANGED IN 32.2.14.0 | 44 |
| AppWall Integrated | 44 |
| WHAT'S CHANGED IN 32.2.13.0 | 44 |
| HTTP/HTTPS Health Check..... | 44 |
| QAT Driver/Engine Upgrade | 44 |
| OpenSSL Upgrade | 44 |
| AppWall Integrated | 44 |
| WHAT'S CHANGED IN 32.2.12.0 | 45 |
| AppWall Integrated | 45 |

| | |
|--|-----------|
| WHAT'S CHANGED IN 32.2.11.0 | 45 |
| WHAT'S CHANGED IN 32.2.10.0 | 45 |
| OpenSSL Version..... | 45 |
| AppWall Enhancements | 46 |
| WHAT'S CHANGED IN 32.2.9.0 | 46 |
| AppWall Features | 46 |
| WHAT'S CHANGED IN 32.2.8.0 | 47 |
| DNS Resolver Enhancements..... | 47 |
| Response for Unsupported Record Types (first introduced in version 32.6.3.50)..... | 47 |
| OpenSSL Version..... | 47 |
| Treck Version | 47 |
| WHAT'S CHANGED IN 32.2.7.0 | 47 |
| Increased Tunnels and Static Tunnel Routes Configuration Capacity..... | 47 |
| User Role can be Restricted from Viewing the Syslog Logs..... | 47 |
| Enlarge Login Banner Size..... | 48 |
| WHAT'S CHANGED IN 32.2.6.0 | 48 |
| OpenSSL Upgrade | 48 |
| Real Server Tracking Logic Changes in WBM..... | 48 |
| Treck Version Upgrade to 6.0.1.66 | 48 |
| WHAT'S CHANGED IN 32.2.5.50 | 49 |
| TLS Version Default | 49 |
| WHAT'S CHANGED IN 32.2.5.0 | 49 |
| Syslog Enhancements..... | 49 |
| Increase of the Number of Syslog Servers to Six | 49 |
| OpenSSL Version..... | 49 |
| TLS Allowed Versions Default..... | 49 |
| Security Hardening | 49 |
| Client NAT Port Assignment Logic..... | 50 |
| WHAT'S CHANGED IN 32.2.4.0 | 50 |
| Health Check Source MAC | 50 |
| Banner Length..... | 50 |
| Alteon VA – Number of Supported NICs (Hyper-V, OpenXEN)..... | 50 |
| Integrated AppWall | 50 |
| Server Session Shutdown | 51 |
| OpenSSL Version..... | 51 |
| WHAT'S CHANGED IN 32.2.3.0 | 51 |
| Alteon User Password Encryption Enhancement | 51 |

| | |
|--|-----------|
| Audit Log via Telnet and SSH | 51 |
| BGP Support for Four-octet AS Number | 52 |
| Full Layer 3 Tunnel Support (IP-in-IP and GRE) – Phase 2 | 52 |
| Jumbo Frames..... | 52 |
| Failover Delay..... | 52 |
| WHAT'S CHANGED IN 32.2.2.50 | 52 |
| Fixed AppWall Performance Degradation | 52 |
| WHAT'S CHANGED IN 32.2.2.0 | 52 |
| WHAT'S CHANGED IN 32.2.1.0 | 53 |
| vDirect-Based Outbound SSLi Wizard (Layer 3 Deployment, Single Standalone Device)..... | 53 |
| SSL Inspection Deployment Support in VLAN Tag and Trunk | 53 |
| Fallback VLAN an Fallback Trunk Support..... | 53 |
| Trunk and VLAN Support in IDS-Chain | 54 |
| Virtual Service Manageability Enhancements..... | 54 |
| Update Session Entry-based on Gratuitous ARP | 55 |
| WHAT'S CHANGED IN 32.2.0.0 | 55 |
| Alteon VA Enhancements | 55 |
| Footprint Reduction..... | 55 |
| Improved Performance on Azure | 55 |
| GEL Support Enhancements..... | 55 |
| GEL License Activation..... | 55 |
| DPS Package Upgrade..... | 56 |
| GEL License Presentation on ADC-VX platforms..... | 56 |
| LLS Availability on Azure | 56 |
| Password Generator | 56 |
| Management IP Address in ADC-VX | 56 |
| Dual Power Supply for Alteon 4208 | 56 |
| SSL Key Replacement | 57 |
| SSL Inspection Wizard Enhancement..... | 57 |
| LinkProof MAC Overwrite..... | 57 |
| Allow Local and Remote Authentication..... | 57 |
| Health Check Enhancements..... | 58 |
| Graceful Health Check Edit..... | 58 |
| Advanced Virtual Wire Health Check..... | 58 |
| AppWall | 58 |
| AppWall in Transparent Mode..... | 58 |

| | |
|--------------------------------|-----------|
| Syslog Message Enrichment..... | 59 |
| Defense Messaging | 59 |
| Username Format | 59 |
| SSL Statistics and MIBs | 59 |
| MAINTENANCE FIXES | 59 |
| Fixed in 32.2.14.0 | 59 |
| General Bug Fixes | 59 |
| AppWall Bug Fixes..... | 59 |
| Fixed in 32.2.13.0 | 60 |
| General Bug Fixes | 60 |
| AppWall Bug Fixes..... | 60 |
| Fixed in 32.2.12.0 | 60 |
| General Bug Fixes | 60 |
| AppWall Bug Fixes..... | 61 |
| Fixed in 32.2.11.0 | 61 |
| General Bug Fixes | 61 |
| AppWall Bug Fixes..... | 61 |
| Fixed in 32.2.10.0 | 62 |
| General Bug Fixes | 62 |
| AppWall Bug Fixes..... | 62 |
| Fixed in 32.2.9.0 | 63 |
| General Bug Fixes | 63 |
| AppWall Bug Fixes..... | 64 |
| Fixed in 32.2.8.0 | 64 |
| General Bug Fixes | 64 |
| AppWall Bug Fixes..... | 67 |
| Fixed in 32.2.7.50 | 67 |
| General Bug Fixes | 67 |
| AppWall Bug Fixes..... | 70 |
| Fixed in 32.2.7.0 | 70 |
| General Bug Fixes | 70 |
| AppWall Bug Fixes..... | 72 |
| Fixed in 32.2.6.50 | 73 |
| General Bug Fixes | 73 |
| AppWall Bug Fixes..... | 75 |

| | |
|------------------------------------|------------|
| Fixed in 32.2.6.0 | 75 |
| General Bug Fixes | 75 |
| AppWall Bug Fixes..... | 79 |
| Fixed in 32.2.5.50 | 80 |
| General Bug Fixes | 80 |
| Fixed in 32.2.5.0 | 82 |
| General Bug Fixes | 82 |
| AppWall Bug Fixes..... | 83 |
| Fixed in 32.2.4.60 | 84 |
| General Bug Fixes | 84 |
| AppWall Bug Fixes..... | 86 |
| Fixed in 32.2.4.0 | 87 |
| General Bug Fixes | 87 |
| AppWall Bug Fixes..... | 91 |
| Fixed in 32.2.3.50 | 93 |
| Fixed in 32.2.3.0 | 95 |
| Fixed in 32.2.2.50 | 98 |
| Fixed in 32.2.2.0 | 100 |
| Fixed in 32.2.1.0 | 105 |
| Fixed in 32.2.0.0 | 112 |
| AppWall..... | 123 |
| Fixed in 32.1.0.0 | 125 |
| AppWall..... | 137 |
| Fixed in 32.0.1.101 | 138 |
| Fixed in 32.0.1.100 | 139 |
| Fixed in 32.0.1.0 | 139 |
| Fixed in 32.0.0.0 | 146 |
| KNOWN LIMITATIONS | 146 |
| RELATED DOCUMENTATION | 146 |



CONTENT

Radware announces the release of AlteonOS version 32.2.14.0. These release notes describe new and changed features introduced in this version on top of version 32.2.13.0.

RELEASE SUMMARY

Release Date: September 30, 2022

Objective: Minor software release that introduces and/or enhances a number of capabilities and solves a number of issues.

SUPPORTED PLATFORMS AND MODULES

This version is supported by the following platforms:

- 4208, 4208S
- 5224, 5224XL
- 5208, 5208 XL/Extreme, 5208S
- 6024, 6024 XL/Extreme, 6024S, 6024SL, 6024 FIPS II
- 6420, 6420 XL/Extreme, 6420S, 6420SL
- 6420p, 6420p XL/Extreme

Note: Memory usage has increased on Alteon versions 31.0.0.0 and later. Therefore, a 6420 platform with a default memory of 32 GB reaches 100% SP utilization very quickly. To use this version of Alteon on a 6420 platform, upgrade the RAM memory to at least 64 GB (factory installed or FUU).

- 7612S, 7612SL
- 7220S, 7220SL
- 8420, 8420 XL/Extreme, 8420S, 8420SL
- 8820, 8820 XL/Extreme, 8820S, 8820SL
- 9800, 9800S, 9800SL
- Alteon VA running on VMware ESXi 6.0, 6.5, 6.7, KVM, Hyper-V, and OpenXen
- Alteon VA on AWS
- Alteon VA on Azure
- Alteon VA on Nutanix
- Alteon VA on Oracle Cloud

For more information on platform specifications, refer to the *Alteon Installation and Maintenance Guide*.

Alteon 32.2.14.0 is supported by APSolute Vision version 4.10.100 and later.

Integrated AppWall version: 7.6.17.0

OpenSSL version:

- FIPS II model: 1.0.2u
- S/SL models, standard models and VA: 1.1.1n

UPGRADE PATH

You can upgrade to this AlteonOS from AlteonOS versions 28.x, 29.x, 30.x, 31.x and 32.x. General upgrade instructions are found in the *Alteon Installation and Maintenance Guide*.

Before Upgrade – Important!

1. Before performing an upgrade, back up your current configuration.
2. To ensure a successful upgrade, run the [Upgrade Advisor Tool](#) with your current configuration and the target version. Then, perform the required actions as instructed in the report output. The Upgrade Advisory Tool includes all the limitation and upgrade considerations specifically relevant to the source configuration, version, device details and target version. Make sure to update the Upgrade Advisory Tool DB before performing the analysis. The Upgrade Advisor Tool is available on the Customer Portal.
3. Read the [Upgrade Limitations](#) in these Release Notes for new upgrade limitations related to this version.

The following table describes the specific upgrade path from each version to 32.2.14.0:

| Current Version | Upgrade Path | Notes |
|------------------|--------------------------------------|--|
| 28.x | > 29.0.9.0 > 30.5.3.0 > this version | As an alternative, you can upgrade directly to 32.2.14.0 using the recovery process. Note: You must save the configuration before starting this process. |
| 29.0.x (x=<8) | > 29.0.9.0 > 30.5.3.0 > this version | |
| 29.0.x (x > 8) | > 30.5.3.0 > this version | |
| 29.5.x (x=<7) | > 29.5.8.0 > 30.5.3.0 > this version | |
| 29.5.x (x>7) | > 30.5.3.0 > this version | |
| 30.x =< 30.5.2.0 | > 30.5.3.0 > this version | |
| 30.x > 30.5.2.0 | Direct upgrade to this version | |
| 31.x | Direct upgrade to this version | |
| 32.x | Direct upgrade to this version | |

General Considerations

- Hypervisors (ADC-VX) running a certain version (for example, 31.0) only support vADCs that run the same version or later.

Downgrade

Configuration rollback (downgrade) is not supported. The configuration should be saved before upgrading to a newer version. If you perform version rollback, Radware recommends the following procedure:

1. Set the configuration block for the next boot to **factory** (the management port setting can be kept).
2. Change the image for the next boot to the image to which you want to roll back.
3. Perform reboot.
4. After reboot, Alteon will run with the previous version with the factory default configuration.
5. Upload the configuration that was saved before the version upgrade

WHAT'S NEW IN 32.2.14.0

None

WHAT'S NEW IN 32.2.13.0

Integrated AppWall

Signature Operation Mode


When AppWall retrieves an updated signature file (automatically or manually), it contains new signatures. Sometimes, these new signatures can generate false positives and block legitimate customer traffic.

In order not to block legitimate traffic, the new signatures will automatically be in *Passive* mode during a configurable period of time (7 days by default). There is no impact on the existing configuration (what is refined, stay refined). Only the new signatures are in *Passive* mode.

During the configurable period of time, the security engineer can evaluate the new signatures and eventually refine them. At the end of the time period, the new signatures automatically move from *Passive* to *Active* mode. This can be configured globally (all Application Paths will inherit from the global settings) or specifically per Application Path.

Signature Operation Mode can be turned off, globally or on a specific Application Path, if the customer wants to be protected immediately, after the signature update, if the application is exposed to a 0-day attack.

Note: Signature Operation Mode is available for Database Security filters and Vulnerabilities Security filter.



WebSocket

In this version, a few more options to configure WebSocket protection were added:

- Per Application Path: You can define if WebSocket protection is Active, Passive or Bypass.
- For the WebSocket payload, we can combine the structured and unstructured format (Text, JSON and XML can be combined with Binary).

Server-Side Request Forgery

In this version we reinforced SSRF protection. We complete the security coverage with more patterns.

Previously, we were only able to refine a URI or domain name. We can now also refine a specific parameter name.

We added also new REST API of the Unvalidated Redirect module in order to configure the pattern list related to LFI, RFI and SSRF.

WHAT'S NEW IN 32.2.12.0

Integrated AppWall

WebSocket

In the previous version support of the WebSocket protocol was introduced. In this version, the following WebSocket support was added:

- **Connection per source** - where the maximum number of connections that a source can open to a specific WebSocket application is defined.
- **Low & Slow attack mitigation** where we configure the following:
 - Time Gap Between Checks - The time span during which the AppWall is counting the traffic rate on the inspected connection.
 - Minimal traffic volume threshold to trigger protection.

Two minor changes were also introduced:

- The enforcement of the WebSocket server response payload type can be optional.
- When the WebSocket is in “block” mode in the Tunnel configuration, the client connection is closed with a Security Page and not with a TCP reset.

The screenshot shows the 'WebSocket settings' tab in the AppWall configuration interface. The settings are organized into several sections:

- WebSocket Inspection:** Includes a checked checkbox for 'WebSocket Inspection' and a text input for 'Allow idle Session Timeout (Min.)' set to 10.
- Connections per Source:** A text input set to 10.
- Slowloris:** Includes a checked checkbox for 'Protection Against "Low and Slow" Attacks', a text input for 'Time Gap Between Checks (Sec.)' set to 60, and a text input for 'Minimal Amount of Sent Data (KB)' set to 10.
- Maximum Frame Size (KB):** A text input set to 20.
- WebSocket Extension:** A dropdown menu set to 'Remove Extension'.
- Client Payload Type:** A dropdown menu set to 'JSON'.
- Server Payload Type:** A checked checkbox and a dropdown menu set to 'JSON'.
- Predefined Policies:** A dropdown menu set to 'Default' and a 'Set Policy' button.
- Mode:** A table with two rows: 'Vulnerabilities' and 'Database', both with a dropdown menu set to 'Active'.

API Security

In the API Security module, a new "Block" action for the endpoint's schema enforcement is added.

Previously, "Active", "Passive" and "Bypass" actions were supported. The new "Block" action will immediately block the client request. It manages use cases such as:

- When an endpoint is deprecated (for example, because of a bug) and the customer does not want any request to reach the API service, the deprecated endpoint can be in Block mode where the new endpoint can be in Active mode
- When an endpoint presents some security risks (for example, data leakage, 0-days attacks, injections) and the customer wants to immediately block any incoming request to this endpoint until it is fixed.

The screenshot displays the API Security configuration interface. At the top, the 'Action' dropdown is set to 'Active'. Below this is a 'Base Paths' section with a text input field containing '/'. The 'Endpoints' section features a search bar and several icons. A '+ Quota' button is located below the search bar. The main table lists endpoints with their respective quotas and actions. The first endpoint, '/api/v1/create/account', has a quota of '1 per minute' and its 'Action' is set to 'Block'. The second endpoint, '/api/v2/create/account', has a quota of '300 per minute' and its 'Action' is set to 'Active'. Red boxes highlight the 'v1' and 'v2' in the endpoint paths and the 'Block' and 'Active' action dropdowns.

| Endpoints (8) | Quota | Action |
|--------------------------|----------------|--------|
| > /api/v1/create/account | 1 per minute | Block |
| > /api/v2/create/account | 300 per minute | Active |



Advanced Base64 Attack in HTTP Headers

Following previous deliveries related to Base64 Heuristic Detection and Multiple Encoded attacks, in this version, we added support for multiple-encoded attacks in the HTTP header, such as harmful Injections, with the AppWall Database filter.

WHAT'S NEW IN 32.2.11.0

SameSite Cookie Attribute

The SameSite attribute of the Set-Cookie HTTP response header lets you declare if your cookie should be restricted to a first-party or same-site context.

The default cookie-sending behavior if the SameSite attribute is not specified in the cookie was recently changed to be as for SameSite Lax. In previous versions, the default was that cookies were sent for all requests (None). Most new browser versions support this new behavior while some browsers still behave according to the old default.

For that reason it is important to allow specifically setting the SameSite attribute with the requested value.

Alteon now allows the following:

- To specify the SameSite attribute value for the cookie inserted by Alteon for persistency purposes both via CLI and WBM and via AppShape++ (using the `persist cookie` command).
- To retrieve the SameSite attribute from a cookie or change its value via the following AppShape++ command: `HTTP::cookie samesite`
- To specify the SameSite attribute when inserting a cookie via the following command:
`HTTP::cookie insert`
- To change the SameSite attribute value for a cookie via the following command:
`HTTP::cookie set`

Integrated AppWall

WebSocket

In this version, WebSocket protocol support is added.

WebSocket is a communications protocol, providing bi-directional communication channels and enables streams of messages over a TCP connection. WebSockets are becoming increasingly popular, because they greatly simplify the communication between a client and a server.


The WebSocket protocol enables interaction between a client application and a web server with lower overhead, facilitating real-time data transfer from and to the server. This is made possible by providing a standardized way for the server to send content to the client without being first requested by the client and allowing messages to be passed back and forth while keeping the connection open. In this way, a two-way ongoing conversation can take place between the client and the server. To achieve compatibility, the WebSocket handshake uses the HTTP Upgrade Header to change from the HTTP protocol to the WebSocket protocol.

AppWall WebSocket support:

- At the tunnel level, you can define the WebSocket operation mode: Bypass, Block or Active (inspect the WebSocket traffic).



- Define a security policy per WebSocket application
- Define a specific WebSocket idle session timeout
- Set a maximum WebSocket frame size
- Define how AppWall behaves related to the WebSocket extensions:
 - Remove the extensions
 - Block traffic containing extensions
 - Ignore the extensions
- Define the Client-to-Server payload type (Binary, JSON, XML or Unstructured)
- Define the Server-to-Client payload type (Binary, JSON, XML or Unstructured)
- Support of Database Security and Vulnerabilities filters



Base64 Heuristic Detection

The way to detect a Base64 payload is not so obvious. If Base64 detection is not process correctly, it may be a source of false negatives or false positives (for example, payload with and without padding.).

Therefore, in this version we introduce a heuristic detection of Base64 payloads that increases accuracy in the attack detection.

In order to optimize performance, the configuration is opened to inspect the pre-decode values in addition to the post-decode values.


Multiple Encoded Attacks

In the previous release, we introduced support for multiple-encoded attacks for any parameter. In this version, we added the support for multiple-encoded attacks in the HTTP headers with the Vulnerabilities filter.

HTTP Header Inspection with the Database Filter

AppWall provides support for attacks in the HTTP headers, such as Injection and Cross-Site Scripting. You can configure AppWall to inspect HTTP headers with the Database filter.

You can also configure the way HTTP headers are to be inspected. The refinements can be done per-Virtual Directory from the Database filter configuration screen or the Quick-Click refinements from the Forensics view.



The screenshot shows a dialog box titled "Add Parameter or Header". It contains the following fields and controls:

- Name:** A text input field containing "User-Agent".
- Type:** A radio button group with "Parameter" and "Header". The "Header" option is selected.
- Type:** A dropdown menu showing "DATABASE FILTER INSPECTION".
- Buttons:** "OK" and "Cancel" buttons at the bottom right.

Maximum Active Connection Alert

AppWall can limit the number of connections for every AppWall tunnel (referred to as SECWA in the Alteon WAF). When AppWall receives the maximum limit of active connection in a tunnel, no new connections are opened.

In this version, we added the option to configure a threshold (in percentage) of active connections. When the threshold is reached, an alert is sent in the Forensics Security events before the maximum number of allowed active connections is reached and the connections queue gets completely full.

| | |
|----------------------------|------|
| Connections | |
| Maximum Active Connections | 1000 |
| Threshold | 85 % |

| | | |
|-----------------|---|--|
| Title: | Incoming Sessions Threshold above Limit | Description: |
| Date: | 6-Dec-2021 | Threshold of incoming sessions on Tunnel was above the limit. |
| Time: | 11:31:23 | TunnelName=88, ID=256, Limit=10, CurCount=4, Threshold=80 |
| Severity Level: | High | Request Data Response Data Details |
| Event ID: | 10 | |
| Server Name: | appwall Gateway | |
| Generated By: | Sub Systems - Tunnels | |
| Reported On: | Sub Systems - Tunnels | |
| Transaction ID: | | |

The events are reported in 1-minute intervals. If current active connections exceed the threshold, AppWall will report this event every minute.

When the number of active connections in the tunnel decreases below the threshold a system log event is reported:

| | | |
|-----------------|---|--|
| Title: | Incoming Sessions Threshold below Limit | Description: |
| Date: | 6-Dec-2021 | Threshold of incoming sessions on Tunnel was below the limit. |
| Time: | 12:49:56 | TunnelName=88, ID=256, Limit=10, CurCount=3, Threshold=80 |
| Severity Level: | High | Request Data Response Data Details |
| Event ID: | 13 | |
| Server Name: | appwall Gateway | |
| Generated By: | Sub Systems - Tunnels | |
| Reported On: | Sub Systems - Tunnels | |
| Transaction ID: | | |

Note: To configure an alert for this event with external logging, refer to the Knowledge base article ; [BP3182](#).

WHAT'S NEW IN 32.2.10.0

Integrated AppWall

Part of advanced security attacks, an attacker can now send a multiple encoded attack.

For example, the attacker can encode a parameter value with Base64 multiple times that contains an SQL Injection.

In the Tunnel Parsing Properties, setting how many times AppWall decodes a parameter value to assess the security of the request has been added. In this version, AppWall supports the Cookie header, whether or not a parameter is in JSON format. Security inspection is done with the Database Security filter and the Vulnerabilities Security filter.

WHAT'S NEW IN 32.2.9.0

AppWall Features

1. API Security hosts protection has been updated with two new functionalities:
 - a. **Host Mapping:** During the process of uploading a new OpenAPI file, it is now possible to choose to which AppWall Hosts to attach the OpenAPI file definition. An explicit use case is when DevOps usually assesses the configuration in a staging (pre-production) environment. With Host Mapping, DevOps can upload the future production OpenAPI file definition into a staging host and evaluate the schema enforcement, the Quota management, and the security inspection.

API Security – Host Mapping

You can configure the mapping and the merge policy from the Hosts located in the OpenAPI file description and the Hosts available in AppWall (Hosts Level Configuration).

| AppWall Hosts | OpenAPI Hosts | Merge Policy |
|------------------------|-------------------|--------------|
| <Any Host> | None | Configure |
| myOpenBanking.com | myOpenBanking.com | Configure |
| myAPI-Service.com | None | Configure |
| test-myOpenBanking.com | None | Configure |

Submit Cancel

- b. **OpenAPI file descriptor upgrade** is used after Host Mapping. It defines a Global Merge policy to combine the OpenAPI files into an existing AppWall host API security protection. Usually, for each subsequent release the development team provides an updated OpenAPI file that describes the new API service that must be merged into the AppWall API security module.

The API security lifecycle starts with the upload of the first OpenAPI file (version 1). After a period of time when refinements can occur, the API service is updated with a new release (version 2). AppWall performs the merge process of the new OpenAPI file.

The Global Merge policy offers multiple options to decide if the AppWall configuration should remain (with refinements), if the new OpenAPI file definition should replace the previous configuration, or to merge the definitions. The level of configuration is per base path, endpoints, methods, headers, parameters, and bodies.

Global Policy

You can choose how to apply the new imported OpenAPI file description to the existing AppWall API Security Host configuration.

BasePath definition: OVERWRITE

Endpoint definition:

- New endpoints: ADD
- Deprecated endpoints: DELETE
- Same endpoints: MERGE

Method definition:

- New methods: ADD
- Deprecated methods: DELETE
- Same methods: MERGE


Quota definition: KEEP

Parameter definition (Path, Query, Header):

- New parameters: ADD
- Deprecated parameters: DELETE
- Same parameters: OVERWRITE

Body definition:

- New bodies: ADD
- Deprecated bodies: DELETE
- Same bodies: OVERWRITE

- 
2. API Quota Management offers a rate limit functionality for API Security. When AppWall is installed in a cluster environment, each AppWall node inspects the traffic, and the cluster manager consolidates the number of API transactions processed from each AppWall node included in the cluster configuration. The cluster manager verifies if the quota is reached. Each AppWall node is updated and can block incoming traffic from a specific source IP address that may abuse the usage of the API service.
 3. In this version, additional support has been added to decode Base64 data in headers. Support was added for more use cases in the Referer header and in the Cookie header.
 4. The Destination IP, Destination Port, and Destination Host fields have been added to syslog messages generated by AppWall to external SIEM solutions.

WHAT'S NEW IN 32.2.8.0

None

WHAT'S NEW IN 32.2.7.0

DNS Nameserver (NS) Records Support

For security reasons, some DNS cache servers require authoritative nameservers to answer NS queries for the domains for which it is authoritative.

Alteon now answers such queries for the domains for which it is authoritative if the nameservers were configured for that domain. In addition, if the nameserver hostname is in the same domain as the hostname for which the NS query arrived, and the user specified an IPv4 and/or IPv6 address for the nameservers, the answer will also include A and/or AAAA records for each nameserver in the ADDITIONAL section (glue records).

The following configuration is required for the GSLB/LinkProof participating Alteons:

- **Define Nameserver Group/s** – A list of hostnames that serve as nameservers for the same hostnames. For each nameserver, you can also define IPv4 and IPv6 addresses.
- When configuring a hostname, either via a virtual service or a DNS Rule, attach the relevant nameserver group.

NFR ID: 200327-000083

Secure Password Policy

Starting with this version, the administrator can enforce password strengths criteria for the passwords of local users (both predefined and user-defined).

When password strength is configured, it is applied to passwords of newly created users as well as password changes for existing users.

The password strength criteria are not applied to the default predefined Admin user.

NFR ID: 200227-000015

WHAT'S NEW IN 32.2.6.0

Integrated AppWall – API Security

The usage of APIs in Web applications and services is on the rise, and security concerns and needs are not entirely covered by traditional protections in WAF. AppWall's API security module provides protections that cover security concerns and the need for working with APIs.

API Security can be automatically configured by importing an OpenAPI document to AppWall. AppWall automatically updates the API security module for hosts configured under the Host Level Configuration that match the ones defined in the OpenAPI document. All API endpoints will be added to the endpoint list of the host, allowing API requests to these endpoints automatically. API requests to the allowed endpoints are still scanned by AppWall's security protections for embedded attacks.

Alteon VA – VMware ESXi 7.0 Support

Starting with this version, Alteon VA supports the recently released VMware ESXi version 7.0 on top of the earlier version.

SHA2 and AES-256 Support for SNMPv3

Starting with this version, the following SNMPv3 support was added for stronger security

- **authentication type** – Support for SHA256
- **privacy type** – Support for AES256

NFR ID: prod00268561

TCP SACK Control on Management Port

Enabling the TCP SACK improves the performance on management ports. However, this can expose the device to the following vulnerabilities:

- CVE-2019-11477
- CVE-2019-11478

For additional information about these vulnerabilities, please access the Radware Knowledge Base.

TCP SACK can be enabled/disabled via CLI using the following command (enabled by default):

```
/maint/debug/tcpsack <ena/dis>
```

This requires a reboot

This feature is relevant on following Alteon platforms: 5208, 5224, 6420, 8420.

This feature is also available for versions 31.0.14.0, 32.2.6.0, 32.4.4.0.

WHAT'S NEW IN 32.2.5.0

Synchronization of Cluster Persistent Data (first introduced in version 32.2.4.60)

Synchronization of persistence information between Alteon devices that are members of the same Active-Active clusters (2-tier clusters) ensures persistency between a client and server so that the server provides the client with services even in cases where the Alteon device for a specific client fails. The Alteon cluster member that receives the new connections from the client can continue to forward new connections to the persistent server.

The Cluster Persistent Data Sync option synchronizes client IP address and SSL ID persistency. The data is synchronized between cluster members over unicast UDP communication. New persistent entries are sent to all other cluster members. In addition, aggregated data (32 entries per message) is sent at every user-defined keep-alive interval (default 30 seconds). When a new Alteon is added to the cluster, or a device that went down comes back up, updates are triggered from all the existing members.

Note: Before configuring cluster persistent data synchronization:

- Session Persistency must be set to Client IP address for virtual services
- High Availability must be disabled
- Sync Persistent Sessions must be disabled

To configure cluster persistent data synchronization (Web UI: **Network > High Availability > Cluster Persistent Data Sync**; CLI: `/cfg/slb/sync/cluster`)

1. Enable the Cluster Persistent Data Sync option
2. Add the IP addresses of all the cluster members

NFR ID: 190911-000454 (prod00272010)

WHAT'S NEW IN 32.2.4.0

This section describes the new features and components introduced in this version on top of Alteon version 32.2.3.50.


For more details on all features described here, see the *Alteon Application Guide* and the *Alteon Command Reference* for AlteonOS version 32.2.4.0.

High Availability Enhancements

New tracking options (VIP and server group) were added to Alteon High Availability capability. These options are not available in the legacy VRRP mode.

In this version, these new options are configurable via CLI only:

- **VIP Tracking**



A user can mark the VIPs to track, and when any of these VIPs is unavailable (at least one of its services is unavailable) a failover will occur.

The user has the option to determine the criteria for the VIP to fail over according to its services, meaning to limit the failover only if specific services of that virtual services are not available.

NFR ID: 191006-000023

- **Group Tracking**

A user can select a real servers group to track, and when that group is not available a failover will occur.

A group is considered as not available according to the number of available real servers as configured for the Group status threshold parameters.

Radware recommends using the group tacking option mainly when working with filters, where a virtual service is not relevant, and as result the VIP tracking option cannot be used.

NFR ID: 190911-000428 (prod00269501)

AppShape++ Enhancements

The following AppShape++ capabilities were added:

- The **httponly** flag is added to the **persist cookie insert** and **persist cookie rewrite** commands. This flag informs the browser not to display the cookie through client-side scripts (document.cookie and others).

NFR ID: 190911-000550 (prod00271354)

- The 308 response code option is added to **http::redirect** command. 308 is the Permanent Redirect response code and it indicates that the resource requested has been definitively moved to the URL given by the Location headers.

NFR ID: 190925-000125 (prod00253762)

AppWall Enhancements

Anti-Scraping Thresholds per URI

Anti-Scraping now supports defining thresholds per URI. In Anti-Scraping mode, the Activity Tracking module counts the HTTP transaction rate to the defined application scope (domain/page) per user per second. You can define different thresholds and different blocking time settings for each (up to 30) protected URI.

Forensics Filters

Forensics events can now be filtered by: URI, Parameter Name, and Refinements. Filtering by refinements display either refined events or events not refined.

Note: When upgrading from previous versions, filtering by 'Refined' includes only new events generated after the upgrade. Filtering 'Not Refined' events includes all events from before the upgrade, refined and not. Radware advises to use this filter together with a time range filter.

WHAT'S NEW IN 32.2.3.0

This section describes the new features and components introduced in this version on top of Alteon version 32.2.2.0.

For more details on all features described here, see the *Alteon Application Guide* and the *Alteon Command Reference* for AlteonOS version 32.2.3.0.

Smart Session Table Adjustment

Based on research Radware performed, more than 99% of the Alteon platforms in the field use less than 10% of their session table capacity.

Alteon allocates static memory for the entire session table in advance even if Alteon uses only a few thousand entries.

In order to increase Alteon free memory, the session table has been reduced to 50% of its capacity.

The session table will not be changed automatically in the following cases:

- The user changes the default value (100%) of the session table.
- The session table peak is above 35% since the last reboot.

| Platform | RAM Size | 100% Session Table | 50% Session Table | Free Memory Saving (free memory improvement) * |
|----------|----------|--------------------|-------------------|--|
| 4208 | 8GB | 6M | 3M | 706 MB (+53%) |
| 5208 | 16GB | 12M | 6M | 1,358 MB (+34%) |
| 5424 | 32GB | 22M | 11M | 2,482 MB (+24%) |
| 5820 | 32GB | 22M | 11M | 2,482 MB (+24%) |
| 6024 | 32GB | 20M | 10M | 2,260 MB (+19%) |
| 6420 | 32GB | 46M | 23M | 4,894 MB (+210%) |
| 7612 | 96GB | 46M | 23M | 4,603 MB (+11%) |
| 7220 | 96GB | 46M | 23M | 4,603 MB (+11%) |
| 8420 | 128GB | 76M | 38M | 8,596 MB (+16%) |
| 9800 | 192GB | 140M | 70M | 7,901 MB (+8%) |



*Based on the platform's default RAM size

The session table size can also be changed manually with the following CLI command:

```
/c/slb/adv/sesscap
```

```
Enter capacity (400 , 200 , 100 , 75 , 50 , 25 , 12) of entries  
sessions table: <Session table capacity>
```

New SLB Metric – Highest Random Weights (HRW)

The Highest Random Weights (HRW) Hash Load Balancing Metric can ensure client IP address persistency in an Active-Active cluster scenario.

Usually Layer 3 session stickiness to a real server is preserved on Alteon via the session table and the persistency entries (p-entries). To ensure that Layer 3 stickiness is preserved when the active Alteon fails, the preserved session table and persistency entries must be by synchronized (mirrored) between the cluster peers. In an Active-Active cluster such synchronization is not practical, and a different mechanism is required to preserve Layer 3 connections and Layer 3 session stickiness to a real server for a scenario where an Alteon instance fails.

The HRW method performs hash on the client IP plus server IP. Thus, when a new connection arrives, hash is performed for the combination of client IP address with each of the servers. The server that results in the highest hash value is selected.

When a real server becomes unavailable or is removed, all session entries mapped to it are removed and load balancing is performed again for those sessions. HRW then selects the new highest result for each client and all sessions of each specific client are mapped to a new server. This is consistent across all cluster members.

Note: If a new server is defined and shortly afterwards failover occurs, sessions that started before the addition of the new server might be redirected to the wrong server (if the new server yields a higher hash value).

NFR ID: prod00272235

WHAT'S NEW IN 32.2.2.0

This section describes the new features and components introduced in this version on top of Alteon version 32.2.1.0.

For more details on all features described here, see the *Alteon Application Guide* and the *Alteon Command Reference* for AlteonOS version 32.2.2.0.

Documentation in HTML Format

Starting with this version, the documentation set is available from the Radware Customer Portal in both PDF and HTML format. You can access the new HTML documentation either from the Documentation Download page for a given version, or you can perform a search for text from the Customer Portal search feature.



Management Login with SSH Key

In addition to the basic user/password authentication, Alteon also supports SSH public key authentication. Public key authentication improves security considerably as it frees users from remembering complicated passwords (or worse, writing them down). It also provides cryptographic strength that even extremely long passwords cannot offer.

SSH public key authentication offers usability benefits as it allows users to implement single sign-on across the SSH servers they connect to. Public key authentication also allows for an automated, password-less login that is a key enabler for the countless secure automation processes.

Note: SSH public key authentication support is available only for local users.

OpenSSL Upgrade

The OpenSSL version is updated in this release as follows:

- S/SL platform models, regular platform models, and Alteon VA now use OpenSSL 1.1.1b
- XL/Extreme platform models, as well as 6024 FIPS II, use OpenSSL 1.0.2r

OCSP Multiple Servers

OCSP multiple servers increase availability by letting you configure a secondary (backup) static OCSP server and by supporting a retry mechanism that prevents OCSP communication failure because of a temporary issue (number of retries is configurable).

WHAT'S NEW IN 32.2.1.0

This section describes the new features and components introduced in this version on top of Alteon version 32.2.0.0.

For more details on all features described here, see the *Alteon Application Guide* and the *Alteon Command Reference* for AlteonOS version 32.2.1.0.


Virtual Service Traffic Events

Traffic events are now also available for virtual services. These traffic events provide a detailed connection and transaction-based view of the traffic processed by virtual services. The traffic events enable you to quickly identify problems and discover their root cause.

The events are in CEF format and can be integrated with third-party SIEM products.

The following type of traffic events can be sent:

- SSL connection events
- SSL handshake failure events
- HTTP transaction events (request and response)
- Layer 4 connection events



The traffic events are sent to a specified group of syslog servers over the UDP/TCP/TLS protocol (via data ports).

Note: Traffic event logging is available with the Perform subscription and Secure subscription.

To perform traffic event logging per virtual service, do the following:


1. Enable the Traffic Event Log globally from **Application Delivery > Application Services > Traffic Event Policy**.
2. Define Traffic Event policies from **Application Delivery > Application Services > Traffic Event Policy/+** that specify the events you want to see, and attach a remote logging object that defines the group of syslog servers and protocol to which these events should be sent.
3. Attach the Traffic Event policy to the virtual services that require logging.

ADC Analytics: System and Network Dashboard and Reports

Starting with this version, the Alteon *System and Network* dashboard and *Reporting* are available using APSolute Vision 4.20 or later. These screens are a centralized set of dashboards that graphically display the health and performance of your system, enabling you to proactively plan capacity, and to troubleshoot and detect anomalies. The Reporting capability lets you define, generate, schedule, and send reports, either manually or automatically in PDF, HTML, or CSV format. The dashboards and reports provide real-time as well as historical data (up to three months).


System and Network Dashboard Main Screen

The System and Network Dashboard main screen displays a summary of all the Alteon devices (32.2.1.0 and later) managed by APSolute Vision. From here you can identify at a glance the top devices by throughput or CPU in addition to other key information per device.




System Dashboard Screen

Clicking on an individual device opens a more detailed view of the system, such as MP/SP CPU, throughput utilization, SSL CPS, and its groups and servers, helping you troubleshoot any health and performance issues, and more.



Network Dashboard Screen

Clicking on the *Network* tab displays a screen with the device ports' statuses and TX and RX statistics:



SSL Enhancements

OCSP Enhancements

This version introduces the following OCSP enhancements:

- Increased availability by letting you configure a secondary (backup) static OCSP server and by supporting a retry mechanism that prevents OCSP communication failure because of a temporary issue (number of retries is configurable).

NFR ID: prod00253069

- Support for the HTTP GET method – Previously only the POST method was available.

Support Subject Alternative Name Field

Alteon now supports generating a CSR or certificate with Subject Alternative Names. Multiple domain names can be configured using the following format:

DNS:domain1.com, DNS:www.domain2.com, ...

NFR ID: prod00267481

Display Certificate Serial Number in Certificate Repository

The certificate serial number is now extracted and displayed in the certificate repository. This is displayed in both CLI (`/cfg/slb/ssl/certs/cert <n>/cur`) and WBM (**Configuration > Application Delivery > SSL > Certificate Repository**).

NFR ID: prod00261471

ICAP Enhancements

This version introduces the following enhancements to ICAP support:

- Ability to send only certain HTTP requests/responses to ICAP server inspection, using AppShape++ script.

The ADAPT::disable command was added for this purpose:

- **ADAPT::disable** – Disables ICAP processing for the current HTTP request if called in an HTTP_REQUEST or current response if called in an HTTP_RESPONSE.
 - **ADAPT::disable request** – Disables ICAP processing for the current request. The request will be forwarded according to filter action without being scanned by the ICAP service. This command can be called in HTTP_REQUEST events.
 - **ADAPT::disable response** – Disables ICAP processing for the current response when called in HTTP_RESPONSE events, or for the response to a current request when called in an HTTP_REQUEST. The response will be forwarded according to filter action without being scanned by the ICAP service.
- Ability to provide the ICAP servers with the original client IP address.
- Alteon lets you include an ICAP header that carries the client IP address. A user can specify whether the client IP address should be taken from the HTTP/S original packet source IP address or from the X-Forwarded-For header. The default ICAP header name used for this is X-Client-IP, but it can change.



AppWall Enhancements

Alteon 32.2.1.0 includes integrated AppWall module version 7.6.4 that introduces the following enhancements.

HTTP Strict Transport Security Support

HTTP Strict Transport Security (HSTS) is a web security policy mechanism that helps protect websites against protocol downgrade attacks and click hijacking. It allows web servers to declare that web browsers (or other complying user agents) should interact with it using only secure HTTPS connections, and never via the insecure HTTP protocol.

Clickjacking is when an attacker uses multiple transparent or opaque layers to trick a user into clicking on a button or link on another page when they were intending to click on the top-level page, and routing them to another page, most likely owned by another application or domain.

AppWall's HSTS feature allows adding HTTP response headers to different hosts to improve security in places where the application is lacking the required measures.

For more information, see https://www.owasp.org/index.php/List_of_useful_HTTP_headers

Two options of predefined headers are available: **Strict-Transport-Security** protects against protocol downgrade attacks and **Content-Security-Policy** protects against clickjacking.

In addition to the predefined header values, the user can also add different headers in the response if desired.

Cookie Security Enhancement

A cookie returned from a web server can have attributes and flags, for example, “secure” and “httponly” flags, that control the way the browser sends the cookie back to the server on the next requests. The “secure” flag tells the browser to send the cookie only on a secure connection (i.e. https), and the “httponly” flag tells the browser not to enable the page to read this cookie in commands like *document.cookie*.

For security reasons, for some relevant cookies, it should be considered modifying the returned cookie from the server to contain the “secure” or “httponly” flags even if the server did not set them.

The *Reply Cookie Flags* option allows the user to update the returned cookie to contain a **Secure** or **HTTP Only** flag.

Security Page Enhancement

The status code and status message of the security page returned can now be defined. The configuration file *WebApp.cfg* contains information for the status code and the status message returned by AppWall for an internal security page.

The default value for the status code is 200 and the default for the status message is *OK*. Valid values: 200-599.



New Web UI

The integrated AppWall module configuration and monitoring is now fully supported via new React-based Web UI and totally replaces the previous AppWall Management Application based on Java.

The new interface is launched via the [Edit Security Policy](#) link in the **Security > Web Security > Secured Web Applications** pane and via the [New AppWall Configuration](#) link in the **Security > Web Security** pane.

Logging Enhancements

Logs per Health Check

Whenever a server goes down because of a health check failure, Alteon sends a notification (syslog message or SNMP trap). However, when a logical expression health check is used and one of the individual health checks fails without causing a logical expression health check failure, there is no notification (the status of each individual health check can be viewed using the **info** command).

Starting with this version, if an individual health check that is part of a logical expression health check fails, a notification is sent for it.

NFR ID: prod00252738

Alteon Session Logs via Management Port

Alteon can now write the session log messages to a predefined file path on the disk, and these logs can be exported using the CLI or WBM on both data and management ports.

To use this feature, enable it in CLI (`cfg/sys/syslog/sesslog/mode disk`) or in WBM (**Configuration > System > Logging and Alerts > Session Log**).

Limitation: Export using SCP fails when the file size is around 300/400 MB (DE47803, DE47808)

Workaround: Use FTP when the file size more than 300 MB.

NFR ID: prod00266536

Keys Import on Alteon 6024 FIPS

On FIPS-certified devices, keys should be created directly on the FIPS device to be protected against discovery. Such keys can be synchronized with a similar FIPS device via a special trust process.

In a scenario where a service moves from regular SSL security to a FIPS-enhanced security, Radware recommends generating a new key for the service on the FIPS device and acquire a new certificate for this key. However, if the original key and certificate must be used, Alteon now lets you import a clear-text key and certificate.

NFR ID: prod00267640

WHAT'S NEW IN 32.2.0.0

This section describes the new features and components introduced in this version on top of Alteon version 32.1.1.0.

For more details on all features described here, see the *Alteon Application Guide* and the *Alteon Command Reference* for AlteonOS version 32.2.0.0.

Application Dashboard and Reporting

The Application Dashboard and Reporting screens are available starting with this version, using APSolute Vision 4.10 and later.

These screens are a centralized set of dashboards that graphically display the health and performance of your applications.


The Application Dashboard provides insights into the application health and performance data, letting you to proactively plan capacity, and to troubleshoot and detect anomalies.

The Reporting capability lets you define, generate, schedule, and send reports, either manually or automatically in PDF, HTML, or CSV format.

The Application Dashboard and Reports provide real-time as well as historical data (up to three months).


Application Dashboard Main Screen

The Application Dashboard main screen displays a summary of all the applications on your managed Alteon devices, from where you can identify at a glance unhealthy applications, the top applications by throughput/requests per second, and some other key information per application.



Per Application – Analytics

Clicking on an individual application opens a more detailed view on the application and its groups and servers, helping you troubleshoot any health and performance issues.



Per Application – SSL

Clicking on the **SSL** tab opens the client-side SSL information of the application:



Note: The Application Dashboard information is based on counter-based information retrieved from Alteon once a minute in a JSON format. This JSON can be also used for integration with external SIEMs (such as Splunk and ELK).

The URL for the JSON request is: **Error! Hyperlink reference not valid.**

[IP>/reporter/virtualServer](#)


Refer to the *Reporting* section in the *WBM Alteon Application Guide* for detailed information on the JSON structure and data.

Alteon Cluster on Azure

This version introduces Alteon VA application clusters on Azure.

Using the solution template that is available in the Azure marketplace, you can configure a cluster of Alteon VAs that process your application's traffic. As the traffic load increases, additional Alteon VAs members are added to the cluster, and when the load goes down, unnecessary members are removed. The cluster has an IP address through which you can change the configuration of the Alteon VAs cluster members, while a serverless Azure function running in the background synchronizes the configuration changes among the cluster members.

The Alteon VA cluster on Azure is deployed with advanced analytics capabilities, providing an easy view to monitor an application's status and detect anomalies. The following are examples of the Application Analytics dashboard and SSL performance activity dashboard:



Real Servers Auto Scaling support on AWS

Alteon VA on AWS now supports real servers running as part of an AWS Auto Scaling group. Using this capability, Alteon VA automatically adds or removes real servers from the real servers group as the AWS Auto Scaling capability adds or removes application servers. This solution is comprised of an Alteon Auto Scaling AWS lambda function together with the Alteon FQDN capabilities.

For further details, refer to the *Alteon VA on AWS Getting Started Guide*.

Real Servers Auto Scaling Support on VMware

Alteon VA, through vDirect now supports real servers auto scaling controlled by VRO.

vDirect adds or removes real servers in real servers group of the Alteon devices automatically as servers are added or removed by the VRO. This is supported starting vDirect version 4.70

For further details, refer to the *vDirect user guide*.

New Alteon Platform Series (9800)

The Alteon Application Switch 9k series includes high-end performance application delivery appliances, providing superior SSL performance with support for the latest encryption standards (ECC). High-performance coupled with a wide range of connectivity options, high performing and reliable storage (SSD), advanced capabilities, and OnDemand scalability make this series suitable for carriers, mobile operators, and large enterprises.

Alteon D-9800 Highlights

- On-demand throughput scalability: 240 Gbps and 320 Gbps
- Platform flavors:
 - 9800 – Up to 35K RSA SSL CPS/35K EC SSL CPS and 30 Gbps bulk encryption
 - 9800S – Up to 100K RSA SSL CPS/50K EC SSL CPS and 50 Gbps bulk encryption
 - 9800SL – Up to 195K RSA SSL CPS/115K EC SSL CPS and 75 Gbps bulk encryption
- Port density:
 - Eight (8) 100 GbE QSFP28
 - One (1) management port – 1Gbe copper
 - One (1) console RS232 DB9
- RAM: 192 GB
- Storage: 480 GB SSD
- Dual AC power supply (DC PS is available)
- Capabilities: Deliver and Perform capability packages

Notes:

- Upgrade between the different 9800 models, including between S and SL models, cannot be done in the field (requires factory installation)

- This release does not include Secure package (which is scheduled to be supported in the next release)
- The ADC-VX form factor is not yet supported
- Jumbo frames are currently not supported on Alteon 9800 platforms.

Alteon 6024 NEBS Certification

Alteon 6024 SL with 80 Gbps throughput is now also available with a NEBS version. Separate P/Ns are available for the NEBS product.

SSL

TLS 1.2 Session Tickets Support

TLS pre-version 1.3 offers two session resumption mechanisms:

- Session ID – The server keeps track of recent negotiated sessions using unique session IDs.
- Session Ticket – The session key and associated information, encrypted by a key (STEK), which is only known by the server, are stored by the client. This removes load from servers.

TLS 1.3 only offers the Session Ticket resumption mechanism.

Alteon now also supports the Session Ticket resumption mechanism for TLS 1.2, 1.1, and 1.0.

If TLS 1.2 Session Ticket support is enabled on Alteon, but the remote side does not support Session Tickets, Alteon reverts to the session ID reuse mechanism.

Using the Session Ticket mechanism for TLS versions 1.2, 1.1, 1.0 can be controlled at the device level and per SSL policy. Note that reuse is controlled separately for the front-end and back-end.

- If the SSL Policy Session Reuse parameter is set to **Inherit**, all reuse parameters are taken from the global settings, and the SSL policy level TLS 1.2 Session Ticket parameter is ignored.
- If the SSL Policy Session Reuse parameter is set to **Disable**, the SSL policy level TLS 1.2 Session Ticket parameter is ignored.
- If the SSL Policy Session Reuse parameter is set to **Enable**, the SSL policy level TLS 1.2 Session Ticket parameter controls the behavior.

Notes:

- This is supported only on S/SL and regular platform models, and Alteon VA.
- Even though it is named TLS 1.2 Session Ticket, when enabled it also allows use of Session Tickets for TLS 1.1 or 1.0 handshakes.

Session Ticket Key Mirroring

Mirroring the key (STEK) used by Alteon to encrypt the Session Tickets on the standby Alteon device allows for fast TLS session resumption after failover.

The STEK is securely synchronized using a passphrase configured on both devices.

To enable STEK mirroring and configure passphrase:

- Web UI: *Network/High Availability* page, *Stateful Failover* tab
- CLI: `cfg/slb/sync/tcktkkey` menu

Note: STEK sync is supported only in switch-level failover HA modes (Switch HA, Legacy VRRP Active-Standby and Hot Standby)

OCSP Stapling

Alteon now supports OCSP Stapling on both the front-end and back-end:

- On the front-end SSL connection, Alteon performs as an SSL server and can staple its certificate before forwarding it to the client, if the client requested staple in the Client SSL Hello.
- On the back-end SSL connection, Alteon performs as an SSL client and can request (if enabled) a stapled certificate from the server.

OCSP Stapling activation is performed via the Authentication Policy:

- An Authentication Policy must be created for either the client or server side depending on where you want to employ OCSP Stapling
- OCSP must be enabled as the Certificate Validation method
- A new parameter, OCSP Mode, is available and determines whether to enable OCSP Stapling or not. Its values have a different effect for Client and Server Authentication Policies:

| OCSP Mode | Client Authentication Policy | Server Authentication Policy |
|---------------|--|--|
| OCSP Server | Alteon communicates with the OCSP server to validate client certificate. | Alteon communicates with the OCSP servers to retrieve the revocation status for the certificate it received from the server. |
| OCSP Stapling | Alteon sends to the client the server certificate accompanied by the OCSP staple retrieved from the OCSP server, attesting the certificate is not revoked. | Alteon requires the OCSP status from the back-end server (OCSP staple). |

| OCSP Mode | Client Authentication Policy | Server Authentication Policy |
|-----------|--|---|
| Both | Alteon validates the client certificate and staples the server certificate it sends to the client. | Alteon requires the OCSP status from the server (OCSP staple). If the OCSP staple is not received, or the received response is not valid, Alteon communicates with the OCSP servers to retrieve the revocation status for the certificate it received from the server |

- Configure the relevant OCSP parameters.
- The Authentication Policy must be attached to relevant SSL policy.

AppWall

New Fingerprint-based Tracking Mechanism

The Activity Tracking module can be set to one of two tracking modes:

- IP-based tracking (available both in Passive and Active modes) is not intrusive.
- Device Fingerprint-based tracking (available only in Active mode) is intrusive.

Device fingerprint technology employs various tools and methodologies to gather IP-agnostic information about the source, including running JavaScript on the client side. Once the JavaScript is processed, an AJAX request is generated from the client side to AppWall with the fingerprint information.

Previously, when an HTTP request is received from a new source, the browser received from AppWall a 302 Redirect response to a fingerprint page. Once the browser received that page, it executed the embedded JavaScripts that generated a fingerprint that was sent back to AppWall as an AJAX call. Only then, AppWall redirected the browser to the originally requested resource in the secured Web application.

As of this version, AppWall embeds the Fingerprint JavaScript into the original server response, avoiding the dual redirect process. The JavaScript process is then executed as the last step of the page rendering process in the browser. Thus, there is no end-user visibility into the redirect process, the fingerprint page is not shown, and there is no latency experienced by the user.



WebSocket Support

WebSockets is a protocol that allows the transfer of different types of data, such as XML, JSON, other types of text, and binary data. As of this version, AppWall detects the WebSocket switching protocol process and bypasses the connection to avoid a scenario of blocking a WebSocket because of lack of conformity with the HTTP RFC. This setting can be configured in the Tunnel HTTP properties section. By default, bypassing WebSockets is disabled.

New Web UI Interface

As of this version, the common operational use cases of AppWall management are offered also as pure Web interface instead of the Java applet. The new interface is launched via the **Edit Security Policy** link in the **Security > Web Security > Secured Web Applications** pane and via the **New AppWall Configuration** link in the **Security > Web Security** pane.

The Web UI runs on a modern technology with a React client side and with a back-end REST API layer based on the Node.JS server. The REST API calls generated from the client-side application are authenticated using JWT (JSON Web Token), properly securing access to the server side.

The highlights of the supported functionality in the new Web UI include:

Configuration:

- Add/Edit/Delete a protected Web server
- Add/Edit/Delete HTTP and HTTPS tunnels
 - TCP properties
 - Parsing properties
 - Message size
 - Active/Passive mode
- Add/Edit/Delete a Web application
- Add/Edit/Delete an application path
- Vision server configuration
- Certificate management
- License management
- IP groups management
- Activity Tracking
- Source Blocking Management
- Cluster Manager settings and adding nodes
- Backup/restore configuration

Security Policies:

- Host based policy:
 - CSRF
 - Activity Tracking
- Security Filters Policy:
 - Global Security Filter settings
 - Enable/disable security filters in application path
 - Manage security filters refinements
- Role based policy

Forensics

- Publishing rules
- Security, Initialization, admin and system logs with filtering options

Dashboard

- Dashboard summary view: resource utilization, traffic volume
- Reporting widgets: Events by Filters, Events by Apps
- Dashboard view of tunnels with stats

New AS++ Command – whereis

The new whereis AS++ command lets you retrieve the geographical location of a specific IP address.

The command supports both IPv4 and IPv6 addresses.

Syntax: `whereis <IP> [continent | country_code | state | city | zip | latitude | longitude]`

When no flag is provided, the command returns all the parameters (continent, country code, state, zip, latitude and longitude) in a TCL list.

Notes:

- For DPS devices, a Perform or Secure subscription is required.
- If there is no valid license or the location of the IP address is unknown, the command returns empty list/parameter.
- If the invalid IP address is invalid, the traffic is failed.

Hardware Health Monitor

The hardware health monitoring module scans the system for hardware elements and collects historical statistics on them. These data are then exported as part of the techdata.

By default, hardware health monitoring is enabled and can be disabled using the following CLI command: `/c/sys/hwhealth`

WHAT'S CHANGED IN 32.2.14.0

AppWall Integrated

- **Signature Operation Mode:**
A new Operation mode, **Forced Active**, is now available. If the Database Security filter or the Vulnerabilities Security filter are in Passive mode, the RuleID or PatternID configured as **Forced Active** will block the traffic.
From the AppWall Management Console, in the Database Security filter, the configuration has been consolidated. Two tabs exist today:
 - **Rule Operations** allows the configuration of the Auto Passive Mode, the definition of the Operation Mode for any RuleID, and an aggregated view of the Database Security filter of each Application Path where the Database filter is defined.
 - **Parameter Refinements** allows to exclude RuleIDs per parameters/headers.
- **FileUpload Security filter:**
 - Support of files with no extension.
 - Advanced support of files upload with content the Content-Type multipart/form-data.

WHAT'S CHANGED IN 32.2.13.0

HTTP/HTTPS Health Check

Starting with this version, an IPv4 HTTP/HTTPS health check can be set to terminate the connection using FIN in case of timeout (the default remains RST).

Configuration of this feature is available only via CLI using the `conntout <fin | rst>` command.

Note: Radware recommends closing the connection with RST in case of timeout, for faster response release. Closing with FIN may cause high MP CPU utilization if many real servers are unreachable.

NFR ID: 211020-000175

QAT Driver/Engine Upgrade


The Intel QAT driver used in Alteon S and SL models has been updated to QAT.L.4.17.0-00002.

OpenSSL Upgrade

The OpenSSL version was updated, for both the data and management path, to version 1.1.1n.

AppWall Integrated

1. **Database Filter:** In the inspection settings, we can configure the filter to do a partial inspection of the parameters (for example, inspect only the first 150 characters).

- 
2. **Content-type HTTP Header** multipart/form-data can be refined if it does not follow RFC (specific implementation with a different delimiter than in the RFC).
 3. **URL-encoded encoding:** More support and refinement options were added in the Parsing properties. Per URI, it can be specified which reserved characters are **unencoded**.
 4. **Cookie Reply flag:** We can now enforce the cookie flag SameSite (Strict, LAX or None) on behalf of the origin server.

WHAT'S CHANGED IN 32.2.12.0

AppWall Integrated

- **SafeReply Filter:** The settings of the SafeReply filter have been moved. Previously, the settings were global when the SafeReply filter was activated. In this version, the settings can be specifically set per Application Path.
- **API Security:** When merging a new OpenAPI schema in an existing configuration, the merge policy can be defined. In this version, during the merge process, the value for the Quota is set, by default, to "Keep".
- **Tunnel Parsing Properties:** In the "Request Boundaries" section, AppWall can accept HTTP GET requests with a Body to mitigate attacks, such as HTTP Request Smuggling attacks. In this version, the "Support Framing for Request Message" option has been removed (doing a TCP reset) rather than presenting a Security Page by the "Allow a GET request with body" option.
- **Auto-Discovery and Auto-Policy:** These two features, Auto-Discovery and Auto-Policy, have been coupled. When activating Auto-Policy in an Application Path, Auto-Discovery is automatically activated. When Auto-Policy in the last Application Path is deactivated, Auto-Discovery will also be automatically deactivated. It is still possible, though, to Activate Auto-Discovery alone. This will require manual deactivation.
- **Forensics Security Events:**
 - It is now possible to filter security events per key words found in the security event Description field.
 - It is now possible to filter WebSocket Security Events.

WHAT'S CHANGED IN 32.2.11.0

None

WHAT'S CHANGED IN 32.2.10.0

OpenSSL Version

The OpenSSL version has been updated to OpenSSL 1.1.1l.



AppWall Enhancements

1. AppWall management API Security hosts protection has been updated. You can now:
 - a. Edit the Path parameter name
 - b. Add/delete a new Endpoint definition
 - c. Add/delete a new Method
 - d. Other UI improvements
2. Database Security Filter performance has been improved in term of time to inspect the request data

A new section was added to the Tunnel Parsing Properties to refine the HTTP boundaries per URI. You can now configure AppWall to accept HTTP requests with a Body or refine such HTTP requests (HTTP Request Smuggling attacks) from the security events. If so, AppWall will accept the request and transfer the body payload to the server.

WHAT'S CHANGED IN 32.2.9.0

AppWall Features

1. In the Tunnel configuration, AppWall now defines multiple properties related to the HTTP parser per URI. The following changes have been added in this version:
 - a. By default, when adding a new URI, the following parameters are validated:
 - i. Allow Parameter without an equal sign
 - i. Fast Upload for large HTTP requests
 - ii. Fast Upload for large HTTP requests with files
 - b. The option "Use IIS Extended Unicode Measures (Block Unicode Payloads)" has been removed from the AppWall management console but is still available from the configuration file.
2. The BruteForce Security Filter prevents remote users from attempting to guess the username and password of an authorized user. The option "Shared IP auto-Detection" check box has been removed from the AppWall management console to limit false positives.
3. Remote File Inclusion (RFI) and Local File Inclusion (LFI) are file inclusion vulnerabilities that allow an attacker to include a file or expose sensitive internal content, usually exploiting a "dynamic file inclusion" mechanism implemented in the application. In the Hosts protection section, by default, Redirect Validation is in passive mode with the option "Protect against external URL" activated.
4. The Tunnel IP (VIP), the Port and the Host have been added to the system log event titled "Large number of parameters in request".

WHAT'S CHANGED IN 32.2.8.0

DNS Resolver Enhancements

Response for Unsupported Record Types (first introduced in version 32.6.3.50)

Previously, Alteon used to answer queries for unsupported record type of domains supported by the Alteon DNS resolver (for GSLB and LinkProof) with "Domain does not exist" (NXDOMAIN). This was now changed to the standard behavior required for such a scenario – answering with a No Error response code and 0 records.

NFR ID: 200723-000119

OpenSSL Version

The OpenSSL version for S/SL platform models, regular platform models, and Alteon VA has been updated to OpenSSL 1.1.1i.

Note: The CVE-2021-3449 vulnerability that was discovered for OpenSSL 1.1.1 is fixed in this version for the data path. For the management path, Radware currently recommends disabling TLS 1.2.

Treck Version

The Treck version has been updated to 6.0.1.69.

WHAT'S CHANGED IN 32.2.7.0

Increased Tunnels and Static Tunnel Routes Configuration Capacity

Starting with this version, you can support 8k Layer 3 tunnels and static tunnel routes if memory allows. To increase the number of tunnels and static tunnel routes to 8k, use the CLI command `/c/slb/adv/memmng/tnltbl`. This change requires **Apply**, **Save**, and **Reboot** to become active.

NFR ID: 200322-000001

User Role can be Restricted from Viewing the Syslog Logs

By default, a user with the **User** role can view the syslog logs via the CLI or WBM.

Starting from this version, the Administrator can specify the **User** role to view or not view the syslog logs.

CLI: `/cfg/sys/access/user/usrlog`

WBM: **System > Users > Local Users**

Note: This support is applicable to local users only (both predefined and user-defined). It is not applicable to remote users.

NFR ID: 200814-000008



Enlarge Login Banner Size

The CLI banner length has been increased from 319 characters to 1300 characters (which can be set using the `/cfg/sys/bannr` command).

NFR ID: 200921-000035

WHAT'S CHANGED IN 32.2.6.0

OpenSSL Upgrade

The OpenSSL version for S/SL platform models, regular platform models, and Alteon VA has been updated to OpenSSL 1.1.1g.

Real Server Tracking Logic Changes in WBM

An option to automatically add all the real servers (including those that will be added in the future) was added to the WBM.

NFR ID: 190911-000343

Treck Version Upgrade to 6.0.1.66

In this version, Treck was upgraded from version 6.0.1.44 to 6.0.1.66, which resolves the following CVEs (including Ripple20, and others):

- CVE-2020-11896
- CVE-2020-11897
- CVE-2020-11898
- CVE-2020-11899
- CVE-2020-11900
- CVE-2020-11901
- CVE-2020-11902
- CVE-2020-11903
- CVE-2020-11904
- CVE-2020-11905
- CVE-2020-11906
- CVE-2020-11907
- CVE-2020-11908
- CVE-2020-11909
- CVE-2020-11910
- CVE-2020-11911
- CVE-2020-11912

- CVE-2020-11913
- CVE-2020-11914

WHAT'S CHANGED IN 32.2.5.50

TLS Version Default

Starting with this version, TLS 1.1 is disabled by default.

Note: The default TLS 1.1 setting is not set to disabled if was enabled prior to this version.

WHAT'S CHANGED IN 32.2.5.0

Syslog Enhancements

Increase of the Number of Syslog Servers to Six

Prior to this version, five syslog servers were supported. Starting with this version, six syslog servers are supported.

NFR ID: 190911-000460

OpenSSL Version

The OpenSSL version for S/SL platform models, regular platform models, and Alteon VA has been updated to OpenSSL 1.1.1f.

TLS Allowed Versions Default

Prior to this version, by default TLS versions 1.1, 1.2, and (where relevant) 1.3 were enabled in newly configured SSL policies. TLS 1.1. is now considered insufficiently secure and allowing it caps the SSL grade provided by Qualys to B. Starting with this version, newly configured SSL policies will have TLS 1.1 disabled by default. Existing SSL policies will preserve the configuration before upgrade. Radware recommends to manually disable TLS 1.1 to achieve a higher SSL grade.

Security Hardening

- Upon authentication failure, the error message does not reflect the reason for the failure.
- All password inputs are masked.
- The log command is available to all user roles using the CLI (to align with the behavior using WBM).
- For upgrades from versions 32.6.1.50 and later, 32.4.3.50 and later, 32.2.5.50 and later, and 31.0.13.50 and later, to any later version, Alteon uses the SHA2 algorithm for the digital signature (in all platforms).

NFR ID: 191126-000098

Client NAT Port Assignment Logic

Starting with this version, it is possible to select the client NAT port assignment algorithm on Alteon running on the vADC form factor. The options are:

- Sequential – Minimizes the probability of fast port reuse, but it can be a security vulnerability
- Random – Provides increased security, but the probability of fast port reuse is higher

This can be done using the command `/cfg/slb/adv/pport` (in WBM, **Application Delivery > Virtual Service > Settings > Session Management** tab).

Notes:

- The change in the client NAT port assignment algorithm will only take place after statistics are cleared (`/oper/slb/clear`).
- On Alteon VA and Alteon platforms in standalone mode, the client NAT port assignment uses an enhanced random mode that also minimizes fast port reuse probability.

NFR ID: 200407-000053

WHAT'S CHANGED IN 32.2.4.0

Health Check Source MAC

When working in legacy VRRP high availability mode, you can now set health check traffic to servers to use the VR MAC for the server's VR owner instead of the interface MAC.

NFR ID: 190911-0 (prod00270223)

Banner Length

The CLI banner length has been increased from 80 characters to the standard banner length of 319 characters (`/cfg/sys/bannr`).

Note: The data type of `agCurCfgLoginBanner` and `agNewCfgLoginBanner` was changed from `DisplayString (SIZE(0..79))` to `OCTECT STRING (SIZE(0..318))`.

NFR ID: 190912-000126

Alteon VA – Number of Supported NICs (Hyper-V, OpenXEN)

The number of vNICs Alteon VA runs on Hyper-V or OpenXEN was increased from three (3) to eight (8) vNICs (one [1] for management and seven [7] for data).

Integrated AppWall

The following are changes and modifications made to the AppWall module:

- Integrated AppWall module can now report events to Absolute Vision using IPv6 addresses.
- The Forensic events filter by time range now supports hour and minute ranges.

- Integrated AppWall can now synchronize Signature Updates and Geolocation data that was manually installed to a backup HA device. To initiate the synchronization, click **Apply** after installing the new updates on the primary device.
- Disabling the publishing of an event also disables sending the event to APSolute Vision.
- AppWall notifies you of configuration file issues and recommends a solution.
- Fixes and improvements to AppWall's configuration **Apply** mechanism.
- Fixes and improvements to the config sync mechanism.

Server Session Shutdown

Real servers can be shut down gracefully by continuing to send to the server traffic belonging to active connections (Connection Shutdown), and in addition can continue allocating to the server new connections if they belong to persistent session entries (Session Shutdown). Previously, Session Shutdown was only available when persistency mode was cookie or SSL ID. Now this is also available for client IP persistency.

NFR ID: 190911-0000346 (prod00 273440)

OpenSSL Version

The OpenSSL version for both management and data path was updated as follows:

- XL/Extreme and FIPS II models: 1.0.2u
- S/SL models, standard models and VA: 1.1.1d

WHAT'S CHANGED IN 32.2.3.0

Alteon User Password Encryption Enhancement

Starting with this version, the user password is encrypted with SHA512 with dynamic Salt.

Important: Due to this support, it is now mandatory to define the configuration sync Authentication Passphrase on both HA peers (using `/cfg/slb/sync/auth`). During upgrade, a default passphrase will be set if there is no passphrase. It is recommended to update that default passphrase after the upgrade.

NFR ID: prod00272191

Audit Log via Telnet and SSH

The audit log now includes the CLI protocol from which the configuration change was performed (either Telnet or SSH).

NFR ID: prod00272163



BGP Support for Four-octet AS Number

The range of the “AS” value for BGP was extended from a 2-byte to a 4-byte value.

NFR ID: prod00268252

Full Layer 3 Tunnel Support (IP-in-IP and GRE) – Phase 2

IP-in-IP and GRE tunnel protocols for the data path is now supported.

NFR IDs: prod00259678, prod00259680

Jumbo Frames

Jumbo frames for the 5208, 6420, 8420, Alteon VA, and DPDK platforms now supported.

NFR ID: prod00268780

Failover Delay

In a high availability environment, a failover delay is now available on the backup in order to eliminate failover flapping when a virtual service failover occurs.

When the failover delay is defined, once the master priority decreases, the backup waits the configured delay time before it becomes the master.

The delay is used whenever the priority is decreased because of real/gateway/interface tracking.

Note: This capability is available for both service and switch mode and is not available for VRRP.

NFR ID: 191006-000024

WHAT’S CHANGED IN 32.2.2.50

Fixed AppWall Performance Degradation

Fixed a severe performance degradation of AppWall integrated with Alteon after upgrading to version 32.2.2.0.

The performance degradation was only related to services that have Secwa attached and impact the traffic that goes through AppWall.

WHAT’S CHANGED IN 32.2.2.0

None

WHAT'S CHANGED IN 32.2.1.0


vDirect-Based Outbound SSLi Wizard (Layer 3 Deployment, Single Standalone Device)

A wizard for quick and easy configuration of an outbound SSL Inspection solution is now available via APSolute Vision (version 4.20 and later). The wizard is implemented using a Radware vDirect workflow.

The wizard supports a Layer 3 environment on a single standalone device.

To access the wizard, access vDirect from APSolute Vision, navigate to the catalog, and filter by **SSL inspection**.

To start with the deployment, click **Create Workflow**.



SSL Inspection Deployment Support in VLAN Tag and Trunk

Fallback VLAN an Fallback Trunk Support

Alteon support for Fallback VLAN and Fallback Trunk enables you to connect the Security Inspection Services (SIS) chain of an SSL inspection deployment via switch and not only directly connect to Alteon.

- Fallback VLAN is defined on the filter redirecting to the next SIS in the chain:
 - If the port defined on the fallback port is a tagged port, Alteon injects the traffic with the VLAN tag defined on the fallback VLAN.
 - if the fallback port is tagged but the fallback VLAN is not defined, the injected traffic is injected with PVID tagging
- Fallback Trunk:

- When the fallback port is part of an LACP trunk, the fallback port should be set to any of the ports participate on the trunk. Alteon load balances the injected traffic between the available ports on the trunk.

Trunk and VLAN Support in IDS-Chain

Alteon sends traffic to the IDS server via the defined IDS port and in parallel it injects the traffic to the IDS port in order to continue in the flow. Starting with this version, if the defined IDS port is part of an LACP trunk and, during injection Alteon load balances between the ports in this trunk. If the IDS port is a tagged port, Alteon tags the traffic sent to the IDS server and also injects the traffic to continue in the flow

Note: If the IDS server is connected via a tagged port (IDS port), but the IDS VLAN is not defined, Alteon tags the injected traffic with PVID tagging.

Virtual Service Manageability Enhancements

The following enhancements were added to simplify virtual service manageability:

- *Virtual Service Status* view:
 - Added the virtual server IP address
 - You can now fully expand a service with one click



- Three new CLI commands were added to display the real servers, groups, and virtual services in tabular format. including a search capability (for more information, see the *Alteon Command Reference* or the online CLI command usage help).

```
/info/slb/realtab
```

```
/info/slb/grptab
```

```
/info/slb/virttab
```

```
>> Standalone ADC - Server Load Balancing Information# /info/slb/realtab
** - Real does not have group/virt configured
```

| Status | Real Server ID Real Server IP Real Server Type | Group ID | Content Rule Content Class | Virtual Server ID Virtual Server IP Virtual Service |
|--------|--|----------|-------------------------------|---|
| DOWN | 1 10.194.245.112 local | 2 | 0 ** | ** |
| DOWN | babu 1.2.2.2 local | babu | 0 ** | ** |
| DOWN | R1 100.3.3.3 local | G1 | 0 ** | Myservice 3.30.30.30 443 (https) |
| DOWN | Real2 6.6.6.6 local | G2 | 0 ** | ** |

NFR ID: prod00263461, prod00263465



Update Session Entry-based on Gratuitous ARP

When a gratuitous ARP is received from upstream routers, Alteon now updates the source MAC address on relevant session entries.

NFR ID: prod00263371

WHAT'S CHANGED IN 32.2.0.0

Alteon VA Enhancements

Footprint Reduction

Alteon VA is now available with a small footprint (2 GB RAM) on Azure or AWS on top of its availability on other hypervisors that were introduced in version 32.1. This makes the usage of Alteon VA on public Clouds more cost effective (for example, you can now utilize the t2.small instance on an AWS instead of m3. medium instances in previous versions).

With 2GB RAM, some of the system capacity tables were reduced as follows:

- Real servers: 1024
- Health checks: 4096
- Content rules: 150
- Filters: 75
- HTTP modification rules: 1000
- Data classes: 100

The Alteon VA with a small footprint is not recommended for advanced Layer 7 processing, such as force proxy, SSL offload, AppShape++ scripts, and so on.

Improved Performance on Azure

Starting with this version, Alteon VA supports SR-IOV on Azure.

With this capability, Alteon VA can utilize up to 15 vCPUs providing improved Layer 7 and SSL performance.

GEL Support Enhancements

GEL License Activation

When activating the GEL license on Alteon instances, there is no longer a need to enter the DPS package. You just need to enter the throughput (in case no subscription add-on is required), and Alteon extracts from the entitlement the relevant DPS package.



DPS Package Upgrade

When upgrading a DPS package license of an entitlement, all of the Alteon devices automatically upgrade their licenses to the new DPS package with no need for manual intervention to change their licenses.

GEL License Presentation on ADC-VX platforms

The licenses of vADCs with GEL licenses are displayed on Alteon ADC-VX platforms with an indication that vADC is running a GEL license.

LLS Availability on Azure

You can now also deploy vDirect with the Local License Server (LLS) on the Microsoft Azure Cloud. This is important if all of your Alteon VAs are running on Azure and need an LLS on the same network.

Password Generator

The password generator also accepts the Entitlement ID to generate the password for upgrades. This enables the support of Alteon VAs running a GEL license that do not have their MAC addresses registered in the install base.

Management IP Address in ADC-VX

Starting with this version, when this platform is configured to operate in ADC-VX mode, the management IP address of the Alteon VX and its vADCs must be on the same network. Otherwise, the apply fails.

Dual Power Supply for Alteon 4208

4208 now supports a dual Power Supply

Note: There is no field upgrade of a single PS to dual PS. Upgrading a single PS to dual PS requires going through the buyback process.

SSL Key Replacement

It is now possible to replace an existing key, using the same ID, via Web UI.

SSL Inspection Wizard Enhancement

A wizard for quick and easy configuration of an inbound SSL Inspection solution is now available via APSolute Vision (version 4.10 and later). The wizard is implemented using a Radware vDirect workflow.

The wizard supports a Layer 3 environment in either a single or 2-box deployment, and can be run on either a standalone, Alteon VA, or vADC.

To access the wizard, do one of the following:

- Select the Alteon device from the APSolute Vision device tree.
 1. Go to Configuration > Application Delivery > SSL > Inbound SSL inspection.
 2. Click the **Inbound SSL Inspection Wizard** link. A vDirect page with the workflow opens in a separate browser page.
 3. Run the Inbound_ SSL_ Inspection_ Wizard workflow.
- From APSolute Vision, open the vDirect page:
 1. Navigate to Operations > Catalog.
 2. Filter by the **SSL inspection** tag (optional).
 3. Run the Inbound_ SSL_ Inspection_ Wizard workflow.

LinkProof MAC Overwrite

LinkProof can now handle scenarios where the WAN Link router is in fact a router cluster, but without a floating MAC address (GARP announcements use the active router MAC address and not the floating MAC address).

To support this scenario, when a new MAC address is received for a WAN Link that differs from the MAC address already in the ARP table for that WAN Link IP address, Alteon overwrites the MAC address in all session entries belonging to this WAN Link. This ensures that traffic is sent to the MAC address of the active router.

NFR ID: prod00262807

Allow Local and Remote Authentication

When Alteon management users are authenticated using remote authentication (RADIUS or TACACS), you can now also allow local users. When this capability is enabled (new User Authentication Priority parameter set to Local First) Alteon will first try to authenticate the user locally and if it fails will use remote authentication.

NFR ID: prod00235979

Health Check Enhancements

Graceful Health Check Edit

When a health check attached to a group or real server is changed (either by attaching a new health check ID or by editing the health check parameters), after **Apply** the status of the health check is preserved. Previously the status of an edited health check immediately after **Apply** failed, causing the server's status to temporarily change to **Down**.

Note: The status of the health check is not preserved after the change in the following cases:

- If the destination port of the health check is changed, either by changing it directly on the health check object or by changing it on the virtual service or real server.
- If the host name is configured as **Inherit** in the HTTP/HTTPS health check and the virtual service hostname is changed.
- If a basic health check is replaced by a logical expression health check, if the old basic health check had a user-defined destination port that was different from service/server port.

NFR ID: prod00252740, prod00261070

Advanced Virtual Wire Health Check

The Advanced virtual wire health check can be used to check the connectivity between the ingress and egress interfaces of a virtual wire device in an SSL inspection deployment.

As opposed to the OOTB virtual wire health check (used by the on-device outbound SSL inspection wizard), the advanced virtual wire health check can also be used in a manual configuration. It does not require static ARP and it runs on the TCP port defined on the filter rport or the health check dport.

AppWall

AppWall in Transparent Mode

The ability to provide WAF capability in transparent mode via filters was introduced in version 32.1.1.0 with several configuration restrictions.

In this version, there is no longer any restriction to the syntax of the Secure Web Application name or the SSL policy ID. However, on filters with an attached SecureWeb Application, it is required to configure the Multi-protocol Filter Set ID:

- If the same Secure Web Application is attached to several filters, all filters must set the filter set ID to the same value.
- If different Secure Web Applications are attached to different filters, a different filter set ID must be set for each filter.

Support for transparent AppWall configuration via WBM has also been added.

Syslog Message Enrichment

The threat category and attack name fields were added to the syslog messages generated by AppWall to external SIEM solutions.

Defense Messaging

Defense Messaging to DefensePro version 8.x was certified to support both a Layer 3 source IP address and Layer 7 XFF based source IP.

Username Format

AppWall now adds support for defining the username format as it is being sent to the user datastore. Now there are three optional formats:

- username@domain
- domain\username
- username

This new function is supported for both RADIUS and LDAP servers.

SSL Statistics and MIBs

MIB and WBM support has been added for SSL front-end and back-end SSL statistics, including the cipher usage statistics. They are available in the following panes:

- **Monitoring > Application Delivery > Virtual Servers > Service [x] > View Service**
- **Monitoring > Application Delivery > Filters > View Filter**

The SSL summary statistics are available through **Monitoring > Application Delivery > SSL**.

MAINTENANCE FIXES

Fixed in 32.2.14.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | The client certificate went through OCSP verification even though it is in OCSP stapling mode. | DE76180 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Request of /v2/config/aw/SecurityEvents/ returned a false response. | DE75916 |
| 2. | The forensics search engine was not accurate. | DE74469 |

| Item | Description | Bug ID |
|------|---|---------|
| 3. | Wildcard hostname (*nma.lt) worked incorrectly and caused false positive. | DE74667 |
| 4. | Session filter removed the cookie in passive mode. | DE74748 |
| 5. | There was no detailed information about a pattern. | DE74850 |
| 6. | Protected applications behind AppWall went down suddenly. | DE75232 |
| 7. | Under certain conditions, no explanation is provided in the Forensics API Security event. | DE75513 |
| 8. | Geo filter (ZZ) to display the Forensics logs for Private networks did not work. | DE75593 |
| 9. | In Forensics, the filter according to the Geo-Location did not work. | DE74346 |

Fixed in 32.2.13.0

General Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | The AppWall nodejs module flapped on virtual platforms in the following cases: 1. When there are more than 10 vADCs 2. When vADCs are configured with the basic flavor. | DE72861 |
| 2. | There was an error with traps for IPv6-related events. | DE73065 |
| 3. | When there was a TCB block leak, DSSP health checks failed. | DE73181 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | Under certain conditions, Source Blocking reports an “Always Blocked” IP source. | DE72050 |
| 2. | The Forensics session and the Dashboard’s Current Activity is not displayed on the AppWall Management Console. | DE73465 |
| 3. | For database refinements which involve XML, a false positive is shown, and the request is still blocked. | DE74094 |

Fixed in 32.2.12.0

General Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | A user was locked out after making a password change. | DE70322 |

| Item | Description | Bug ID |
|------|--|---------|
| 2. | Real server health checks were not started when there was a run-time instance with an improper index in the dispatch queue of slice 4. | DE71443 |
| 3. | When a DPDK image reset, an unexpected DNS server IP address was added by BSP. | DE71758 |
| 4. | After the AppWall health check failed, the MP restarted AppWall every 15 seconds . | DE71822 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | When adding a host under an existing Webapp using API, an Error 400 was shown. | DE70145 |
| 2. | A Corrupted Configuration File Detected error was shown. | DE70260 |
| 3. | HTTP DELETE requests were being blocked by AppWall's FileUpload filter and reported as PUT. | DE70675 |
| 4. | The Brute Force filter was not working on API-based server responses. | DE70797 |
| 5. | A Threshold of incoming sessions event was shown when the total active connections were much lower than the maximum. | DE71105 |
| 6. | Under some conditions, long header Hostnames led to a syslog failure. | DE70821 |
| 7. | The APSolute Vision AppWall dashboard displayed wrong data | DE70207 |

Fixed in 32.2.11.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | In an SLB environment with VLAN level proxy configured, in some instances the MAC flapped after an SLB config apply. | DE69665 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | AppWall blocked requests when Host protections (CSRF/URL Rewrite/Redirect validations) had the "Inherit" status. | DE67920 |
| 2. | Debug log added to link the Source Blocking scoring and the related security event. | DE66587 |

| Item | Description | Bug ID |
|------|---|---------|
| 3. | Wrong IP blocked with Source Blocking. | DE68383 |
| 4. | Wrong host displayed in syslog security event. | DE68396 |
| 5. | Wrong hostname displayed in the Forensics security events when blocked by the Application Security policy. | DE68487 |
| 6. | AppWall displayed an “Initialization error” after the navigation to Security filters. | DE68858 |
| 7. | AppWall API management: HTTP tunnel PUT method changed to contain all the mandatory fields. Creation of the PATCH Method. | DE69722 |

Fixed in 32.2.10.0

General Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Starting with this version, the SNMPv3 target address table is available in the Ansible module. | DE67001 |
| 2. | New SSH and HTTPS connections failed when a faulty SSH inbound session existed (associated with an obsolete file descriptor). | DE66477 |
| 3. | The SSL Hello health check caused a memory leak which led to a panic. | DE66188 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | HRS attack: HTTP GET request with BODY was not being blocked while there was a security event. | DE65623 |
| 2. | Under some conditions, the AppWall management console WAF stopped working and was not accessible. | DE67515 |
| 3. | The AppWall Activity Tracker recognized a legitimate Google search engine as a bad bot. | DE67646 |
| 4. | Wrong hosts reported with AppWall Hosts protection. | DE64012 |
| 5. | AppWall blocked the server response when a tunnel was in passive mode. | DE65600 |

Fixed in 32.2.9.0

General Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | The random salt was a predictable random number generation function generating a similar sequence. | DE63665 |
| 2. | Could not enable the extended_log via Ansible. | DE63838 |
| 3. | The real health check displayed different times in CLI and WBM. | DE64028 |
| 4. | When pbind clientip and vmasport were enabled, the persistent session was not permanently deleted. | DE64351 |
| 5. | Servers were vulnerable to CVE-2021-3449 if they had TLSv1.2 and renegotiation enabled (default). Fix: The MP OpenSSL version has been upgraded to 1.1.1k to fix this. | DE64378 |
| 6. | Predefined HTTP headers were used when POST HTTP health checks were sent without taking into the account the actual body length. | DE64698 |
| 7. | Defect that tracked DE65346 -- Device auto rebooted with reason of hardware watchdog. | DE65346 |
| 8. | After performing config apply, GSLB DNS responses returned a remote IP address instead of a local VIP. | DE65360 |
| 9. | SIP UDP service run by AppShape++ failed (it was used for persistency and/or Layer 7 manipulation). | DE65430 |
| 10. | Even though the SP/MP profiling logic was disabled by default, Alteon panics with SP profiling logic being triggered. | DE65488 |
| 11. | When a vADC Layer 2 configuration was applied/pushed to an ADC-VX (with /c/vadc/add or rem), if at the same time a vADC Apply (or config sync) occurred indicated by a flag, a race condition while logging this configuration caused the vADC to freeze while waiting for the flag, and was eventually restarted by the Watcher. | DE65960 |
| 12. | When BFD and tunneling are enabled, a panic occurs. | DE66000 |
| 13. | While initiating the SSL client connection for the SSL health check, the vADC MP crashed. | DE66137 |
| 14. | The MP CPU utilization was high when querying virtual stats. | DE66778 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|--------------------|
| 1. | AppWall Publisher does not send syslog security events . | DE64858 |
| 2. | Under rare conditions, after an upgrade, the AppWall configuration file was empty. | DE65443 |
| 3. | In APSolute Vision, Brute Force security events do not display the “request data” payload. | DE65248 |
| 4. | Could not submit a change to the AppWall configuration from the user interface. | DE65271 DE58941 |
| 5. | An AppWall configuration file became corrupted after a system upgrade. | DE64176 |
| 6. | A RuleID was triggered with a request that does not contain a character. | DE64175 |
| 7. | A RuleID was triggered with a request that contains a specific Chinese character. | DE64517 |

Fixed in 32.2.8.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | Upon Submit, there was a Quick Service setup wizard internal error. | DE57036 |
| 2. | In WBM, the equivalent to the filterpbkp CLI command was missing. | DE59726 |
| 3. | In a DPDK VA environment with two NUMAs, packets were not tunnel-processed when they were VMAed to and SP of a different NUMA. | DE60629 |
| 4. | When starting up a vADC startup, the admin context froze and the Watcher killed the process, resulting in a panic. | DE61767 |
| 5. | Alteon closed the front-end and back-end SSL connection abruptly. Fixed the classification of second request if there is content class SSL. | DE61780 |
| 6. | The WANlink current sessions count for IPv6 SmartNAT were not decremented properly due to using the wrong index. As a result, the /stat/slb/real and /stat/slb/lp/wanlink command displayed accumulated values. It has been fixed by using an appropriate index for updating the statistics. | DE61940 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 7. | When the user sent traffic, a throughput high alert message was issued even though the throughput was less than the configured throughput threshold limit. | DE61978 |
| 8. | Actions changing the configuration (such as Apply, Save, and Diff) were incorrectly allowed for users with viewer/operator classes of service when REST requests were sent. | DE62393 |
| 9. | Even after changing the log level from debug to error, warning messages continued to be issued. | DE62436 |
| 10. | A ticket from a failed connection required passing over the authentication policy on the next connection. | DE62486 |
| 11. | With specific browsers, HTTP2 traffic with an uncommon form in the header was not answered. | DE62608 |
| 12. | Exporting a configuration from ADC-VX did not work. | DE62633 |
| 13. | Incorrect MTU syslog messages were issued for vADCs. | DE62660 |
| 14. | The packet capture timestamp was incorrect. | DE62730 |
| 15. | On an ADC-VX, the HW Watchdog rarely rebooted due to an unknown trigger. | DE62748 |
| 16. | While exporting techdata, IPv6 connectivity went down for a short while and then came back up. | DE62821 |
| 17. | When uploading a Layer 2 packet capture from an ADC-VX to the FTP server, Alteon panicked. | DE62851 |
| 18. | Using Ansible, could not configure the TLS 1_3 parameter. | DE62868 |
| 19. | There was vADC auto-reboot issue because of a software panic. | DE62942 |
| 20. | A config sync from a non-HA device to an HA-configured device caused the loss of the HA configurations. | DE62951 |
| 21. | Health check tables were not supported for the l4 admin and slb admin users. | DE62974 |
| 22. | Using WBM, from the Virtual Service Monitoring perspective, the health check failure reason differed from the correct one displayed by the CLI when some of the related virtual services for the given virtual server were blocked. | DE63057 |
| 23. | A non-supported configuration caused a crash. | DE63069 |
| 24. | There was an inconsistency in the current throughput per second statistics units of virtual servers. | DE63093 DE63108 |

| Item | Description | Bug ID |
|------|--|---------|
| 25. | In an HA environment, a config sync operation with a tunnel configuration led to disruption in traffic on the peer device due to a shift in the internal tunnel indices. | DE63190 |
| 26. | In Ansible, it was not possible to remove one VLAN from all interfaces because the value "0" was not accepted. | DE63215 |
| 27. | When multiple VIPs are configured with srcnet, the ptmout value was not being considered. | DE63480 |
| 28. | When VIRT6 went down, when deleting the IPv6 SLB virt, Alteon panicked. | DE63542 |
| 29. | When the user changed the dbind settings to disabled along with the SSL configuration, the dbind configuration was set to forceproxy even though it was set to disabled. | DE63556 |
| 30. | SSL statistics in the CLI and WBM did not match on Alteon running version 32.4.5.0. | DE63568 |
| 31. | Fetching the routing table via REST API when the routing table was full caused a panic. | DE63585 |
| 32. | When a real server had an rport set to 0 and an rport ser to x, the service became unavailable. | DE63618 |
| 33. | After SSL Offloading was enabled, Alteon stopped accepting connections. | DE63629 |
| 34. | After changing the admin password and Applying, there were configuration sync issues with the peer. | DE63758 |
| 35. | Using CLI, after running the /stats/slb/virt command, backup real servers did not display. | DE63802 |
| 36. | After changing a group on an FQDN server, the servers were bound to the older group as well as the new group. | DE63832 |
| 37. | After a signal panic, Alteon stopped booting. | DE63890 |
| 38. | After Alteon received a packet and tried to open a session entry, an incorrect initialization of a pointer resulted in a NULL access and Alteon panicked. | DE64148 |
| 39. | Peer Alteon devices panicked due to vulnerability to CVE-2021-3449. | DE64467 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | High volume of Forensics security events can cause CPU spikes on backup devices | DE63625 |
| 2. | Wrong management IP used to send security events to APSolute Vision | DE62702 |
| 3. | When AppWall (7.6.9.50) is configured in Transparent Proxy mode, the IP configured in the tunnel parameter as “forwarding IP” replaced the real client IP | DE62493 |
| 4. | Failure in AppWall under rare condition, when decoding Base64 traffic | DE62625 |
| 5. | Failures occurred to update AppWall Security updates | DE61559 |
| 6. | Under certain conditions, the AppWall management console can disclose local file | DE61634 |
| 7. | Under rare and extreme conditions, AppWall ignore the server response | DE61267 |

Fixed in 32.2.7.50

General Bug Fixes

| Item | Description | Bug ID |
|------|--|--|
| 1. | Snmpbulkwalk on the capacityUsageStats node returned invalid OID output. | DE62230 DE62231 |
| 2. | In rare circumstances during tsdmp or techdata export, a panic would occur. | DE62550 DE62552 |
| 3. | In a DSR and multi-rport configuration environment, the /stat/slb/virt X command returned statistics as 0. | DE62341 DE62343 |
| 4. | In an HA environment, synching the configuration to the peer device with sync tunnel config flag disabled results in the peer panicking. | DE61960 DE61963 DE62011 DE62012 |
| 5. | After upgrading to version 31.0.13.0, uneven load balancing started. | DE62335 DE62467 |

| Item | Description | Bug ID |
|------|--|--------------------|
| 6. | When a DNS responder service was created, the user was allowed to configure parameters, which caused errors. Now the user can no longer configure parameters in this case. | DE61878 DE61879 |
| 7. | Failed to access the Alteon WBM and the SSH connectivity was lost. | DE62307 DE62309 |
| 8. | Using WBM, there was a display issue when modifying a virtual service with actionredirect. | DE61598 DE61599 |
| 9. | When while handling malicious DNS packet with compression pointer loops, Alteon panicked. | DE62128 DE62129 |
| 10. | There were no Mibs for the health check count to display them for the command /info/sys/capcityswitchCapHealthCheckMaxEntswitchCapHealthCheckCurEnt. | DE61739 DE61740 |
| 11. | Using WBM, when configuring the Nameserver group under DNS Authority, the table name in the mapping file was incorrect. | DE61482 DE61483 |
| 12. | vADCs did not process SSL traffic. | DE61693 DE61694 |
| 13. | There was no support for query type return errors even if the domain was found. | DE61640 DE61641 |
| 14. | Port mirroring increased the SP CPU utilization. | DE62264 DE62267 |
| 15. | There was no support for query type return errors even if the domain was found. | DE61251 DE63650 |
| 16. | Alteon closed the front-end and back-end SSL connection abruptly. Fixed the classification of second request if there is content class SSL. | DE61781 |
| 17. | When the user sent traffic, a throughput high alert message was issued even though the throughput was less than the configured throughput threshold limit. | DE61979 |

| Item | Description | Bug ID |
|------|--|-------------------------------|
| 18. | Alteon did not forward traffic when LACP was disabled and worked as expected when LACP was enabled. | DE61510 DE61518 DE61521 |
| 19. | When Alteon had high MP memory utilization, restarting caused configuration loss. Alteon came up with the default configuration. | DE61204 DE61205 |
| 20. | When a syslog file had long log messages, the /info/sys/log command did not display any log messages. | DE60884 DE60885 |
| 21. | During configuration export, creating the AppWall configuration failed, and as a result the entire operation failed. | DE60948 DE60949 |
| 22. | The default STP group was not available for a newly added physical VM port. | DE61295 DE61296 |
| 23. | When sending an OCSP request over the management port, there were two leaks. | DE60848 DE60849 |
| 24. | If Alteon received a request when all real servers were down, the group with all the real servers' indexes less than 33 and the RR, BW, or response metric failed to select a real server, even if they came up. | DE61143 DE61144 |
| 25. | When the management WBM listener connection control block was closed during its validation, a 50X WBM error displayed. | DE60912 DE60913 |
| 26. | Following a set of SNMP operations, on some occasions Alteon panicked from a memory corruption with a boot reason power cycle. | DE61039 DE61042 DE61083 |
| 27. | In an Alteon HA environment with an SNAT configuration in AppShape++, changing, applying, and synching non-SLB configurations resulted in the following syslog warning: Configuration is not synchronized | DE61093 DE61094 |
| 28. | When the SSH connection with the correct password was attempted for a locked user, the user lockout status was checked too late. | DE60700 DE60701 |
| 29. | AppWall was stuck and did not process traffic but was not restarted by the MP. | DE61472 DE61478 |
| 30. | When the default gateway MAC was changed, Alteon sent return traffic to the incorrect or old MAC. | DE60779 DE60782 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 31. | Using WBM, a 50X error occurred due to buffer leak in an HTTPS request. | DE60763 DE60764 |
| 32. | Alteon sometimes would crash when it received the same apply :filter deletion and network class deletion that was assigned to the PIP that was defined for the real server. | DE61028 DE61029 |
| 33. | When SSL hardware acceleration is active via a QAT card, the Acceleration Engine may go out of sync due to unknown conditions during Config Apply . | DE60361 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|---------|
| 1. | Certain transactions were not properly processed leading to a network connection failure of AppWall version 7.6.8 integrated in Alteon version 32.6.1.0. | DE61267 |
| 2. | Under rare conditions, a configuration change in AppWall integrated in Alteon may have led to a failure. | DE60598 |
| 3. | Enabling base64 decoding in the Database security filter, may have led to an AppWall failure. | DE62625 |
| 4. | Saving security events was limited to the latest 200 events | DE60583 |

Fixed in 32.2.7.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|-------------------------------|
| 1. | When resolving a DNS PTR record, IP matching was skipped (for both hostlk enabled and disabled) if the service hostname was not configured. Fix: The service hostname check now is skipped only if the hostlk is disabled. | DE60805 DE60808 DE60809 |
| 2. | A virtual service application-id configuration diff did not sync to an HA pair. | DE60452 |
| 3. | AppWall was down and the MP did not kill it, resulting in AppWall staying down indefinitely. | DE60157 DE60366 |
| 4. | Starting with this version, the Certificate Group Duplicate button is removed because it is not usable for certificate groups. | DE60330 |

| Item | Description | Bug ID |
|------|--|--------------------|
| 5. | Using Alteon VA, WBM displayed the port type as "Giga Ethernet Copper" irrespective of the actual port type used. | DE59940 |
| 6. | Using WBM, an 50X error occurred due to a leak in buffers on an HTTPS request. | DE60799 |
| 7. | Periodic statistics logging was corrupting the configuration environment during Apply/Save, which resulted in a panic. | DE60307 |
| 8. | Some DNS requests were not answered or were delayed. | DE60088 |
| 9. | A deadlock due to non-async signal functions caused a reboot. | DE59876 |
| 10. | There were negative values in OIDs related to Total Octets in content rules statistics. | DE59834 |
| 11. | The /info/sys/capacity command did not display current virtual and real services. | DE60169 DE60171 |
| 12. | When trying to free the session entry allocated for an AX-processed session, a panic occurred. | DE60179 DE60181 |
| 13. | A vADC displayed all default user account passwords in a dump. | DE59870 |
| 14. | In an MSTP with trunk environment, Alteon failed to communicate with another device. | DE59895 |
| 15. | When a user was in lockout, the information message was not consistent, causing a security problem. | DE59810 |
| 16. | When a user tried to group SFP and non-SFP ports in LACP, the error message that was issued was not clear enough. | DE59740 |
| 17. | After configuring an IPv6 address as a syslog host, the IPv6 VIP stopped working because the address was removed from the nbrcache entry. | DE59663 |
| 18. | DNS query responses were not handled for query types MX and CNAME. | DE60207 |
| 19. | Starting with this version, added the Expiry Time field for the cookie in the Services pane. | DE60047 |
| 20. | The source MAC for a generated SYN ACK was erroneously overwritten during the last IP forwarding process in the non-RTSRCMAC scenario for TCP DNS and dbind ena virtual traffic. | DE59782 |
| 21. | The bandwidth metric sometimes did not work if all the WAN links in a group were configured with health checks. | DE59355 |
| 22. | SAN input for DNS without a period (".") was not allowed. | DE60099 |
| 23. | The DNS query on a Backup device gave an incorrect response. | DE59541 |

| Item | Description | Bug ID |
|------|--|---------|
| 24. | vADCs were in running state but were not able to be accessed via MGMT until they were disabled and then re-enabled. | DE59083 |
| 25. | On a 5208 XL platform, version 32.2.4.60, Alteon did not receive an information message when saving an image on ADC-VX slots completed. | DE59496 |
| 26. | The WAN link server displayed an overflow message for a clear issue for an edge condition. | DE59395 |
| 27. | Could not handle SSL traffic without SNI without the traffic being decrypted. Fix: Now you can attach an SSL policy with front-end and back-end SSL disabled. | DE58830 |
| 28. | With Alteon configured with cookie and multiple rports for real servers, when sending traffic without a cookie, rport persistency was not maintained for the subsequent requests for the same TCP connection. The traffic was load balanced to the lowest rport. | DE59148 |
| 29. | Maxcon support for 1 million was erroneously not implemented in the 30.5 series. | DE58162 |
| 30. | Configuring a data class with a special character propagated to AX failed due to a parsing error associated to the unsupported ASCII character, resulting in an out-of-sync configuration state. | DE59366 |
| 31. | Due to a network outage, Alteon panicked due to an IPv6 gateway failure. | DE59414 |
| 32. | An IPv4 filter session sometimes would be deleted before it aged out if the session memory was previously used by an IPv6 session. | DE60386 |
| 33. | On a 5208 platform, Ethernet ports connected to FireEye stayed down. | DE60232 |
| 34. | When real servers associated with a deleted FQDN real were deleted, AX was not updated. | DE58106 |
| 35. | There were two leaks when sending OCSP requests over the management port, which have been fixed. | DE60845 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | AppWall WebUI sometimes showed a 500 error. | DE59923 |

| Item | Description | Bug ID |
|------|---|---------|
| 2. | AppWall integrated in Alteon sometimes returned an empty page to a client request. | DE59640 |
| 3. | Email notification (STMP) configuration for AppWall integrated in Alteon was wrong. | DE58413 |
| 4. | Occasional slowness in AppWall integrated in Alteon due to memory consumption. | DE58350 |
| 5. | An event- "Failed to update configuration according to awcfg.xml" sometimes appeared even when the configuration was correct. | DE60488 |

Fixed in 32.2.6.50

General Bug Fixes

| Item | Description | Bug ID |
|------|---|-------------------------------|
| 1. | When trying to group SFP and non-SFP ports in LACP, the error message that was issued was not clear. | DE59741 |
| 2. | Using the CLI, when executing the /c/l3/ha/switch/pref command, if the SSH/Telnet connection terminated, a panic occurred. | DE59572 |
| 3. | Before RIP was assigned to an outgoing packet, the packet included the last four bytes of the IPv6 address, resulting in the leading zero in the address being blocked. | DE59487 DE59488 |
| 4. | As a fix, the FIPS domain name length was changed from 14 to 32 characters. | DE59701 DE59702 |
| 5. | The DNS IPv6 EDNS client subnet IP address was incorrect. | DE59578 DE59581 DE59582 |
| 6. | When a real server went down, the virtual statistics summary display was incorrect. | DE59510 DE59514 |
| 7. | On an Alteon VA platform, the jumbo frames feature did not work because the DPDK layer for the VMXNET3 driver did not provide an API call to set the MTU value. | DE59286 DE59288 |
| 8. | On a 5424 platform with an unlimited SSL license, the info/sys/general command incorrectly displayed "S" and not "SL". | DE59025 |
| 9. | In a basic SLB environment, when trying to disable a real server operationally that started with the letter "p," Alteon did not correctly prompt the action. | DE58913 DE58914 |

| Item | Description | Bug ID |
|------|--|-------------------------------|
| 10. | Even after setting the throughput threshold limit to "0," throughput alerts were issued. | DE58819 DE58820 |
| 11. | The total IP range limit value mentioned in the validation error for network classes was incorrect. It should have been 4294967294 instead of 4294967295. | DE59457 DE59458 |
| 12. | When TACACS with clog was enabled, during a techdata/tsdmp operation, unnecessary logs were issued to the syslog. | DE58760 DE58761 |
| 13. | The description for MIB altSwSpCpuPressureDeactivatedTrap was incorrect. | DE58769 DE58770 |
| 14. | When sending ICMP traffic to Alteon, the ICMP session was dumped to the syslog server as UDP. | DE59279 DE59280 |
| 15. | Using CLI over an SSH/Telnet connection, when the /c/slb/real x/shut command was executed without input, closing the connection led to a panic. | DE58595 DE58598 DE58599 |
| 16. | When sending client traffic to an IPv6 VIP with sharing enabled for the VR server, Alteon did not respond. | DE58979 DE58980 |
| 17. | After upgrading from version 30.5 to version 32.2, LinkProof NG static NAT did not perform reverse NAT. | DE58604 DE58607 |
| 18. | Alteon used a console with a 9600 baud rate, and the MP issued information faster than the console could receive it. | DE58737 DE58738 |
| 19. | When FTP was configured on a non-std data port and the port was same as the customized server data port, the data connection did not work. | DE58989 DE58990 |
| 20. | When REST API requests were received after a WBM idle timer timeout, the WBM idle timeout detection mechanism influenced related responses, causing a 401 error. | DE59593 DE59594 |
| 21. | When DSSP messages were received on the backup device, a software panic occurred. | DE58699 DE58702 DE58703 |
| 22. | The Alteon device was not indicated as the next hop in a traceroute from the client machine to the ISP router. | DE58624 DE58626 |
| 23. | After upgrade, in a VRRP environment, Alteon failed to accept the configuration when the same nwclass was associated to more than one VIP and both were part of same VR group. | DE58380 DE58381 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 24. | Executing the /c/slb/gslb/dnsresvip/ command automatically created an index for a new entry. However, if no other subsequent changes were made to this entry, the diff command did not show the new entry. | DE58577 DE58578 |
| 25. | After upgrade, there was a false detection of session table corruption, resulting in an autorecovery. | DE59001 DE59002 |
| 26. | SSL traffic without SNI could not be handled without decrypting the traffic. The fix was to allowing attaching the SSL policy while front-end and back-end SSL are disabled. | DE58832 |
| 27. | While a session having proxy port was being freed, a panic occurred. | DE58193 DE59841 |
| 28. | When deleting an LSA from a neighbor's retransmission list, a panic occurred for link-state ACK packets. | DE59110 DE59111 |
| 29. | In an SLB environment, when a filter was configured with reverse enabled for UDP traffic, traffic intermittently failed due to CPU spikes. Traffic never succeeded when the CPU went down. | DE58364 DE58365 |
| 30. | After deleting the FQDN server and applying and saving, then deleting the group and applying and saving, then adding a new FQDN server and a new group and applying, the error message "Application services engine is not synchronized with the current configuration" was issued. Fix: After removing the FQDN server, the real servers from AX are now also removed. | DE58110 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | AppWall failed to extract the upgrade image. | DE58085 |
| 2. | While accessing the Forensics logs, received a 500 error. | DE59301 |

Fixed in 32.2.6.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|--------------------|
| 1. | In an HTTP Modification rule, when clicking the path option, the Path field was not visible. | DE58288 DE58290 |

| Item | Description | Bug ID |
|------|---|---------|
| 2. | In an ADC-VX environment, after executing the techdata, tsdump, or td-stats all commands, the MP CPU reached 100% utilization. | DE58250 |
| 3. | The Alteon NTP time jumped one month ahead. | DE58133 |
| 4. | At boot time, when AppWall crashed, Alteon also crashed. | DE58058 |
| 5. | When user configuring a scripted health check for port 25 (SMTP), during runtime the syslog was flooded with health check failure logs. | DE57867 |
| 6. | On receiving an ICMP_UNREACH packet, when matching an existing session with no real server, a panic occurred. | DE57860 |
| 7. | When a VRRP group was configured, sharing did not work properly. | DE57848 |
| 8. | In AppShape++ scripting, an early and unnecessary variable validation was removed from the validator function. | DE57762 |
| 9. | After upgrading from version 31.0.10.50 to 32.2.3.50, the GSLB DNS Summary Statistics displayed with a 0. | DE57675 |
| 10. | In Layer 2 mode when flooding to more than one port, fragmented packets (both in order and out-of-path) were lost. | DE57641 |
| 11. | In an ADC-VX environment, after enabling /cfg/slb/ssl/adv/bereuse, after a reset or reboot the value changed back to disabled. | DE57632 |
| 12. | When an unchained buffer was treated as a chained buffer in non-DPDK platforms, a one-time crash occurred. A check was added to packet captures to prevent this. | DE57568 |
| 13. | Due to an incorrect version comparison, TLS 1.1 displayed as disabled by default. | DE57561 |
| 14. | The length of the hostname in the HTTP healthcheck field was increased to 128 characters as required. | DE57548 |
| 15. | There was a high load on the queues from Alteon to AppWall, a session entered into the pending list twice, and activated after termination. This caused a panic. | DE57537 |
| 16. | When PIP mode was configured as address and HA mode as switch, if the same PIP range was associated to more than one service or real server, the PIP ARP limit was reached. | DE57517 |
| 17. | Alteon incorrectly validated unsupported path attributes (currently the BGP community path attribute). | DE57512 |

| Item | Description | Bug ID |
|------|--|--------------------|
| 18. | Using WBM, the percent character (%) in the passphrase for private keys did not work. | DE57488 |
| 19. | Using WBM, could not renew existing certificates because of internal indexing issues. | DE57470 |
| 20. | When a DPDK initialization failed on any error except a queue error, it reverted to tuntap. | DE57371 |
| 21. | On a 9800 platform, after saving a configuration the following error displayed: mgmt: Flash Write Error | DE57349 |
| 22. | Using WBM, removing a target address from the SNMV3 did not remove the address from the AppWall UI server list. | DE57314 |
| 23. | When the SNMP OID hwApplicationSwitchNameInfo was probed, the port state incorrectly changed to disabled by referring to the wrong port flag state. This led the gateway health check to fail. | DE57304 |
| 24. | When the MP froze, the Watcher did not also kill the AW process of this MP. | DE57293 |
| 25. | When the real server rindex fell in a different word index group (rindex value /32), SLB traffic ignored the real server's weight for the roundrobin group metric. | DE57269 |
| 26. | After rebooting a master and it comes up with an RSTP setup, an ARP packet was sent and received over the backup's block port. | DE57251 |
| 27. | The interface IP address and floating IP address were swapped and applied. The IF IP address was added to the IP6 Neighbor Cache table as the new IF IP address, but was deleted as the old floating IP address. | DE57224 |
| 28. | After rebooting a vADC, the GSLB/LinkProof licenses were disabled. | DE57178 |
| 29. | After performing a recovery, the session capacity value was incorrect. | DE57147 |
| 30. | As per RFC 3416, the SNMP Get Next values should be in lexicographical format, but Alteon did not follow this for the FDB table and other tables. A fix was made only for the FDB table. | DE57060 |
| 31. | On a FIPS card, a session terminated while it was still pending for a task. | DE57049 DE57051 |
| 32. | After a period of no traffic, the race condition timing could lead to an AppWall restart. | DE56991 |

| Item | Description | Bug ID |
|------|--|---------|
| 33. | OSPF was not able to send a link state update (redistributed route) to peer when the gateway went down. | DE56965 |
| 34. | In an SLB environment with HA and session mirroring enabled, real server current session statistics and redirect statistics displayed incorrectly in the /i/slb/virt x summary on the backup device. This resulted in traffic failure when the backup became the active. | DE56946 |
| 35. | A configuration with many real servers caused a delay in context switching, resulting in LACP messages not being handled. | DE56933 |
| 36. | Using WBM, when trying to modify the throughput limit, an error occurred. Added a REGEX to support all the throughput licenses. | DE56921 |
| 37. | After version upgrade, GEL licenses were rejected. | DE56887 |
| 38. | In an HA environment with vADCs, when trying to send more OSPF routes to the peer device, a panic occurred. | DE56836 |
| 39. | An incorrect FIPS license string (deprecated) caused a flow of FIPS tests. | DE56812 |
| 40. | When a service was configured in a non-existing VIRT, it remained unnoticed until the VIRT was defined. | DE56794 |
| 41. | Using WBM, the Edit Security Policy option did not display. | DE56783 |
| 42. | When mgmt was disabled and the syslog defined on mgmt, the new syslogs did not display in /info/sys/log. | DE56733 |
| 43. | There was a RADIUS Authentication failure because secret was not configured. No warning was issued for this. | DE56722 |
| 44. | After inserting a 1G SX Multimode transceiver, the following error displayed: "Cannot work with 1G transceivers." | DE56713 |
| 45. | Alteon DPDK platforms dropped out-of-order fragmented packets. | DE56700 |
| 46. | The vconsole internally used Terminal MultiPlexer (TMUX), which is not available on DPDK-based platforms. | DE56691 |
| 47. | When trying to upload tech data when the management network was slow, an SCP timeout error occurred. | DE56655 |
| 48. | After applying the /info/sys/general command, the output was incorrectly 7612 S instead of 7612 SL. | DE56608 |
| 49. | While deleting an IPv6 configuration, a panic occurred. Added defensive validations. | DE56597 |
| 50. | Using WBM, the Monitoring > System > Capacity > Application Delivery page did not display capacity information. | DE56486 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 51. | Port 2233 was visible to public networks. The new behavior is that port is visible to a local host only (for example: 127.0.0.1:2233). | DE56399 |
| 52. | Using the CLI, after configuring a local add as a nwclass ID, after reboot, the configuration was not applied. | DE56336 |
| 53. | Using WBM, the configured Server Certificate group in a configuration did not display. | DE56289 DE56291 |
| 54. | Configuring the data class IP address with mask 0 caused a panic. Because mask 0 is invalid, the fix was to ignore it. | DE56281 |
| 55. | When IPv6 TCP small packets were received by the MP out of order via the data port, the memory associated with the packets was not returned (after the usage) to the pool of free small packets, causing problems for features allocating such packets. | DE56080 |
| 56. | On an ADC-VX, an NTP timeout occurred. | DE55856 DE55861 |
| 57. | In an SLB environment with forceproxy, the TCP policy/pushack worked as disabled even though it was enabled, causing a TCP retransmission problem. | prod00267404 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Integrated WAF: Websec module down/up events are shown in the device system logs. | DE57855 |
| 2. | Error API call when trying to change a tunnel operational status using AppWall API. | DE57217 |
| 3. | AppWall API - Get specific security event resulted in error. | DE57216 |
| 4. | Doc bug in AppWall API documentation | DE57200 |
| 5. | Integrated WAF: Incorrect information under syslog's DIP field. | DE56918 |
| 6. | Alteon is not sending syslog messages for integrated AppWall. | DE56861 |
| 7. | WAF XML file breaks Event details into multiple queries. | DE56386 |
| 8. | Activity tracking refinement issue. | DE56277 |
| 9. | Multiple events from different sessions are seen with same transaction ID | DE56260 |

Fixed in 32.2.5.50

General Bug Fixes

| Item | Description | Bug ID |
|------|---|--------------------|
| 1. | Using WBM, you could not renew existing certificates because of internal indexing issues. | DE57474 |
| 2. | When AppWall had memory pressure, traffic was bypassed and did not restart after 60 seconds. | DE57400 |
| 3. | When a DPDK init failed on any error except a queue error, the configuration reverted to TUN/TAP. | DE57375 |
| 4. | On a 9800 platform, after saving a configuration, the following error displayed: <code>mgmt: Flash Write Error</code> | DE57353 |
| 5. | Using WBM, removing the target address from SNMPv3 did not remove the address from the AppWall UI server list. | DE57318 |
| 6. | When SNMP OID <code>hwApplicationSwitchNameInfo</code> was probed, the port state incorrectly changed to DISABLED by referring to wrong port flag state. This led to a gateway health check failure. | DE57308 |
| 7. | The Watcher did not kill the AppWall process that was related to the MP. | DE57297 |
| 8. | SLB traffic ignored a real server's weight for the roundrobin group metric when the real server rindex was included in a different word index group (rindex value /32). | DE57273 |
| 9. | If the Interface IP address and floating IP address were swapped and applied, the IF IP address was added to the IPv6 Neighbor Cache table as the new IF IP address but was deleted as the old floating IP address. | DE57228 |
| 10. | After reboot a vADC, the GSLB/LinkProof license was disabled. | DE57182 |
| 11. | When performing a recovery session, the incorrect capacity value was displayed. | DE57151 |
| 12. | Per RFC 3416, the SNMP Get Next values should be in lexicographical order, but this was not implemented for the FDBtable and other tables. This issue was fixed only for the FDBtable. | DE57058 |
| 13. | After a certain amount of time with no traffic, race condition timing could lead to an AppWall restart. | DE56989 DE56995 |
| 14. | OSPF was not able to send a link state update (redistributed route) if there was a link failure or route change. | DE56969 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 15. | In an SLB environment with HA and session mirroring enabled, the real server current session statistics and redirect statistics were displayed incorrectly after issuing the command <code>/i/slb/virt x summary</code> on the backup device. It resulted in traffic failure when the backup became the active. | DE56944 DE56950 |
| 16. | A configuration with many real servers caused a delay in context switching, resulting in LACP messages not to be handled. | DE56931 DE56937 |
| 17. | Added REGEX to support all throughput licenses. | DE56925 |
| 18. | When Alteon tried to send more OSPF routes to a peer device, a panic occurred. | DE56840 |
| 19. | While trying to access SSH, a bad FIPS license string (which was also deprecated) caused a flow of FIPS tests. | DE56816 |
| 20. | When a service was configured in a non-existing VIRT, it remained unnoticed until the VIRT was defined. | DE56798 |
| 21. | Using WBM, the Security Policy option did not display. | DE56787 |
| 22. | When the management port was disabled and the syslog was defined on the management port, the new syslogs did not display when issuing the <code>/info/sys/log</code> command. | DE56737 |
| 23. | RADIUS Authentication failed because the secret password was not configured. In addition, no warning was issued for this issue. | DE56726 |
| 24. | After inserting a 1 G SX Multimode transceiver, the following error displayed: <code>Cannot work with 1G transceivers.</code> | DE56717 |
| 25. | Alteon DPDK platforms dropped the out-of-order fragmented packets. | DE56704 |
| 26. | When uploading Techdata when the management network was slow, an SCP timeout error occurred. | DE56659 |
| 27. | After applying the <code>/info/sys/general</code> command, the output of the command incorrectly displayed "7612 S" instead of "7612 SL". | DE56612 |
| 28. | While deleting an IPv6 configuration and adding defensive validations, a panic occurred. | DE56601 |
| 29. | To aid with a configuration that requires many real server health checks, the maximum and current values for real services was added to the <code>/info/sys/capacity</code> output. | DE56490 |
| 30. | When using the CLI to configure a local add as network class ID, after reboot the configuration was not applied. | DE56334 DE56340 |

| Item | Description | Bug ID |
|------|---|---------|
| 31. | When small IPv6 TCP packets were received by the MP out of order via a data port, the memory associated with the packets did not return (after usage) to the pool of free small packets, causing problems for features allocating such packets. | DE56331 |
| 32. | Using WBM, a configured server certificate group did not display. | DE56295 |
| 33. | A check was added for packet captures to prevent a one-time crash that occurred when an unchained buffer was treated as a chained buffer on non-DPDK platforms. | DE55730 |

Fixed in 32.2.5.0

General Bug Fixes

| Item | Description | Bug ID |
|------|--|--------------------|
| 1. | Could not save a configuration change and received the error <code>Flash Write Error</code> . | DE57353 |
| 2. | If there was no default Gateway defined or the Gateway failed, after a security scan there was total service outage. | DE56256 |
| 3. | When a burst of packets were sent to the MP for ARP resolution, subsequent packets were dropped when ARP resolution was already in progress for the first packet of a given destination, or when there was an RST from the client followed by a retransmission of a GET request, a connection drop occurred. | DE56152 |
| 4. | In an IPv6 environment, when the protocol is set to both for a virtual service, the lookup failed for the virtual service and the client traffic was dropped. | DE56137 |
| 5. | In an IPv6 environment, a specific virtual service could not be DNS-resolved by GSLB. | DE55998 |
| 6. | In an IPv6 environment, a specific virtual service could not be DNS-resolved by GSLB. | DE55993 |
| 7. | The HTTP modification rule for a host match did not accept a dot (.) in the match term. | DE55932 DE55934 |
| 8. | The translation to Chinese for the value <code>slbNewCfgEnhVirtServApplicationType.13</code> was incorrectly translated as "basic slbit"; it should have been "SMTP." | DE55929 |
| 9. | Stuck sessions in AX caused another of issues, resulting in a panic. | DE55833 |

| Item | Description | Bug ID |
|------|---|---------|
| 10. | Alteon lost communication with the LLS and entered the grace period. | DE55778 |
| 11. | Using WBM, the dot (.) character was not supported in an SSL policy name. | DE55720 |
| 12. | After an upgrade to version 31.0.12.0, a panic occurred because of null pointer access. | DE55710 |
| 13. | When processing some network elements having consecutive IP addresses as an exclude set, the network class configuration error " total IP range cannot be greater than 4294967295!" was issued. | DE55669 |
| 14. | When CDP was configured with a domain name, after the DNS resolution the request was framed using the resolved IP address in the HOST header field instead of the domain name. | DE55652 |
| 15. | On an Alteon 5412XL platform, the same cookie load-balanced to multiple real servers. | DE55597 |
| 16. | In an AppWall integrated in Alteon environment, a new secwa did not display in the AppWall Console. | DE55470 |
| 17. | The configuration migration tool duplicated the GSLB network for Inbound LLB rules. | DE55449 |
| 18. | The MP froze during the GEL active license periodic revalidation. | DE55434 |
| 19. | A DNS request matched the cache unexpectedly. | DE55407 |
| 20. | Layer 7 SNI-based LLB did not work with BWM enabled in Enforcement mode. | DE54451 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Source Threshold is not enforced by Activity Tracking's Anti-DDoS in certain cases in 7.6.7.0. | DE56123 |
| 2. | Parameter Security filter might fail to load certain Regular Expressions correctly. | DE56110 |
| 3. | Rare case where additional changes to AppWall configuration was not synced to the backup. | DE56051 |
| 4. | Some Security Events have the wrong Security Event Description. | DE55887 |
| 5. | Rare case under heavy traffic causing a parsing mistake that can lead to traffic being blocked. | DE54949 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 11. | Using AppWall integrated with Alteon, all Web applications stopped. | DE55234 DE55238 |
| 12. | Routes through GRE/IPinIP tunnels did not display after running the /i/sys/capacity command. | DE55211 |
| 13. | Site resources were not cached by FastView | DE55128 DE55132 |
| 14. | After connecting to the GEL server, the Alteon console was flooded with some junk logs every 18 seconds. | DE54944 |
| 15. | Using WBM, you could not create a service using TCP 995. | DE54878 |
| 16. | Allow filters failed to decrypt IPv6 traffic. | DE54824 |
| 17. | The error message "Someone else is doing the diff [flash] try again!" was issued. | DE54814 |
| 18. | When HAID 2 was configured, /info/slb/virt displayed the wrong Virtual MAC ID. | DE54759 |
| 19. | After upgrading, Alteon was not able to push the intermediate certificate and failed to apply the configuration. | DE54733 |
| 20. | After Revert Apply, the gateway flapped in Alteon running version 31.0.9.0. | DE54685 |
| 21. | Config sync was unsuccessful. The Application Services Engine was not synchronized with the current configuration. | DE54676 |
| 22. | The WBM menu was disabled, but you could use CLI to modify settings. | DE54662 |
| 23. | Performing proxy processing on an OSPFv6 packet caused a panic and reboot. | DE54648 |
| 24. | During a new image upload, if the available disk space was low on a device, an error message was only issued after 94% of the download completed. Now a warning message about low disk space is issued before the download starts. 0 | DE54637 |
| 25. | A BGP peer established a connection and changed back to the Connect state. | DE54625 |
| 26. | Could not upgrade from Alteon VA version 32.2.0.0 to 32.2.3.0 version. | DE54606 DE54610 |
| 27. | When GW 1 was deleted, DNS health checks were not generated but ICMP health checks were generated. | DE54588 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 28. | APoSolute Vision sent an incorrect REST query to Alteon. | DE54487 DE54491 |
| 29. | There was error while applying a configuring for a network class. | DE54482 |
| 30. | There was an Alteon SSL inspection and IWSVA Integration Issue. | DE54469 |
| 31. | The Packet Capture tool did not capture all the packets sent from the SP to the MP. | DE54433 |
| 32. | When the TACACS server was configured with command logging, Alteon failed to identify the global commands cdump, telnet, traceroute as global commands. Instead, it tried to process from the local menu where it does not exist, resulting in a panic. | DE54424 DE54428 |
| 33. | Using WBM, downloaded techdata and core dumps were corrupt. | DE54419 |
| 34. | The SNMP overload health check mechanism stopped working when it was added to the logExp health check. | DE54410 |
| 35. | The fragmented CPU size was increased from 16K to 64K. | DE54401 |
| 36. | Using the WBM, a VLAN name of 32 characters was allowed, while in the CLI, only 31 characters was allowed. | DE54375 DE54386 |
| 37. | In the Real Server configuration pane, the HA master displayed FQDN instances. | DE54388 |
| 38. | There was a bug in the Advisory Tool upgrade. | DE54376 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|--|-------------------------|
| 1. | The communication properties option in the wizard was not relevant. It has been removed. | DE51197 prod00272955 |
| 2. | SC6307 – In WBM, VLAN sometimes would not function properly if the VLAN was configured using the Java applet in a previous version, and AppWall was upgraded to newer version. | DE54671 |
| 3. | The AllowList REST API call was changed incorrectly after upgrade from version 7.5.8 to version 7.6.6. The REST API call is now fixed. | DE54742 |
| 4. | The exported Forensics events was not in the correct XML format. | DE55291 |

Fixed in 32.2.4.0

General Bug Fixes

| Item | Description | Bug ID |
|------|---|------------------------------|
| 1. | Alteon failed to identify cdump, telnet, and traceroute as global commands and tried to get command details from the current menu, resulting in accessing invalid memory and causing a panic. | prod00278132 |
| 2. | When using HTTP/2 after login, traffic stops working. | prod00278052 |
| 3. | In a LinkProof for Alteon environment, there were Intermittent ICMP packet drops. When pinging from the same sequence number, the ping reply packets dropped intermittently. | prod00274632 prod00276798 |
| 4. | In an SLB environment with a pbind client IP address, persistence was not maintained. | prod00275771 |
| 5. | When a device came up after reboot, the HA status displayed as NONE because the HA state was recorded based on the current HA service group state for which the apply was in process. | prod00275321 |
| 6. | After upgrading to version 32.2.3.0, Alteon rebooted often due to a panic. | prod00277796 |
| 7. | After attempting to generate new Web Management Certificate, Alteon crashed. | prod00278178 |
| 8. | When the primary WAN link went down and the backup WAN link took over, an incorrect syslog message displayed. | prod00276594 |
| 9. | AppWall for Alteon issued the following error message: Server Error: "Get of FilterAdv/Database failed!" | prod00277201 |
| 10. | A confusing configuration resulted while implementing LDAP(S) health check. | prod00274926 prod00275743 |
| 11. | On DPDK platforms, Interface errors for port statistics were issued. | prod00277490 |
| 12. | In an Azure environment, Alteon VA crashed. | prod00276479 prod00276485 |
| 13. | When an HTTP modification string was configured with multiple escape sequences, Alteon did not insert an escape sequence. | prod00276803 |
| 14. | In a DSR environment, there was a discrepancy between /info/swkey and virtual server statistics. | prod00277836 |
| 15. | When using HTTP/2 after login, traffic stops working. | prod00278068 |
| 16. | Changes to the SSL policy caused a corruption. | prod00278255 |

| Item | Description | Bug ID |
|------|---|--------------|
| 17. | On an Alteon VA, Alteon reset the connection when traffic failed over. | prod00277405 |
| 18. | ICAP responses were not forwarded to the client. | prod00276507 |
| 19. | SSL traffic caused a panic. | prod00278065 |
| 20. | BGP 4 Byte ASN was not compatible with Cisco Nexus 9K and Huawei routers. | prod00276712 |
| 21. | Traffic was forwarded to a failed WAN real server. | prod00276354 |
| 22. | On an Alteon 5424 platform with 24G RAM and software version 32.4.1.10, the maximum sessions remained as 11M even though the sesscap value was 100%. | prod00277363 |
| 23. | There were many FLOOD entries being created in the FDB table for the PIP MAC. This caused some of the traffic to fail. | prod00277244 |
| 24. | In a GSLB environment, Alteon became stuck with high MP CPU utilization. | prod00276518 |
| 25. | While STG information was sent from an ADC-VX to a vADC, a panic occurred. | prod00278077 |
| 26. | During an upgrade to version 32.2.30 or later, the configuration became stuck in diff. | prod00276739 |
| 27. | An invalid hypervisor type was set for virtual platforms. | prod00276258 |
| 28. | Using WBM on a vADC, could not renew an SSL certificate. | prod00276406 |
| 29. | Using WBM, a user could change the admin password while being authenticated via TACACS or RADIUS. Usually a user is not allowed to change the admin password when logged in with "admin Privileged" using TACACS or RADIUS. | prod00277354 |
| 30. | IPv6 SNMP queries over the data port were not working because checking for management access with the ingress data port failed. | prod00277307 |
| 31. | With two vADCs hosted on the same ADC-VX, all applications stopped working. | prod00277921 |
| 32. | In an SLB environment, after a config sync was performed with PIP sync disabled. Alteon did not replace the client IP address with a PIP. | prod00277516 |

| Item | Description | Bug ID |
|------|---|--------------|
| 33. | <p>The priorities for remote real servers among different GSLB network did not behave as expected.</p> <p>With this version, priority is given to nwclasses matching in added networks. As a result, if there is a SIP match for one of the networks, a network with SIP=any will not be considered. If there is no SIP match for networks with SIP configured, then a network with SIP=any will be considered. Priority is considered among the real servers of the matched network.</p> | prod00276833 |
| 34. | Trend Micro's IWSVA (AV) in ICAP mode (with Alteon acting as ICAP client) was only partially working. | prod00277013 |
| 35. | Added GSLB site IP address validation. | prod00277093 |
| 36. | Using WBM, when starting a packet capture, unexpected data displayed for /c/sys/alerts when the packet capture filter string was set to more than 128 characters. | prod00275469 |
| 37. | The Alteon 6024 platform rebooted due to a panic. | prod00276358 |
| 38. | An HTTP header modification value set to None was considered as valid input. | prod00277182 |
| 39. | Connections to a VIP closed abruptly. | prod00276582 |
| 40. | When the management port was disabled, syslog messages were not sent on the data port. | prod00278036 |
| 41. | The backup group status in a content rule displayed an incorrect status when the backup group was not directly associated to any service. | prod00276753 |
| 42. | In an IPv6 SLB environment with an IPv6 HTTP health check and IPv6 HA configured, the memory allocated for HTTP HC was not freed, which led to a memory leak. | prod00276963 |
| 43. | During stress traffic, a panic occurred. | prod00278080 |
| 44. | Using WBM, you could not edit the IP address for a new Outbound LLB Rule. | prod00277382 |
| 45. | Using WBM, during configuration sync, continuous fetching of the virtual server table caused a panic. | prod00277465 |
| 46. | During SNMP polling, a panic occurred. | prod00277992 |
| 47. | After HA failover, Alteon lost router connectivity in order to reach real servers. | prod00277716 |
| 48. | When changing to the default configuration, the runtime session capacity was not reflected. | prod00276871 |

| Item | Description | Bug ID |
|------|--|--------------|
| 49. | When importing a configuration with BGP, Alteon issued Notice messages with non-ASCII characters. | prod00275645 |
| 50. | Throughput Threshold alerts displayed despite the threshold level being set 0 (disabled). | prod00276299 |
| 51. | Using WBM, could not configure BGP 4-byte-ASN. | prod00276811 |
| 52. | After upgrading to version 31.0.11.0, SSL offload did not work properly. | prod00276273 |
| 53. | Could not log in to AppWall. | prod00275568 |
| 54. | The port speed capability was not handled for the MR platform XGE interface while dumping the port configuration and port auto-negotiation configuration options, resulting in no diff configuration. | prod00275658 |
| 55. | In an SLB environment, when the session move operation was executed, in some cases this operation was not reset on one of the SPs, which resulted in all subsequent session move operations to fail on that particular SP. | prod00276336 |
| 56. | Using WBM, when "Return to Last Hop" was set for a virtual server, an additional field type was also set internally. | prod00276930 |
| 57. | On a vADC, incorrect Throughput Alert messages were issued. | prod00275925 |
| 58. | When the Alteon HA state changed from Master to Backup, the gateway and real server's health checks failed. | prod00278211 |
| 59. | When changing from ena to dis and vice versa, could not apply the /cfg/l3/ha/switch/filtpbkp command. | prod00277752 |
| 60. | The Alteon NG+ license did not apply the 5 vADC license. | prod00276635 |
| 61. | VRs and Switch HA and Service HA configurations sometimes would flap or go into the INIT state after synching the configuration from the secondary device to the primary device if there was a difference in the configuration between the two devices. | prod00276499 |
| 62. | After a panic, the Admin context went into a reboot loop. | prod00276326 |
| 63. | In an SLB environment with preemption disabled for the primary real server, when it was in the failed state and the backup real server became the primary, the original primary real server became the backup server when its health check came UP, even though preemption was disabled. | prod00277334 |
| 64. | Could not sync or apply changes. | prod00276400 |

| Item | Description | Bug ID |
|------|---|--------------|
| 65. | Using the preempt disabled feature, a primary real server that was moved to the OPER DIS state by the HC module when the backup was UP for the service, continued to be in the OPER DIS state even when the "backup" and "preempt dis" settings were removed from it. | prod00276614 |
| 66. | When processing the second fragment destined for the Alteon interface when the redirect filter was configured, Alteon panicked. | prod00277479 |
| 67. | When logged in as a TACACS or RADIUS user, could not modify or create SNMPv3 authentication or privacy passwords. | prod00276999 |
| 68. | The Intermediate CA certificate could not be imported due to unexpected max limit. | prod00278074 |
| 69. | There was a disparity of the MAC address between the primary and backup devices. | prod00275353 |
| 70. | After deploying a TCP optimization policy, the software panicked. | prod00277923 |
| 71. | An unexpected LACP changed state resulted in the device switching to BACKUP state. | prod00278165 |
| 72. | After upgrading to version 32.2.3.0, the device constantly rebooted due to a panic. | prod00278290 |
| 73. | An explicit proxy caused unexpected behavior for HTTP/HTTPS traffic. | prod00278450 |

AppWall Bug Fixes

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Scenarios where the 'Replace HTTP Reply Messages with Custom Messages' feature did not function. | DE53496 |
| 2. | After performing a 'Revert' for AppWall in Alteon, you must refresh the page. | DE50247 |
| 3. | For AppWall in Alteon, in some scenarios, the AppWall page is grayed-out for a brief period while applying a new configuration. | DE51355 |
| 4. | For AppWall in Alteon, in rare cases, when applying configuration changes, AppWall's "Login" page is shown and the login will not succeed. In such cases, a restart to AppWall's service is needed. | DE51346 |
| 5. | Source Blocking module might not be enforced on IPv6 sources identified using an HTTP Header, as in the case of CDNs. | DE51975 |

| Item | Description | Bug ID |
|------|---|---------|
| 6. | Auto Discovery should be set manually to “Resume Auto Discovery” when enabling “Auto Policy Generation” on an already-configured application path in the security policy. | DE52165 |
| 7. | When using Source Blocking with IPv6 addresses, at least one IPv4 address must exist in the list for the feature to be enabled. | DE49832 |
| 8. | Rare case leading AppWall to restart. | DE53577 |
| 9. | Scenarios where the 100-Continue header was not sent correctly by AppWall in Alteon, causing the transaction to fail. | DE53201 |
| 10. | Rare case when refining parsing properties failed with a server error. | DE53336 |
| 11. | Event log filters by date may include additional events in some scenarios. | DE54073 |
| 12. | Rare case that led to the error "Server Error: "Get of FilterAdv/Database failed!" in the WebUI for AppWall in Alteon. | DE51538 |
| 13. | Scenario where sync fails for AppWall in Alteon. | DE53151 |
| 14. | AppWall in Alteon does not parse parameters which value contains Emoji Unicode characters. | DE51007 |
| 15. | LDAP group-based authentication may fail in some scenarios. | DE53520 |
| 16. | Some scenarios where Redirect Validation was not enforced on specific URL prefixes. | DE53373 |
| 17. | A Vulnerability security event is wrongly classified as "HTTP Method Violation". | DE53368 |
| 18. | Wrong title in "Threat" field for FastUpload events. | DE53379 |
| 19. | LDAP group authentication may fail login in some scenarios. | DE53261 |
| 20. | Rare case where transactions were blocked while the tunnel Operational Mode is in Bypass. | DE52453 |
| 21. | Wrong tunnel name reported on Source Blocking events in some scenarios. | DE52002 |
| 22. | Scenario where Source Blocking stopped blocking blocked sources after a configuration change. | DE52167 |
| 23. | LDAP attribute cannot be modified when using LDAP group-based authentication. | DE53760 |
| 24. | A specific type of injection was not detected. | DE53785 |
| 25. | Scenario where LDAP configuration was not kept after reboot. | DE54019 |

| Item | Description | Bug ID |
|------|--|---------|
| 26. | Rare case where an error was shown in WebUI after adding publishing rules. | DE53413 |
| 27. | Filtering Event Log based on predefined forensics view may not work in some cases. | DE54045 |

Fixed in 32.2.3.50

| Item | Description | Bug ID |
|------|---|------------------------------|
| 1. | BGP 4-byte ASNs were not compatible with Cisco Nexus 9K and Huawei routers. | prod00276567 |
| 2. | Using WBM, could not configure BGP 4-byte-ASN. | prod00276623 |
| 3. | An invalid hypervisor type was set for virtual platforms. | prod00271421 |
| 4. | After syncing the configuration from the secondary device to primary device, virtual routers, Switch HA, and/or Service HA may flap or go into the INIT state if there was a configuration difference between two devices | prod00276317 |
| 5. | Using APSolute Vision, when Alteon with no AppWall license was configured with ADC Analytics, an MP memory leak occurred, resulting in all MP related processes to not function. | prod00276068 |
| 6. | Traffic was forwarded to a failed WAN real server. | prod00276183 prod00276357 |
| 7. | When a starting packet capture through WBM, incorrect data displayed when running /c/sys/alerts when the packet capture filter string was set to more than 128 characters. | prod00275357 |
| 8. | The backup group status in a content rule displayed the incorrect status when the backup group was not directly associated to any service. | prod00276622 |
| 9. | An IWSVA (AV) in ICAP mode (with Alteon acting as the ICAP client) was only partially working. | prod00276988 |
| 10. | Connections to a VIP randomly closed. | prod00276581 |
| 11. | Fixed a panic scenario based on case prod00275591. | prod00276361 |
| 12. | There was a disparity of the MAC address between the primary and backup devices. | prod00275352 |
| 13. | In an IPv6 SLB environment with an IPv6 HTTP health check and IPv6 HA configured, the memory allocated for the HTTP health check was not freed, which led to a memory leak. | prod00276964 |

| Item | Description | Bug ID |
|------|---|--------------|
| 14. | Using WBM, the HTTP health check edit pane did not display configured settings and values. | prod00275725 |
| 15. | When a device came up after reboot, the HA status displayed as "NONE" because the HA state was recorded based on current HA service group state for which an Apply was in process. | prod00275638 |
| 16. | With AES was used for privacy/encryption, the initialization vector was not set properly, causing an AES encryption failure. | prod00276311 |
| 17. | The device banner and /boot/cur displayed different active Alteon versions on the ADC-VX. | prod00276980 |
| 18. | The port speed capability was not handled for the MR platform XGE interface while dumping the port configuration and port auto-negotiation configuration options, resulting in no diff configuration. | prod00275657 |
| 19. | After upgrading to version 31.0.11.0, SSL offload did not work correctly. | prod00276281 |
| 20. | Using WBM, the HTTP health check edit pane did not display the configured settings and values | prod00275722 |
| 21. | Using LinkProof for Alteon, intermittent ICMP packet was dropped. After pinging from same sequence number, the ping reply packet intermittently dropped. | prod00276799 |
| 22. | In a GSLB environment, the device became stuck with high MP CPU. | prod00276545 |
| 23. | Incorrect throughput alert messages displayed on vADCs. | prod00275927 |
| 24. | In an SLB environment, when the session move operation is executed, in some scenarios this operation was not reset on one of the SPs, which leads all subsequent session move operations to fail on that particular SP. | prod00276342 |
| 25. | Added GSLB site IP address validation. | prod00277092 |
| 26. | The Alteon NG+ license did not apply the 5-vADCs license. | prod00276640 |
| 27. | Using the preempt disabled feature, a primary real server that is moved to the OPER DIS state by the health check module when the backup is UP for the service continues to be in OPER DIS state even when the "backup" and "preempt dis" configuration is removed from it. | prod00276613 |
| 28. | Alteon VA crashed in an Azure environment. | prod00276482 |
| 29. | When importing a configuration with BGP, notice messages were issued with non-ASCII characters. | prod00275644 |

| Item | Description | Bug ID |
|------|--|--------------|
| 30. | Using WBM, when the Return to Last Hop was set for a virtual server, an additional field type also was set internally. | prod00276929 |
| 31. | ICAP responses were not forwarded to the client. | prod00276508 |
| 32. | When upgrading to version 32.2.30 or later, the configuration became stuck in diff. | prod00276745 |
| 33. | There were many flood entries created in the FDB table for the PIP MAC, causing some of the traffic to fail. | prod00277027 |

Fixed in 32.2.3.0

| Item | Description | Bug ID |
|------|---|--------------|
| 1. | Could not log in to AppWall because the AppWall token did not match the Alteon token. | prod00275564 |
| 2. | A long certificate name was not accepted when attached to back-end policy. | prod00272989 |
| 3. | Site selection rules displayed the MIB name instead of the Rule ID. | prod00272405 |
| 4. | NTP requests were not sent in an OSPF network. | prod00274152 |
| 5. | When viphlth was enabled, there was no response to ICMP health checks directed at VIPs. | prod00274567 |
| 6. | The GSLB DNS client network rules real server selection pane was too small. | prod00272404 |
| 7. | After upgrading to version 32.2.2.0, constant VRRP flaps with MP keepaliveFailure occurred. | prod00274443 |
| 8. | While loading the configuration from flash, an Apply failure occurred during bootup time. | prod00274156 |
| 9. | In a GEL Environment, the Alteon VA prompt license server was constantly reestablishing. | prod00274121 |
| 10. | With lower BFD rx-int configured, when there was a change in the session table type between ABT and PBT, the BFD session went down, causing deletion of the BGP session. This issue has been addressed by yielding control to the SP to send BFD packets. | prod00272433 |
| 11. | In an AppWall integrated with Alteon environment, the Websocket bypass feature stopped. | prod00274445 |
| 12. | While running a scan over SSH, Alteon panicked. | prod00274764 |
| 13. | After a device reset, could not connect to the Alteon VA management IPv6 address. | prod00274941 |

| Item | Description | Bug ID |
|------|--|--------------|
| 14. | In an AppWall integrated with Alteon environment, there were multiple "Networking Problem" events. | prod00274862 |
| 15. | Using WBM, could not change the default of factory configuration to save the management configuration. | US64628 |
| 16. | With Layer 7 Application Acceleration, some connections were dropped in the middle. | DE50652 |
| 17. | Using LinkProof NG, when the upload/download limits for the WAN link were configured to be greater than 455 Mbps, WAN link bandwidth utilization displayed incorrect statistics. | prod00273016 |
| 18. | Health checks failed due to a corruption in the small/medium/jumbo packet free pool list because of a synchronization problem in the ARP module. | prod00274561 |
| 19. | SIP INVITE and fragmented packets were not forwarded to real servers. | prod00273235 |
| 20. | Using WBM, a Notify View ISO could not be configured without creating a custom Notify Tag. | prod00273725 |
| 21. | Using WBM, could not configure the sync passphrase. | prod00274327 |
| 22. | After running /stat/slb/clear, only part of the filter statistics was cleared, and the others remained cleared. | prod00272888 |
| 23. | A vADC panicked. | prod00274793 |
| 24. | Configuration sync failed with a timeout. | prod00273099 |
| 25. | Using WBM, when changing the "DNS Responder VIP" from "dis" to "ena" and vice versa, Alteon did not update the flags that are used to identify the config change. Because of this, Alteon found no config change during Apply and an issue occurred. | prod00273282 |
| 26. | After resetting the admin password from the console, the password displayed in clear text in diff flash. | prod00274145 |
| 27. | In a GSLB environment, Alteon did not resolve a DNS query even though the remote real servers were UP. | prod00272897 |
| 28. | While running a scan over SSH, Alteon panicked. | prod00274797 |
| 29. | After a Submit via QAS, a service's rport was overwritten. | prod00272874 |
| 30. | Using config sync, disabling virt synchronization removed virtual servers from the backup device. | prod00273196 |
| 31. | A vADC could not handle any data traffic including a health check. The vADC did not restart after an SP panic/freeze. | prod00274323 |

| Item | Description | Bug ID |
|------|--|--------------|
| 32. | SNMP data of polling interface details incorrectly displayed the interface type. | prod00273386 |
| 33. | A vADC panicked, became stuck, and was not able to handle any traffic. | prod00274804 |
| 34. | After reverting an unsaved configuration, the HA State remained INIT and was not updated automatically. | prod00272980 |
| 35. | Using WBM, an Invalid EC Key Size (6). error displayed while generating an SSL certificate an RSA key. | prod00273179 |
| 36. | After upgrading to version 32.2.1.0, session logs were not generated. | prod00272743 |
| 37. | Handled CVE 2019-11477, CVE 2019-11478, and CVE 2019-11479 using a Linux Kernel patch. | prod00273353 |
| 38. | Alteon indirectly caused a vulnerability to the DNS cache poisoning attack. | prod00269190 |
| 39. | When idbynum was enabled, there were issues with Revert Apply. | prod00273940 |
| 40. | When enabling an HTTP/2 policy, a panic occurred. | prod00273687 |
| 41. | Using Passive FTP, an RTS session was created instead of a filter session for FTP data traffic. | prod00272718 |
| 42. | When Alteon sent syslog messages, a panic occurred. | prod00272887 |
| 43. | A MAC flap on Layer 2 occurred when the DUT was connected on one port and the server was connected on a different port. | prod00273062 |
| 44. | Using APSolute Vision, importing a certificate in Alteon did not work with the ADC + Certificate Administrator role. | prod00274709 |
| 45. | When VLAN 1 was disabled and an Apply was done for any config change, the ping response to the interface was delayed, causing a timeout. | prod00273596 |
| 46. | Was not able to configure service 111 for TCP and UDP. | prod00272575 |
| 47. | IEEE 802.3 standard protocol packets (such as STP packets that run over LLC) sometimes were incorrectly classified as packets with a length error by the Fortville MAC. The CRC was not stripped from such packets, and the RLEC counter was incremented. These packets later caused problems when they were transmitted with the unstripped CRC to other entities in the network. | prod00272402 |
| 48. | Alteon was rebooted unexpectedly by Watchdog. | prod00273479 |

| Item | Description | Bug ID |
|------|--|--------------|
| 49. | A packet capture's TCP stream displayed corrupted data due to TSO allocated buffers. | prod00269186 |
| 50. | When the DNS virtual service protocol is UDP Stateless, HTTP and FTP services failed for IPv6 traffic. | prod00273832 |
| 51. | Using WBM, when VIPs were added to/removed from the HA service list, Alteon panicked. | prod00273658 |
| 52. | After Applying configuration changes, VIPs stopped responding. | prod00272576 |
| 53. | Using WBM, there was an HTTP modification rule configuration issue. | prod00273396 |
| 54. | Using WBM, the Maximum Session Number was not changed after adding a CU. It only was changed in CLI. | prod00274757 |
| 55. | After upgrading to version 32.2.1, the MP CPU utilization spiked. | prod00273889 |
| 56. | In a GSLB with VRRP/HA environment, after applying a configuration, the DSSP health checks failed. | prod00273181 |
| 57. | A configurational change to shutdown did not display correctly under /cfg/slb/group x/cur. | prod00272733 |

Fixed in 32.2.2.50

| Item | Description | Bug ID |
|------|---|--------------|
| 1. | SNMP data in the polling interface details incorrectly displayed the interface type | prod00273296 |
| 2. | Using WBM, when VIPs were added to/removed from the HA service list, a panic occurred. | prod00273460 |
| 3. | When the DNS virtual service protocol was UDP stateless, the HTTP and FTP services failed for IPv6 traffic. | prod00273709 |
| 4. | When reverting an unsaved configuration, the HA state remained INIT did not updated automatically. | prod00272958 |
| 5. | In a GSLB environment, Alteon did not resolve a DNS query even though the remote real servers were UP. | prod00272749 |
| 6. | In an Alteon VA environment, the /stats/slb/clear command did not clear all filter statistics. | prod00272788 |
| 7. | Using /cfg/slb/group x/cur, configurationally changing to "shutdown" did not displayed correctly. | prod00272696 |
| 8. | Using config sync, disabling virtual synchronization removed virtual servers from the backup device. | prod00273176 |

| Item | Description | Bug ID |
|------|--|--------------|
| 9. | Using WBM, generating a certificate resulted in the following error: Invalid EC Key Size (6) | prod00272033 |
| 10. | After upgrading to version 32.2.1.0, the MP CPU spiked. | prod00273206 |
| 11. | After upgrading to version 32.2.1.0, session logs were not generated. | prod00272627 |
| 12. | After resetting the admin password from the console, the new admin password displayed in clear text in diff flash. | prod00272628 |
| 13. | When VLAN 1 was disabled and applied for any configuration change, the ping response to the interface was delayed, causing a timeout. | prod00273436 |
| 14. | SIP INVITE and fragmented packets were not forwarded to real servers | prod00272668 |
| 15. | When a Submit occurred via QAS, the rport service was overwritten. | prod00272755 |
| 16. | Using LinkProof NG, when uploading or downloading WANlink limits that are configured to greater than 455 Mbps, WANlink bandwidth utilization produced incorrect statistics. | prod00273015 |
| 17. | The site selection rules displayed the MIB name instead of the Rule ID. | prod00272850 |
| 18. | Using Passive FTP, the RTS session was created instead of the filter session for FTP data traffic. | prod00272727 |
| 19. | Using WBM, when changing "DNS Responder VIP" between dis to ena, Alteon did not update the flags that are used to identify the configuration change. Because of this, Alteon did not recognize the configuration change during apply, causing a problem. | prod00273456 |
| 20. | When the DUT connected to one port and the server was connected to a different port, a MAC flap occurred on Layer 2. | prod00273068 |
| 21. | Alteon rebooted with a power cycle. | prod00272624 |
| 22. | In a GSLB with VRRP/High Availability environment, after applying a configuration, DSSP health checks failed. | prod00273182 |
| 23. | Was not able to configure service 111 for TCP and UDP. | prod00272610 |
| 24. | GSLB DNS client network rules real server selection window is too small. | prod00272847 |
| 25. | Alteon rebooted unexpectedly by Watchdog | prod00273482 |
| 26. | When enabling an HTTP/2 policy, a panic occurred. | prod00273787 |

| Item | Description | Bug ID |
|------|---|--------------|
| 27. | When applying configuration changes, the VIP stopped responding. | prod00272780 |
| 28. | Sending syslog messages caused a panic. | prod00272884 |
| 29. | Using WBM, the HTTP modification rule configuration had problems. | prod00273397 |
| 30. | When a lower BFD rx-int was configured, when there was a change of the session table type between ABT and PBT, the BFD session went down, causing the BGP session to be deleted. This issue was addressed by yielding control to the SP for sending BFD packets | prod00272646 |

Fixed in 32.2.2.0

| Item | Description | Bug ID |
|------|---|--------------|
| 1. | Using APSolute Vision, if you configured a virtual server, the Sync button to synchronize the configuration with the backup virtual LB was grayed out. | DE33418 |
| 2. | On a 6024 platform with 128GB RAM, In an environment that uses jumbo frames (with /cfg/l2/mtu set to greater than 1500), the config sync send operation fails when all the jumbo packets are consumed due to an SNMP memory leak. | prod00273909 |
| 3. | Alteon sends multiple requests to the RADIUS server for one login to WBM. | prod00270429 |
| 4. | Tunnels displayed automatically under the "Default Web Application" menu without an option to remove them. | prod00271288 |
| 5. | Alteon did not display the ICAP notification page to the client browser. | prod00270816 |
| 6. | Updated the online help for IPv6 local networks to "rem6 <Local Network v6 Address entry index>" / "rem <Local Network v4 Address entry index>" . | prod00270457 |
| 7. | After applying ab IPinIP tunnel configuration on a DSR service, an error was issued. | prod00269596 |
| 8. | In an AppWall in Alteon environment, the generated syslog had missing values. | prod00271339 |
| 9. | Using WBM or SNMP, when a GSLB network prefix was configured, the IPv6 mask configuration did not get set properly. This caused improper matching of the GSLB network during DNS request processing. | prod00269737 |

| Item | Description | Bug ID |
|------|--|--------------|
| 10. | The VRRP status remained as Active-Active even if related VRs were erased, when that status should have changed to Active-Standby. | prod00271605 |
| 11. | In an AppWall in Alteon environment, the download failed when the secwa was applied in inline mode on the Alteon VIP when the file size was more than 50Mb. | prod00270992 |
| 12. | A gmetric network does not work with the IPv6 nwclass having an element with a prefix 96 or less. | prod00269710 |
| 13. | Using WBM, default group 1 displayed without any changes made to it, while in CLI the group did not display unless changes were made to it. | prod00271477 |
| 14. | Using WBM, could not assign a VLAN to an interface. | prod00271061 |
| 15. | Using WBM, Alteon panicked when generating techdata. | prod00271962 |
| 16. | Using the CLI, creating client network rules with IPv6 was limited to 32 characters. | prod00270733 |
| 17. | In AppWall, after changing the publishing rules, the configuration was deleted when synching from the master to the backup, | prod00271685 |
| 18. | When RTSRCMAC is enabled and the gateway is disabled, Alteon does not return UDP/SIP virtual traffic to the client. | prod00270859 |
| 19. | Using WBM, an AppShape++ script with the incorrect syntax was allowed, which corrupted the configuration upon save. | prod00270537 |
| 20. | The current and total session counters were not accurate in server group statistics. | prod00271249 |
| 21. | In an AppWall in Alteon environment, activity tracking displayed 10.10.10.10 as the source ID in the security log for IPv6 clients. | prod00269417 |
| 22. | AppWall in Alteon security logs were not populated. | prod00272032 |
| 23. | When trying to collect the tech support file from the device, the device status changed from Master to Standby due to an "MP keepaliveFailure detected in SP" error. | prod00271714 |
| 24. | After changing all of the IP addresses of a single network to different IP address, non-existing MACs remained in ARP table. | prod00272260 |

| Item | Description | Bug ID |
|------|--|--------------|
| 25. | <p>In an SLB environment, when the primary group became operational, the backup group's session table was removed.</p> <p>As part of the fix, the session entry is removed if the real server is not enabled under the group. In this scenario, this condition failed because the session's real server that is backed up is removed from the group when the primary real server becomes operational. This leads to removal of the backup real server's session entry when the primary real server comes up.</p> | prod00270615 |
| 26. | The Alteon secondary device was inaccessible via the mgmt port and console. | prod00271312 |
| 27. | If a bandwidth management contract is associated to a traffic pattern and the TOS overwrite feature is enabled, a packet capture did not reflect the DSCP field modification. | prod00270090 |
| 28. | After a vADC rebooted from a panic, that part of the configuration was lost. | prod00271650 |
| 29. | <p>The STG-VLAN configuration failed to apply on reboot because the number of parameters exceeded 64.</p> <p>Fix: After upgrade, perform the configuration and save, then reboot.</p> | prod00271341 |
| 30. | Using WBM, the user lost access to a vADC. | prod00270783 |
| 31. | After a failover, the VRRP backup sent advertisements. | prod00271957 |
| 32. | When a user tried to configure a group "metric response" with the dynamic weight SNMP health check, a warning message was issued. | prod00269082 |
| 33. | A standalone device rebooted with a software panic. | prod00271231 |
| 34. | The binary health check failed with a timeout even through the checked server replied with unexpected value. | prod00271037 |
| 35. | After an interface related VLAN was deleted and then added back, the Layer 3 interface stayed down. | prod00272240 |
| 36. | After creating a Notify Tag from Configuration > System > SNMP > SNMPv3 > Notify Tags, opening the new Notify Tag displayed the content of a different Notify Tag. | prod00269989 |
| 37. | After rebooting the device, with configuration changes in diff, received errors after Apply. | prod00270495 |

| Item | Description | Bug ID |
|------|---|--------------|
| 38. | <p>After upgrading from version 30.5.8.0 to 31.0.9.0, vADC-1 booted with configuration in diff. The configuration could be applied but generated the following error:</p> <p>ERROR mgmt: Error: Save not done. Application services engine is not synchronized with the current configuration.</p> | prod00271393 |
| 39. | The EDNS+Source network-based name resolution failed for certain source addresses. The GSLB query failed when it contained the EDNS extension with the client subnet address, which fails to match the network class configuration. | prod00270959 |
| 40. | <p>A real server under /info/slb/group displayed in the BLOCKED state. When a group was not attached to any service or filter, no svc-pool entry was created for it. As a result, the wrong group was displayed with the /info/slb/group command.</p> <p>Fix: If at least one group is configured for the real server with no svc-entry corresponding to the group, the svc-pool entry is preserved with the default health check and group ID. In addition, if there is not any svc-entry corresponding to the group that is being queried, the default health check for the real server is displayed.</p> | prod00272042 |
| 41. | When an LDAP bind request packet length exceeded 127 (for contents greater than 116, including LDAP markers), multi-byte representation was not used, which caused Alteon to not generate the advanced health check type LDAP as expected. | prod00269895 |
| 42. | After running the /c/slb/cur command, if the configuration contained any AppShape++ script associated to a filter, Alteon panicked. | prod00270299 |
| 43. | XML fragmented files over SIP were not forward to real servers. As a fix, the maximum dechunk datagram was resized from 8200 to 16400. | prod00270949 |
| 44. | When the filter action was "nat", the client NAT IP address options were missing from the Dynamic NAT tab | prod00272364 |
| 45. | When the LDAPS module received the response from the server, the timestamp was not updated properly. As a result, the response time was calculated incorrectly, resulting a very long response time. | prod00270545 |

| Item | Description | Bug ID |
|------|---|--------------|
| 46. | <p>PIP count validations for limiting the number of ARP/NBR entries in non-HA mode were not available. This allowed the user to add more than the maximum allowed entries in non-HA mode, and when the user switched to HA mode, the validations issued errors.</p> <p>As a fix, added the same set of validations for non-HA mode. In addition, maximum PIPs are now 2K and the number of ARP and NBR entries are 2K each.</p> | prod00268389 |
| 47. | The Info/slb/group command displayed the incorrect VLAN for unavailable servers. | prod00270185 |
| 48. | If the link was down when the STG was off and "blockport" was enabled, the incorrect port state was assigned to a LAG member port after reboot. | prod00271622 |
| 49. | On a vADC and standalone, entering the command blkport disable caused a panic. | prod00270659 |
| 50. | When running a vDirect script in Alteon, received a timeout. | prod00270588 |
| 51. | In an ADC-VX environment, when fetching the SSL chip status reboot, a panic occurred. | prod00271318 |
| 52. | WBM did not display the virtual service configuration after synchronization. | prod00270171 |
| 53. | After enabling compression, file download failed. | prod00272082 |
| 54. | Using the command /info/slb/sess/dump, the configuration sync fails while dumping huge SLB sessions onto the console. | prod00271269 |
| 55. | Using WBM, when adding interfaces to a VM, Flow Continuation Ingress ports could not be validated. | prod00265360 |
| 56. | In a filter configuration, the default value of "matchdev" differed between WBM and CLI. | prod00270627 |
| 57. | Was unable to install a legacy compression license on top of NG/NG+. | prod00271478 |
| 58. | After disabling the Layer 3 filter, the health check started failing. | prod00269199 |
| 59. | <p>In a hot-standby VRRP environment, when port 1 was disabled on the backup, Alteon attempted to disable the port as part of the hot standby algorithm irrespective of the current status of port. The functions called during the flow used ND APIs and they resulted in high MP CPU.</p> <p>As part of the fix, disabling the port again is prevented if the port is already in the disabled state.</p> | prod00271916 |

| Item | Description | Bug ID |
|------|--|--------------|
| 60. | In an ADC-VX environment, the WBM, SSH, and console were not available until device was rebooted. | prod00271285 |
| 61. | Out-of-order TCPv6 segments from the client to the MP caused a panic. | prod00270532 |
| 62. | Services went down on the master ACOD device. In the syslog there was no indication of failed real servers and there was a significant inconsistency between the syslogs/console logs and tsdump info. | prod00270096 |
| 63. | Using WBM, the dashboard displayed the wrong throughput for a virtual server, even though there was no traffic for the virtual server. | prod00270112 |
| 64. | When configuring a health check ID and real server ID together with a length greater than 35, due to a bug in the health check script a panic occurred. | prod00271593 |
| 65. | In a BGP environment, when network class changes were applied, the device panicked. | prod00270719 |
| 66. | The "new cached bytes" field in the statistics for the acceleration engine cache mechanism, displayed the wrong value. | prod00271429 |
| 67. | An additional "\" character was inserted in the body of the HTTP Advanced health check | DE47480 |
| 68. | With Reverse enabled in a filter and vmasport enabled, the return traffic did not undergo server processing/NATing, causing the server packets to display on the client network. | prod00272714 |

Fixed in 32.2.1.0

| Item | Description | Bug ID |
|------|--|--------------|
| 1. | In an SLB environment with primary and standby devices, after syncing the configuration from primary to standby, the virtual service configuration did not display in the WBM of the standby device. | prod00270171 |
| 2. | In SLB monitoring using the APIs, the status of a real server that is part of a content rule and its health check failure reason could not be fetched using the API SlbStatEnhContRuleActionGroupEntry. | prod00270081 |

| Item | Description | Bug ID |
|------|---|--------------|
| 3. | <p>In an SLB environment, although only 29 real servers were configured, when trying to configure a real server (with duplicate), the following error message was issued:</p> <pre>The maximum of 1023 Real Servers has been reached. To add new real server, first delete any unused Real Servers and apply.</pre> | prod00269765 |
| 4. | In a virtualization environment, during configuration synchronization, the MP CPU of the vADC stayed at more than 80% for a long time. | prod00269753 |
| 5. | In an SLB environment with cookie persistent mode and forceproxy, the svclstconns metric always selected the same server as a collection of active connections, causing unequal load distribution for the service | prod00269642 |
| 6. | In an SLB environment with force proxy enabled, when the server group names exceeded 50 characters and first 50 characters were the same, after upgrading, Alteon stopped processing the traffic. | prod00269640 |
| 7. | When RADIUS authentication was enabled and a user logged in using SSH (probably using scripts), a vADC panic occurred due to NULL memory access. | prod00269220 |
| 8. | <p>In an AppWall integrated with Alteon environment, when submitting a SECWA configuration, AppWall issued the following error:</p> <pre>You are not authorized to edit this Web Application.</pre> | prod00269188 |
| 9. | <p>In an AppWall integrated with Alteon environment, you could enable SSL for the authsrv (/c/security/websec/authsrv/ldap 1/ssl ena) even though SSL will not be used.</p> <p>As a fix, this command has been removed the from CLI.</p> | prod00269183 |
| 10. | Irrespective of the LACP port configurations, Alteon with STP off did not pass transparently BPDU from Cisco Nexus with MSTP. | prod00269094 |
| 11. | In an SSH environment, downloading an image using SCP was slow compared to downloading through FTP. | prod00269084 |
| 12. | In an SLB environment with DNS Responder VIPs, with mixed delegation/non-delegation traffic, a panic occurred. | prod00269062 |
| 13. | In an SLB environment with forceproxy, after configuration sync (with associated real server removed) from the master to the backup device, the device rebooted. | prod00269015 |

| Item | Description | Bug ID |
|------|--|--------------|
| 14. | Using CLI, an incorrect description was displayed for the command /c/l3/ha/service/dis | prod00268974 |
| 15. | In a monitoring environment, a panic occurred when continuously polling for a set of OIDs (slbStatLinkpfIpTable, pip6CurCfgTable, pip6NewCfgTable, pip6CurCfgPortTable, pip6NewCfgPortTable, pip6CurCfgVlanTable, pip6NewCfgVlanTable) with GET REQUESTs. | prod00268928 |
| 16. | When a data port was used for NTP, and the packets were received from non-configured NTP servers, the syslog message NTP illegal packet length for the dropped NTP packets was issued. | prod00268904 |
| 17. | In a VRRP environment, changes to a VR's priority during migration failover ended with an apply lock and high MP memory usage. | prod00268858 |
| 18. | In an SLB environment, when the HTTP2 policy was enabled with a group of one real server and one backup real server configured, when the active real server went down, traffic was not shifted to the real server configured as the backup, and the client received a 503 error. | prod00268741 |
| 19. | Using CLI, In an SLB monitoring environment, in the virtual server statistics the displayed highest sessions were greater than the total sessions. | prod00268723 |
| 20. | An HTTP head host modification rule could be changed or modified using CLI but not using WBM | prod00268688 |
| 21. | Using WBM, when configuring an SSL service, the certificate and the group were set and configured even when the user chose the 'any' option. This caused the newly configured APP to function slowly. | prod00268685 |
| 22. | In an SLB environment, when a FQDN real server was changed, Alteon was not updated for more than a half an hour after the change, and it changed only after the FQDN real server was disabled and then enabled. | prod00268654 |
| 23. | In an HA environment with the same network class associated to a SmartNAT and also a real server, the ARP for a few of the PIPs in the network class range were not answered. | prod00268645 |

| Item | Description | Bug ID |
|------|--|--------------|
| 24. | In an HA with SLB environment, even though the PIP Network Class Range was enabled to receive GARP (/c/13/ha/nwclgarp ena), the GARP was not sent for all IP addresses from the proxy network class range. | prod00268505 |
| 25. | The SNMP CLI configuration commands /c/sys/ssnmp/rcomm and /c/sys/ssnmp/wcomm in accepted a NULL string, resulting in errors when adding or removing real servers from a group using WBM. | prod00268503 |
| 26. | In an environment with health checks, when the SNMP health check was configured, the weight displayed but it did not display when the SNMP health check was part of a LOGEXP. | prod00268455 |
| 27. | In an SLB environment, when a content rule group contained a remote real server with the DSSP health check, an inconsistent DSSP health check status displayed. Note: A Config Apply action is now not allowed if the content rule group contains a remote real server with a DSSP health check and the DSSP health check is not part of the default service group. | prod00268431 |
| 28. | In a virtualization environment on a vADC, the SP memory displayed as HIGH all of the time, while the device had no traffic and no SLB configuration. | prod00268394 |
| 29. | In an SLB environment, a filter configured with the protocol as "50" was not restored after rebooting the device. | prod00268390 |
| 30. | In an SLB environment, when the real service port (the rport of a virtual service) was configured with a value less than 5 (except for multiple rports/IP addresses service scenarios), the traffic on these rports failed. For the fix, a validation has been added to allow rport 0-multirport or 1-ipservice or 5-65534. | prod00268324 |
| 31. | In an SLB environment with filter sessions, when the primary became available, even though backup clear (clrbkp) was enabled, the sessions that were bound to the backup server were not cleared on the filter. | prod00268272 |
| 32. | When the FastView license expired, Alteon also lost the compression license. | prod00268238 |

| Item | Description | Bug ID |
|------|---|--------------|
| 33. | When the number of basic health check components used in the logical expression-based health check object was changed, such that the new expression had fewer objects than the old expression, a software panic occurred. | prod00268236 |
| 34. | When a client connected to Alteon using SSH with RADIUS authentication, a panic occurred. | prod00268120 |
| 35. | Using WBM, HA Real Server Tracking could not be configured. | prod00268053 |
| 36. | In an HA environment with an SLB configuration, configuration of the backup real server and/or backup group was not synced to the peer device. | prod00268048 |
| 37. | In a virtualization environment, when a vADC was deleted and when a new vADC was created with same vADC number, the old configuration was restored in the newly created vADC. | prod00268003 |
| 38. | When Alteon sent a zero byte just before the EOM terminating sequence of 0x0d0a2e0d0a (observed in the capture file) and the server did not answer with anything, Alteon did not receive a 250 response from the server after sending the e-mail content (syslog messages). | prod00268002 |
| 39. | When OCSP used DNS over management, after 64K DNS requests, failures occurred, causing Alteon to close the connection during SSL handshake. | prod00267963 |
| 40. | In an SLB environment with forceproxy and an ICAP and SSL Inspection configuration, if the ICAP server terminated or did not respond, a panic occurred. | prod00267959 |
| 41. | In an Alteon Integrated with WAF environment, the Parameter name within the parameters filter did not match the REGEX. | prod00267953 |
| 42. | In an SLB filters environment, the IPv6 redirect filter used a proxy port to forward packets to the server, but the IPv4 redirect filter did not. | prod00267951 |
| 43. | In an SLB environment, when operationally disabling or enabling a real server in a server group, a syslog message indicating the action was not generated. | prod00267949 |
| 44. | In an SLB environment with forceproxy configured and with the HTTP2 Gateway implemented caused high SP memory usage. | prod00267931 |
| 45. | Using WBM, in the Monitoring > System > Maintenance pane, when the resolution changed, the Export button for techdata was located in the wrong position. | prod00267870 |

| Item | Description | Bug ID |
|------|---|--------------|
| 46. | In an OSPF environment, Alteon was unable to update the peer with any change to the OSPF parameter. | prod00267852 |
| 47. | Using WBM, even though a user logged in with the "admin" user, the user could not operationally disable a real server. | prod00267832 |
| 48. | In an SSL environment with a certificate repository, after manually importing all of the keys (clear text RSA keys) and certificates to both the master and backup devices, when trying to associate the certificates to their corresponding VIPs, configuration sync failed, an error that a key was missing on the backup device displayed on the master device. | prod00267781 |
| 49. | When Alteon was managed with a "notacacs" and "noradius" login, the following issues occurred: <ul style="list-style-type: none"> When backdoor users logged in, permissions to change the admin password were based on the previous user login The who command displayed nothing or displayed the previous user's login name When logging in with the "noradius" user with the admin password, the user could not change the admin password | prod00267749 |
| 50. | In an HA environment, when a proxy was configured for a filter was same as a floating IP address, the filter's proxy entries were added to the ARP table of the backup with the device MAC address without checking the HA state, causing the backup to reply to ARP queries. | prod00267746 |
| 51. | In an HA environment, the filter proxy was added to the ARP table with the device MAC address instead of the HA MAC address, causing Alteon to not forward dynamic NATed DNS responses to the internal DNS server. | prod00267723 |
| 52. | In an SSH environment, when the export/import of configuration operations were performed using gtcfg or ptcfg, SSH sessions became permanently stuck. | prod00267716 |
| 53. | Using APSolute Vision, when accessing the <i>High Availability</i> tab, the following configuration error was issued: 404 Not Found: REST API lookup failed | prod00267695 |
| 54. | In an HA environment, even though the configurations were the same on both the active and standby devices, a warning message related to an HA configuration mismatch was issued. | prod00267681 |

| Item | Description | Bug ID |
|------|--|--------------|
| 55. | In a BGP environment, when deny route redistribution was disabled for a BGP peer, although the BGP peer went down and came back up, Alteon stopped sending advertisements. | prod00267678 |
| 56. | In a virtualization environment, a vADC was accessible over HTTPS, even though HTTPS access was disabled in the configuration. | prod00267642 |
| 57. | Even though access on a device's management port was restricted using an access-list (/cfg/sys/access/mgmt/add), it did not work properly. | prod00267587 |
| 58. | <p>When services were moved from the master node to the backup node, no SNMP traps were sent to the Monitoring server.</p> <p>Note: These traps were omitted when implementing the new feature "Extended HA".</p> <p>Traps, syslog messages, and log messages have been updated, extended, or replaced with new messages.</p> | prod00267571 |
| 59. | Using WBM, in an SLB environment, when configuring a virtual service in the Content Rule pane, an invalid URI was accepted for the redirect URI configuration, while the CLI displayed an error message for that invalid URI. | prod00267552 |
| 60. | Using WBM, while monitoring the servers and being logged in as a real server operator, when trying to disable the server operational status through Application Delivery > Server Resources > Real Servers, the status of that real server did not change. | prod00267516 |
| 61. | Using WBM, when trying to set the group real server status to connection shutdown, its status kept displaying as enabled. | prod00267515 |
| 62. | When Alteon received an IPv6 address with a full length address (more than 32 characters including colons – for example, 2101:2101:2100:2100:2101:2100:2100:2101) and processed the IPv6 fragmented packet, a panic occurred. | prod00267493 |
| 63. | In an SLB environment with the group metric svcleastconns and a multi-rport scenario, load distribution to the real server was not proper. | prod00267433 |
| 64. | Using WBM in an SLB environment, the virtual server copy did not work properly, and the copied virtual server had different settings for cookie and server group. | prod00267161 |
| 65. | When performing an Apply of a configuration imported using REST API, an error was issued. | prod00267152 |

| Item | Description | Bug ID |
|------|--|--------------|
| 66. | In an SSL environment, certificates that were set to expire after 100 years displayed as expired. | prod00267056 |
| 67. | Pings to PIP/VPR were blocked. | prod00266689 |
| 68. | Using WBM, users with user roles Operator, L4 Operator, SLB Operator, and SLB Viewer could execute Apply and Save commands for a configuration created by the Administrator. | prod00266672 |
| 69. | Using WBM, you could modify the privacy and authentication settings for SNMP default users. | prod00265974 |
| 70. | Using WBM to create route maps, the following parameters had incorrect values for the route map object: Local preference, Metric, Weight | prod00264251 |

Fixed in 32.2.0.0

| Item | Description | Bug ID |
|------|--|--------------|
| 1. | Using WBM, in the Service Status View pane, the real servers incorrectly displayed. | prod00267276 |
| 2. | Using WBM, in the Service Status View pane, the filter option in the displayed data did not work as expected. | prod00267217 |
| 3. | After upgrading to Alteon version 32.1.x, you needed to log in two times to get access to Alteon VA, ADC-VX, or vADC. | prod00267210 |
| 4. | Using WBM, the complete IPv6 Management IP address did not display. | prod00267208 |
| 5. | In an SLB environment, when real servers were moved from one server group to the other, although the real servers were moved away from a group, the old sessions still remained and did not age out. | prod00267134 |
| 6. | In an SLB environment, after the primary real server went down and the backup real server and group took over, the service became inaccessible. | prod00267089 |
| 7. | Using CLI, on a vADC with a QAT SSL card, in the output from the stats/sp x/mem command, the tech support dump (tsdump) did not contain the QAT driver memory usage. | prod00267071 |
| 8. | Alteon did not handle a specific condition related to FQDN and went into an inconsistent state. | prod00267062 |
| 9. | In a Global SLB environment, when the network gmetric used a network class as the source IP address, the DNS response was incorrect. | prod00267044 |

| Item | Description | Bug ID |
|------|--|--------------|
| 10. | In an inbound link load balancing Smart NAT environment, the Availability metric in the SmartNAT GSLB rule was not processed, causing an improper ISP links order. | prod00267020 |
| 11. | Using WBM, from the <i>Certificate Repository</i> pane, you could not perform a search in the table. | prod00266986 |
| 12. | In a configuration sync environment, after a routine configuration change, the MP CPU reached 100%. | prod00266964 |
| 13. | In an SLB environment, when overlapping IP addresses were defined in a network class configuration with exclude enabled, and when an exclude range was a subset of the other exclude range, the filter defined with this network class fired incorrectly for an excluded IP address, causing the filter to misfire. | prod00266924 |
| 14. | In a Global SLB environment, when the network element was of type subnet, the fromIp was incremented by 1 to skip the network address and the toIp was decremented by 1 to skip the broadcast address, causing a large value for the IP count, and Alteon prevented the subsequent network elements and network classes from being added to the internal tables. This caused a GSLB SIP lookup failure for missing network ranges. | prod00266917 |
| 15. | In an SLB environment, filter processing processed the traffic addressed to the SmartNAT dynamic address/PIP addresses, failing the DNS amplification scan. | prod00266909 |
| 16. | When the NTP server was configured over IPv6, the IPv6 address was not recognized on routing through the management port IPv6 address. | prod00266888 |
| 17. | Using WBM, when deleting a Layer 3 gateway, the gateway entry did not disappear, but a stale entry for the same gateway ID was displayed in the disabled state and with an IP address 0.0.0.0 and VLAN 0. | prod00266880 |
| 18. | In an HA environment, when duplicate IP addresses were configured for DNS responder virtual servers and regular virtual server IP addresses on the master device, configuration sync to the peer device did not work, ending with errors. | prod00266879 |
| 19. | In a management environment, when different management certificates on the master and backup were configured (/c/sys/access/https/cert), configuration sync failed without a meaningful error message. | prod00266876 |

| Item | Description | Bug ID |
|------|--|--------------|
| 20. | In an SLB environment with dynamic address mode with an AppShape++ script (source NAT), Alteon forwarded the traffic to the server with the source MAC address set to the client MAC address instead of the Alteon/HA MAC address. | prod00266869 |
| 21. | Using WBM, in the Certificate Repository Import screen, the correct certificate file was not imported when trying to use the Browse button | prod00266868 |
| 22. | In a Link Load Balancing (LLB) environment, after restoring the backup configuration using <code>get config</code> , the LLB-related configuration (<code>/c/slb/gslb/network x/wangrp WAN-Group-1</code>) was lost. | prod00266817 |
| 23. | Using WBM, configured AppShape++ script did not display. | prod00266779 |
| 24. | When the NTP was set over a data port and the NTP server was down, an incorrect SNMP Trap (Critical Temperature Trap) was sent when the NTP request timed out. | prod00266743 |
| 25. | In an Azure environment, when the RADIUS server was on a different network other than the management network, RADIUS authentication did not work. | prod00266675 |
| 26. | On a Cavium-FIPS platform, the PKCS12 file of the CA-group was encrypted and larger than 16K in some cases and failed to load. | prod00266654 |
| 27. | In an SLB environment, after configuring the real server weight using the CLI command <code>/c/slb/real x/weight</code> , a panic occurred. | prod00266636 |
| 28. | In an SLB environment with an acceleration environment, due to connections being reset, some application outages and traffic failures were observed. | prod00266633 |
| 29. | In an SLB environment, on a real server, due to packet drops in the SPs, TCP latency occurred for health check packets. | prod00266603 |
| 30. | In in Outbound Link Load Balancing environment, the transparent health check to a destination server was sent from an inappropriate port/VLAN (WAN Link). | prod00266602 |
| 31. | While using a REST API call to export the configuration, Alteon ignored the path and name specified in the API request. Alteon generated a name and transferred the file to the root folder of the SCP server instead. | prod00266593 |

| Item | Description | Bug ID |
|------|---|--------------|
| 32. | When importing a key which is not encrypted (plain text), due to minimal passphrase that was set, the import caused all onboarding of HTTPS applications that use non-encrypted certificates to fail. | prod00266573 |
| 33. | <p>In a monitoring environment, invalid TRAP OIDs were sent for the SP CPU Pressure On/Off.</p> <p>Note: The correct MIB OID has been added to the trap.c and GENERIC-TRAP-MIB.MIBs:</p> <p>altSwSpCpuPressureActivatedTrap - 1.3.6.1.4.1.1872.2.5.7.0.214</p> <p>altSwSpCpuPressureDeactivatedTrap - 1.3.6.1.4.1.1872.2.5.7.0.215</p> | prod00266559 |
| 34. | In a VRRP environment with an SLB configuration, the session move operation did not get synchronized to the backup, leading to session mirroring not working, causing statistics discrepancies on the backup devices. | prod00266543 |
| 35. | In an SSL environment, when changing the cipher suite from TLS 1.2 to the User Defined " TLS_ECDHE-RSA-AES128-GCM-SHA256" cipher, the AX configuration was corrupted and the service to which the SSL policy was attached stopped working. | prod00266530 |
| 36. | In an environment with AX configured, the primary and secondary vADCs panicked one after the other. | prod00266525 |
| 37. | In a Layer 7 environment, if the original request did not contain any query, Alteon did not remove the query separator "?" in the redirect URI. | prod00266453 |
| 38. | Using WBM, in the <i>Outbound LLB Rule</i> pane, the IP address/network could not be edited. | prod00266452 |
| 39. | In a virtualization environment, due to vADC management mask settings not considered for locking, when attempting to get access by the management interface to a vADC, access was given to another vADC. | prod00266409 |
| 40. | In a VRRP environment, when health checks failed on the backup, statistics discrepancies (incorrect number of sessions to the real servers) occurred on the backup device. | prod00266339 |
| 41. | In an SLB environment, when there was a change in the virtual server configuration (disable/enable), the session move operation via CLI did not move the session to a different real server. | prod00266338 |

| Item | Description | Bug ID |
|------|--|--------------|
| 42. | When the time zone was set to Asia/Jerusalem (GMT offset +02:00), as the daylight saving setting was not taken into account, Alteon displayed the incorrect time from the month of October. | prod00266305 |
| 43. | In an SLB environment with HA, after the failover, uneven load distribution occurred on the new master device. | prod00266157 |
| 44. | Using WBM, In the certificate repository, when importing an intermediate CA, the size displayed as 0. Note: After the fix, the size is not calculated and is displayed blank. | prod00266154 |
| 45. | In a Cloud environment, when there was a VSAN failure, and when switching to redundant storage from the VMware side caused an I/O failure for a few seconds, the MP was stuck, causing the watcher to trigger the soft reboot and an outage of all Alteon VAs. | prod00266092 |
| 46. | In an SLB environment, when real servers were allocated to multiple virtual services and a Revert Apply was performed, the session table was deleted automatically. | prod00266012 |
| 47. | Using WBM, with the "User" role, configuration sync could be performed even though the "User" account should not be able to do this. | prod00266008 |
| 48. | Using WBM, on an ADC-VX, when attempting to log out of WBM, the device kept the user logged in. | prod00266006 |
| 49. | While running a vDirect script on Alteon devices, it took more than 20 minutes to display the output or the script timed out with no result. | prod00265982 |
| 50. | In an SSL environment, the user was unable to change the ciphers string under the advanced HTTPS health check. | prod00265975 |
| 51. | Using WBM, in the Configuration > Setup > High Availability pane, there was no option to delete VR Group settings. | prod00265973 |
| 52. | Using WBM, in an SLB environment when configuring a virtual service, the cookie configuration changed after making a change to the virtual server even if the user did not modify the persistent binding (pbind) cookie settings. | prod00265867 |
| 53. | Using WBM, when duplicating a real server, sometimes the "ERR json parse failed" message was returned. | prod00265865 |
| 54. | Using WBM, from the health check pane Configuration > Application Delivery > Health Check > add , the Always Perform Health Check field displayed twice. | prod00265861 |

| Item | Description | Bug ID |
|------|--|--------------|
| 55. | Using WBM, you could not set the action as Discard for a virtual server. | prod00265857 |
| 56. | When performing SNMP monitoring on SSL offloading stats (FE/BE), due to a memory corruption, a panic occurred, and the device rebooted a few times. | prod00265843 |
| 57. | In an Alteon integrated AppWall environment, SSL sessions were not created for specific tunnels. | prod00265812 |
| 58. | In a virtualization environment for a vADC, after performing a Revert Apply on an ADC-VX, the admin password changed back to the default password (admin) on the vADC. | prod00265710 |
| 59. | When agTftpCfgFileName was more than 83 characters, exporting the configuration with SCP through the REST API server failed. | prod00265672 |
| 60. | If the data-class entry contained a backslash (\) character and configuration sync was performed, the configuration was not synced correctly. | prod00265617 |
| 61. | In an SLB environment, when the client connected directly but through different VLANs for forward and backward traffic, the SP CPU utilization became high even though the amount of traffic was not increased, causing a degradation. | prod00265558 |
| 62. | In a Global SLB environment, when a configuration Apply was performed during the periodic statistics calculation, when the internal data structures used in GSLB were reset and repopulated, an illegal access occurred, causing a panic. | prod00265544 |
| 63. | When a new virtual server with a service-based proxy address and a corresponding VPR were both configured within the same Apply operation, Alteon did not display the VPR status in the VRRP and the ARP cache. | prod00265538 |
| 64. | In an SLB environment, if the configuration had a disabled virtual server and one of the services of the virtual server had a non-existent AppShape++ script, the configuration could not be saved. | prod00265537 |
| 65. | In a virtualization environment, one of the vADCs hung and panicked. | prod00265451 |
| 66. | In a virtualization environment, when the LACP was configured with 40G ports, during the vADC boot-up frequent gateway health check failures occurred. | prod00265434 |

| Item | Description | Bug ID |
|------|---|--------------|
| 67. | Using WBM, when using the SSL Inspection Wizard, when performing a revert, in certain conditions a REST API 405 error displayed even though the Revert was successful. | prod00265381 |
| 68. | <p>In a virtualization environment, when the vADC IP address/net mask combination was configured incorrectly and failed to add the relevant gateway, disabling and then enabling vADCs caused Linux ifconfig errors, resulting in management connectivity loss for the ADC-VX.</p> <p>Note: This issue was addressed by not allowing invalid gateway settings and ensuring that the ADC-VX and vADC management IP addresses are defined on the same network.</p> | prod00265371 |
| 69. | In an HA environment, during configuration sync, the real server configuration under HA triggers were not synced to the peer correctly. | prod00265322 |
| 70. | In a virtualization environment with HA configured, during upgrade, one of the vADCs hung and panicked. | prod00265317 |
| 71. | In an SLB forceproxy environment with IP service and filters configured, when performing an Apply , Alteon attempted to add a service mapping entry (needed for IP address and Port translation) for a filter, but instead accessed data meant for the virtual service, causing a panic. | prod00265289 |
| 72. | In a BGP environment, you could not import the default gateway alone or any other "range of IP"/"IP" separately. | prod00265280 |
| 73. | On the 6024 platform with 32 GB RAM, the vADC-5 license could not be installed on top of Alteon NG/NG+. | prod00265279 |
| 74. | In an SSL environment, when configured with client-IP, SSL-ID persistency and with SSL-ID traffic, a panic occurred. | prod00265243 |
| 75. | When dumping the FDB entries in the SP using the /maint/debug/spfdb command, only 8K entries were dumped when the Max size of the FDB per SP was actually 16K. | prod00265212 |
| 76. | In an SNMP monitoring environment, when accessing the MIB OID 1.3.6.1.4.1.1872.2.5.4.3.14 corresponding to runtime instances of a health check, a panic occurred. | prod00265181 |
| 77. | <p>Using WBM, when logging in as a TACACS user, the following error message displayed:</p> <pre>mgmt: The language defined at the TACACS server is not recognized. Using global language.</pre> | prod00265166 |

| Item | Description | Bug ID |
|------|---|--------------|
| 78. | In an HA environment with session mirroring enabled after failover, the new master did not mirror sessions to the new backup. | prod00265127 |
| 79. | In an Alteon integrated with AppWall environment, when the Accept-Language header was missing, AppWall responded with a 302-response code. | prod00265072 |
| 80. | If the IDSChain was not working for subsequent fragments or did not forward fragment IP frames that matched the filter, the RADIUS Server communication broke. | prod00265053 |
| 81. | Using WBM, in the Layer 7 Load Balancing Content Class Configuration pane, if the content class string contained a backslash (escape characters), the REGEX text field value displayed incorrectly. | prod00265029 |
| 82. | In a monitoring environment, fetching the Layer 3 Interface statistics using REST API did not work. | prod00264975 |
| 83. | Using CLI, with verbose 1 set, when a health check that was associated to a server group or real server was deleted, a prompt for user input did not display. | prod00264970 |
| 84. | In an HA environment configured with SLB, the mirrored P-session on the backup vADC was bound with the wrong real server group, causing services to get hampered. | prod00264936 |
| 85. | When PIP was configured under a DNS-UDP stateless service, as it is not applicable it was ignored. Note: As a fix, a warning message has been added only in CLI. | prod00264906 |
| 86. | In an HA environment, the backslash ("\") character in the LDAP user name was not synced to the peer device, and WBM did not display them. | prod00264903 |
| 87. | Using WBM, when a real server was deleted from a GSLB network, as these entries could not be reused even after deletion, once all the maximum 128 entries were exhausted, the following error message displayed: Real server precedence table is full | prod00264835 |
| 88. | On 4408 and 5208 platforms, when upgrading from versions earlier than 30.2.8.0 to version 30.2.8.0 or later, and the ports were enabled for management access, this resulted in an inconsistent configuration after the upgrade. | prod00264787 |
| 89. | The image upload on the management port using SCP was slower than using FTP. | prod00264763 |

| Item | Description | Bug ID |
|------|---|--------------|
| 90. | In an AppWall integrated with Alteon environment, for a virtual server that had an AppWall tunnel, Alteon stopped processing traffic. | prod00264676 |
| 91. | In an SLB environment with health checks configured, with an HTTP health check there was no difference in the failure status regardless of the failure reason. If the checked file was removed (404 code), the file required authentication (401 code) or an internal server error (500 code), for all cases the following error displayed: Reason: Server's response is not as expected. | prod00264674 |
| 92. | In an Alteon HA environment, when configuration sync failed with a Global SLB/Link Load Balancing configuration, after the failure the new configuration moved automatically to the current configuration without performing an Apply operation. | prod00264673 |
| 93. | In a DNS environment, Alteon does not include the edns0 client subnet in the DNS response. | prod00264633 |
| 94. | In an SLB environment with AppShape++ scripts, when adding an AppShape++ script to a virtual server without creating the service on that virtual server and performing an Apply , an Apply error did not occur, and any further configuration change on the virtual server and performing Apply , the <code>Pending configuration</code> message always displayed. | prod00264597 |
| 95. | Alteon allowed management access via data ports on IPv6 even though the access was disabled. | prod00264531 |
| 96. | In an HA environment, after synchronizing the configuration from the master device, the health checks for a real server failed/toggled on the backup device. | prod00264498 |
| 97. | Due to a debug tool that was configured for OpenSSL, HTTPS health checks caused 100% CPU usage on the MP, introducing delays in HTTPS health checks. | prod00264468 |
| 98. | When configured a URI under a CDP group with the left parenthesis ("(:) character in the URI and with traffic, a panic occurred | prod00264433 |
| 99. | In an HA environment with SLB configured, after configuration sync, when Alteon attempted to configure the backup real server as a backup group, the backup real servers in the group were removed on the peer device. | prod00264432 |

| Item | Description | Bug ID |
|------|--|--------------|
| 100. | In an IPv6 environment, even though IPv6 local networks were configured, Alteon sent a server response to the default gateway instead of sending it directly to the connected client. As a result, a real server could not be reached from the subnet. | prod00264431 |
| 101. | In an SLB environment, incorrect statistics were displayed while fetching virtual service statistics (via <code>/stats/slb/virt</code>), the statistics for a real server (Current, Highest, Total sessions) displayed as 0, even though the real server handled the connections. | prod00264430 |
| 102. | On an Alteon VA platform, although the new VLANs were defined to contain default ports, after the reboot, the configuration was always pending in the diff operation. | prod00264390 |
| 103. | In a forceproxy SSL environment, internally when MP and AX went out of synchronization, Alteon continued to send an old certificate even after installing a new certificate. | prod00264339 |
| 104. | Using WBM, from the Configuration > Application Delivery > LinkProof > Inbound LLB Rules pane, there were several issues during configuration. | prod00264289 |
| 105. | Using WBM, with SLB monitoring, when a content rule was used with a real port, the session counter displayed incorrectly. | prod00264285 |
| 106. | Using WBM, in an Inbound Link load balancing environment, the NAT address configuration was missing in the Global SLB's client network rule page. | prod00264245 |
| 107. | Using WBM, when attempting to configure HTTP modification for header removal, Alteon forced the user to input the header value. | prod00264244 |
| 108. | Using WBM, in an SSL environment in the Export tab, even though the "certificate and key" option was selected to export, only one Export button displayed. | prod00264233 |
| 109. | In an HA environment with script health checks configured, after deleting/adding/modifying a script and performing configuration sync, there was a discrepancy in the health checks between the master and the backup device. | prod00264172 |
| 110. | In an SLB environment, when a real server with the same IP address was configured for different groups, and each of the groups were configured with the same logical expression health check, Alteon failed to evaluate the logical expression except the group in which the real server came up first. The rest of the real servers remained down in respective groups. | prod00264146 |

| Item | Description | Bug ID |
|------|---|--------------|
| 111. | In an environment with a configuration where the client packet comes into Alteon through one VLAN (ingress) and after server processing, the response packet leaves to the client in another VLAN (egress), duplicate IP FDB entries got created for external IP addresses. | prod00264048 |
| 112. | In an SSL environment with Cavium cards, after upgrading a couple of certificates and performing Apply , a panic occurred. | prod00264047 |
| 113. | In a virtualization environment when ADC-VX rebooted with a panic, the RADIUS secret became corrupt and the RADIUS login failed. | prod00264025 |
| 114. | Using CLI, when executing a non-existing or hidden command with the /maint/pktcap menu, an error was not issued. Note: As a fix, all the hidden commands under /maint/pktcap were removed and cannot be executed. | prod00264010 |
| 115. | In an SLB environment with filter processing enabled, VMAed traffic source MAC learning did not occur, causing traffic to be flooded on all the VLAN ports, causing higher throughput utilization. | prod00264009 |
| 116. | In an SLB environment with multiple rports, when a new real server was created with addports and if it was associated to more than one service, if any of the service health checks was toggled, Alteon forwarded client requests to the server on the service port rather than on the real server's service port (rport = addport of the real server). | prod00263992 |
| 117. | In an SLB environment, when a particular sequence of SLB configuration steps involving a HTTP virtual service and another virtual server along with Apply , the configuration became corrupted. | prod00263986 |
| 118. | In an SLB environment, when a group was configured with one or more real servers (by manual configuration), when deleting or removing real server(s) from the group, the following Apply error displayed: <code>Error: Real server group 100 associated to virtual server 100 service 80 is not defined</code> | prod00263985 |
| 119. | In a virtualization environment, when autosync was enabled on both ADC-VX and vADCs, configuration changes to the definition of the primary vADC from the ADC-VX triggered the sync to loop between the vADCs. | prod00263984 |

| Item | Description | Bug ID |
|------|--|--------------|
| 120. | For the BWM-history-related e-mail, when the SMTP 'To' user was not configured, but when Alteon tried a number of times to send this e-mail, after a while Alteon did not respond to SSH/HTTPs via management. | prod00263983 |
| 121. | Using WBM, when a configuration dump was performed on a FIPS device, the following error displayed: <code>Error: Configuration import/export via HTTP is already running.</code> | prod00263982 |
| 122. | In an SLB environment, you could not configure a virtual server with a different protocol and Alteon returned the following error: <code>Error: Virtual server vl has the same SIP SLB group id as virtual server vl-udp.</code> | prod00263980 |
| 123. | In a virtualization environment with HA, when p-session sync updates were received from the master, the backup attempted to become the master. This was no longer an issue when the p-session sync was configurationally disabled. | prod00263979 |
| 124. | In an AppWall integrated with Alteon environment, when troubleshooting some false-positive "HTTP reply not RFC-compliant" events were issued that indicated that Request Data and Reply Data under Forensics were identical. | prod00263587 |
| 125. | There was a discrepancy between the peak compressions usage command output (/info/swkey) and syslog messages. | prod00261525 |
| 126. | In a SmartNAT environment, the concurrent sessions value of the WAN link server was much larger than the displayed session statistics. | prod00261497 |
| 127. | Due to a kernel issue, Alteon went into ULP mode and could not be accessed via Telnet, SSH, HTTP, or HTTPS while the Management IP address was reachable only over ICMP. | prod00260720 |

AppWall

| Item | Description | Bug ID |
|------|--|---------|
| 1. | Fixed a rare failure in the HTTP parsing process. | DE43435 |
| 2. | Fixed a rare failure in HTTP Response parsing process. | DE43438 |
| 3. | The client IP address was not sent in the security page. | DE42288 |
| 4. | For some types of security violations, the case number shown in the security page was 0. | DE41895 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 5. | When the server response body was in JSON format, the BruteForce security filter failed to block the IP address for a bad login after the IP address reached the threshold limit. | DE44726 |
| 6. | BruteForce security events syslog messages had the wrong event type value: learning instead of security. | DE45524 |
| 7. | Fixed PCI compliance Report data in APSolute Vision in the 6.5.5 section referring to Improper error handling. | DE23276 |
| 8. | Primary LDAP server failure detection and failover to the secondary server did not work under certain conditions. | DE42480 |
| 9. | When a non-authenticated user attempted to access a Web page, the Authentication Gateway redirected the user to the login process and upon successful authentication, redirected it back to the originally requested page. The redirection back to the originally requested page did not preserve the original HTTP request parameters. | DE42479 |
| 10. | Under rare conditions, Alteon stopped processing traffic on a VIP with an Application security policy. | DE42240 |
| 11. | When the Authentication Gateway received requests from an old version of the Internet Explorer browser, AppWall redirected successfully authenticated users to the authentication process. | DE42339 |
| 12. | In Monitor deployment mode and in Alteon OOP mode, both Request and Response data in the security logs for non-RFC-compliant HTTP Reply displayed Response data. | DE40221 |
| 13. | Added a terminating chunk to a 302 chunk encoding reply with an empty body. | DE43566 |
| 14. | Was unable to refine forensic events for SafeReply credit cards. | DE44273 |
| 15. | Login monitoring settings in HTTP custom headers were ignored. | DE43567 |
| 16. | For AppWall running on Alteon version 32.0.1.0, adding a DefensePro the Defense Messaging configuration using port 443 failed. | DE42698 |
| 17. | Fixed issues with AppWall policy synchronization between the master and backup Alteon platforms. | DE44274 DE44670 |
| 18. | A rare failure could occur when an HTTP response could not be properly parsed. | DE44316 |
| 19. | A long JSON value within a query parameter could cause a failure. | DE44890 |

| Item | Description | Bug ID |
|------|--|---------|
| 20. | For the Database Security Filter ignored parameters, the logs displayed the length of parameter name instead of the parameter param value. | DE44869 |
| 21. | Fixed the "Server Name" field value in the Security logs for AppWall running on Alteon. | DE45098 |
| 22. | Fixed a possible failure in AppWall once applying a policy change. | DE34945 |
| 23. | REGEX support was added for both. | DE44273 |
| 24. | API calls for NTP servers sometimes were not be successful. | DE41308 |
| 25. | The Database.kcf file was not replaced during the upgrade process to version 7.5.8. | DE42077 |
| 26. | The ptcfg command did not work properly in Alteon. A "Failed to create AW configuration File" message was shown. | DE44559 |

Fixed in 32.1.0.0

Version 32.1.0.0 includes all field bugs available in version 31.0.6.0.

| Item | Description | Bug ID |
|------|--|--------------|
| 1. | Using the CLI, when executing the command <code>/stat/spx/allcpu</code> , the SP CPU statistics that displayed was 0%. | prod00263872 |
| 2. | In an SLB environment with ICAP messages chunked, due to parser issues in Alteon, a panic occurred. | prod00263781 |
| 3. | Using WBM, when creating a new HTTP or HTTPS service, Alteon added an extra command for FTP for the service. | prod00263714 |
| 4. | In an SLB environment, when enabling an SNMP health check for a group with the roundrobin metric, a panic occurred. | prod00263635 |
| 5. | In a Geo Proximity environment, a software upgrade caused an invalid GEO configuration, which led to an outage. | prod00263469 |
| 6. | In an SLB Filter environment with dbind forceproxy, dport configured with a range and rtsrccmac enabled did not handle the return traffic for port range except the starting port. For example, for dport range 8080-8443, traffic worked only for 8080 but not the other ports in the range. | prod00263325 |
| 7. | In an SLB environment, when the Script health check was configured with nonat for a virtual service, the incorrect source IP address was used by Alteon. | prod00263231 |

| Item | Description | Bug ID |
|------|---|--------------|
| 8. | In a VRRP active-standby configuration, when configuration sync was performed, though the corresponding virtual service was UP, the virtual router (VSR) went into the INIT state. | prod00263222 |
| 9. | In an SLB environment with FQDN servers configured: <ul style="list-style-type: none"> The DNS response was received during a Revert Apply or configuration sync, causing a problem. When a Revert Apply or configuration sync was performed during service, the DNS response caused a problem. | prod00263196 |
| 10. | In a virtualization environment on an ADC-VX platform, with vadcadv enabled, when an upgrade was performed from versions earlier than 30.5.3.0/31.0.3.0 to version 32.x, the configuration appeared in diff after reboot. | prod00263131 |
| 11. | Using WBM, in the Monitoring > LinkProof > WAN Links > Per WAN Link IP/ID and Monitoring > LinkProof > WAN Link Groups pane, the statistics did not display correctly. | prod00263121 |
| 12. | In the <i>Monitoring</i> perspective, sometimes empty e-mails were randomly generated. | prod00263061 |
| 13. | In an SLB environment with rtscmac enabled, the source MAC address of a virtual server would change during the same session, causing packets to be blocked by ISP. | prod00263043 |
| 14. | Using WBM, in the Configuration > Application Delivery > SSL > Certificate Repository > Intermediate Certificate pane, the key type of the intermediate certificate was displayed as unknown. | prod00262965 |
| 15. | In an SLB environment with IPv4 virtual servers and an IPv6 real server, when using IP version conversion and some SLB related-configuration changes were made, misleading syslog messages were issued. | prod00262937 |
| 16. | When upgrading an ADC-VX platform, Alteon became stuck in a loop during the upgrade and experienced a panic, requiring a hard reset. | prod00262927 |
| 17. | In a Layer 7 environment, the redirection URI under Content Classes took the variable query \$QUERY keyword only after the custom queries. | prod00262866 |
| 18. | In an SLB environment with SSL offload, and with forceproxy enabled and rtscmac enabled, and with a filter enabled on the server port, when the server packets were dropped in the SP after server processing, SSL offloading did not work properly. | prod00262841 |

| Item | Description | Bug ID |
|------|--|--------------|
| 19. | Using CLI in an SLB Monitoring environment, the octet count displayed by the virtual server statistics command <code>/stats/slb/virt x</code> was incorrect. | prod00262825 |
| 20. | Alteon failed to import encrypted private keys that had a long password (> 40 characters). | prod00262772 |
| 21. | In an SLB SIP environment with AppShape++ scripts, a SIP parser issue occurred. | prod00262760 |
| 22. | On an Alteon 5208 S platform, depressing the PWR button for a few seconds did not perform a graceful shutdown of the platform. | prod00262716 |
| 23. | In an SLB monitoring environment with names configured for real servers, when displaying the real server group statistics with the CLI command <code>/stats/slb/group</code> , the real server name was listed instead of the IP address. The fix was to change the heading to "IP Address/Name". The real server name displays if it is configured. Otherwise, the IP address displays. This also applies to the commands <code>/stats/slb/virt</code> and <code>/stats/slb/sp x/virt</code> . | prod00262715 |
| 24. | Using WBM in an SLB environment, you could not configure POP3 over SSL (TCP port 995). | prod00262692 |
| 25. | After disabling the default user, the command <code>/cfg/sys/access/user</code> did not display the correct value. | prod00262676 |
| 26. | In an SLB environment with filters, even though <code>rtsrcmac</code> (Return to Source MAC) was enabled for a filter, ICMP reply packets corresponding to the filter session were routed to the VLAN gateway instead of the client port. | prod00262649 |
| 27. | Using WBM in an SLB environment, when a virtual router and Proxy IP address under a virtual server were the same, the following error displayed: <code>The IP Address of Virtual Router 2 conflicts with the Client NAT (PIP) IP address</code> | prod00262620 |
| 28. | During a Nessus security scan on Alteon, due to opening and closing SSH connections frequently, a panic occurred. | prod00262619 |
| 29. | Using WBM in an SSL environment, you could not generate a CSR. | prod00262589 |
| 30. | Using the CLI, the command <code>/info/l3/ha</code> output information was misleading (it displayed VRRP information). | prod00262578 |

| Item | Description | Bug ID |
|------|--|--------------|
| 31. | In an SLB environment with an IP service configured with the svcleast metric, traffic was distributed to the same server, leading to uneven load balancing of the traffic. | prod00262568 |
| 32. | In an SLB environment with content classes configured, when selecting a different group's real server per the content class, rather than a group-real server being configured on the virtual service, the front-end session abruptly aged out/terminated, causing service issues. | prod00262567 |
| 33. | When logged in with a backdoor-enabled user and with RADIUS enabled, after running the <code>/oper/passwd</code> command to change the user's password, the displayed username was incorrect, the syslog message was generated was with incorrect username, and the Who command displayed the incorrect username. | prod00262566 |
| 34. | In an environment with a slower client (LG K220) and a faster server, after enabling HTTP2, high SP CPU usage occurred. | prod00262565 |
| 35. | Using WBM, in a DNS Proxy configuration, you could not roll back the default group configuration to 'none'. | prod00262545 |
| 36. | After using the CLI command <code>/info/transceiver</code> , Alteon either rebooted unexpectedly or Alteon's traffic was stuck for about 13-15 seconds. | prod00262540 |
| 37. | Due to an ND issue, a panic occurred and caused a reboot. | prod00262521 |
| 38. | Due to an unauthorized Rx queue disable mode of I210 MACs, Alteon dropped some packets. | prod00262519 |
| 39. | Using WBM in an SLB SSL environment, attempting to create a new authentication policy also added the passinfo default configuration, causing the Apply to fail. | prod00262518 |
| 40. | Using WBM, when generating a server certificate with SHA256, the certificate was instead generated with SHA1. | prod00262456 |
| 41. | On platforms that do not have QAT, due to irrelevant memory consumption and that memory being set to debug, when new management certificates were configured or created and a configuration sync was performed, a panic occurred. | prod00262436 |
| 42. | Using WBM, in the Monitoring > Application Delivery > Global Traffic Redirection > Remote Real Virtual Servers pane, the titles of the table were not displayed in human readable format. | prod00262436 |
| 43. | Export of applogs using SCP server with the hostname as the destination failed, but with an IP address as the destination worked. | prod00262426 |

| Item | Description | Bug ID |
|------|--|--------------|
| 44. | Using APSolute Vision, the Generate and Export buttons on the Monitoring > System > Maintenance pane were misplaced. | prod00262402 |
| 45. | When the gateway was unreachable, and even though Alteon had no interface that was alive interface, Alteon delayed in recognizing a gateway health check failure. | prod00262350 |
| 46. | In an SLB environment, when a Script health check was part of a LOGEXP, a different number of health checks packets were sent out per interval for the different health checks combined in the LOGEXP health check. | prod00262279 |
| 47. | In an SLB environment, even though the servers were up, Alteon responded with a 503 error | prod00262264 |
| 48. | In an SSL environment with certificates, import of certificates in PFX format failed when the passphrase contained special characters such as '@'. | prod00262239 |
| 49. | In an SSL environment with certificates, import of certificates in PFX format failed when the passphrase contained special characters such as '@'. | prod00262238 |
| 50. | In an SLB environment with HTTP2 enabled on virtual services, sometimes Alteon stopped responding with resource issues. | prod00262190 |
| 51. | In a LinkProof environment, Alteon responded to customer requests without changing the server IP address to the Virtual Server IP address and server packets being handled by filter processing, causing the access to fail. | prod00262164 |
| 52. | In a gateway-per-VLAN environment, all the traffic to the Alteon interface and virtual server was sent back to the gateway based on the default gateway and not per the VLAN gateway, causing the feature to not work. | prod00262161 |
| 53. | Alteon modified the source IP address of hops on the traceroute path of UDP and TCP responses, causing the client to receive an incorrect result. | prod00262158 |
| 54. | When logging in to WBM through a data port, the WBM user login information was missing, and the incorrect client IP address was logged in the syslog message. | prod00262143 |
| 55. | In specific browsers (some versions of Chrome and Opera), which send some non-optimized HTTP2 HPACK header encodings that Alteon does not handle correctly, the PUT method did not work. | prod00262074 |

| Item | Description | Bug ID |
|------|--|--------------|
| 56. | After using the CLI command <code>/c/sys/syslog/cur</code> , the message <code>Syslog thread safe mode</code> displayed when it should not have. | prod00262045 |
| 57. | In an SLB environment, the PIP path under the virtual server (<code>/cfg/slb/virt <vsid>/service <vport> https/pip</code>) displayed in diff flash even though the settings were set to the default. | prod00262042 |
| 58. | When a primary group was configured without real servers associated with an FQDN server, the backup group used FQDN real servers, causing an Apply failure. | prod00262017 |
| 59. | Using WBM, in an SLB environment, you could not configure a Buddy Server. | prod00262010 |
| 60. | When the DNS server was down, Alteon stopped sending health checks with the destination as the hostname. | prod00261970 |
| 61. | Using WBM, when creating a Smart NAT dynamic NAT entry, the Local Address drop-down list included a None option which should have been named Any . | prod00261955 |
| 62. | Using WBM, when creating a new VRRP virtual router, the check box that is used to enable the virtual router was named Enable Virtual Routers instead of Enable Virtual Router . | prod00261953 |
| 63. | In an SLB environment with <code>rtsrccmac</code> enabled and reverse disabled, a request to a virtual server included an Allow filter, causing SLB traffic to fail. | prod00261909 |
| 64. | In a virtualization environment, when the ADC-VX was version 30.2.x and the vADC was version 31.0.x, there was a compatibility issue without proper information on an LACP trunk, causing port issues. | prod00261865 |
| 65. | In previous versions, client IP persistency could not be maintained when the SP CPU was selected based on the client IP address and port (VMASport enabled). | prod00261812 |
| 66. | In an SLB environment, changes to the network class associated to an in-route map required a BGP soft reset for the changes to take effect. | prod00261805 |
| 67. | When the audit log was enabled, Alteon sent a blank syslog for the delete operation. | prod00261801 |
| 68. | When monitoring Alteon using SNMP, when an SNMP GET was performed for a virtual server with <code>nonat</code> enabled (DSR), the current sessions displayed as NULL. | prod00261791 |

| Item | Description | Bug ID |
|------|--|--------------|
| 69. | In a Global SLB environment with the redirect exclusion feature enabled, Alteon selected a service for the DNS response with the action as "redirect" instead of resolving the DNS. | prod00261790 |
| 70. | In an SLB environment using CLI, when the xforward command was run for a service, the delayed binding forceproxy setting was not set. | prod00261789 |
| 71. | In the Monitoring environment with <code>/cfg/sys/report</code> set to on, a panic occurred with SIGSEGV(11) in thread RSTA(tid=81). | prod00261691 |
| 72. | When importing the configuration using REST API, Alteon always responded with a success message to the <code>agTftpLastActionStatus</code> query even though the import operation failed. | prod00261680 |
| 73. | In a Smart NAT environment, due to a sequence of validations in Global SLB, the warning messages for gmetric were confusing to the user. | prod00261630 |
| 74. | <p>When using Alteon as a relay agent, Alteon did not modify the source port when forwarding a request to a server that was on port 68. The server responded back as being on port 68, and Alteon dropped it as Alteon was listening only on port 67.</p> <p>Note: To fix this issue, a new CLI command was added: <code>/cfg/l3/bootp/prsvport</code></p> <p>When enabled, the source port is preserved.</p> <p>New MIBs that were created: <code>ipCurCfgBootpPrsvPort</code> <code>ipNewCfgBootpPrsvPort</code></p> | prod00261624 |
| 75. | In a LinkProof NG environment, when the source address was configured for proxy or SmartNAT 'Any' dynamic NAT, the Return to the source MAC address did not work for filter traffic and the return traffic did not behave as expected. | prod00261528 |
| 76. | In a LinkProof NG environment, the inbound proximity (gmetric proximity) did not work with Smart NAT. | prod00261523 |
| 77. | In a Smart NAT environment, Alteon forwarded the ICMP reply to the client without changing the source IP address to the public IP address. As a result, the VPN gateways could not be pinged using the public IP address. | prod00261521 |

| Item | Description | Bug ID |
|------|---|--------------|
| 78. | In an SLB environment with forceproxy, when HTTP content had to be replaced to HTTPS content, Alteon could not match the content-types application/json or application/xml, so Alteon could not replace this part of the HTTP code. As a result, the whole page appeared with issues. | prod00261493 |
| 79. | In an SLB environment with forceproxy, the content-based rules with FQDN servers were not working and returned 503 error. | prod00261490 |
| 80. | With a data class configured, when attempting to modify the same data class without performing an Apply, there was a discrepancy between the Alteon white list and the vDirect getextendedinfo configuration file. The diff displayed the modifications, but the Apply failed. | prod00261406 |
| 81. | On the Cloud WAF portal, with white lists for IP addresses having zero as the last octet, an Apply operation failure occurred. | prod00261121 |
| 82. | In the Advanced HTTP health check configuration, although the maximum number of characters for the Body parameter was stated as 1024 characters, only 512 characters were allowed. | prod00261017 |
| 83. | Using WBM, when a user logged in using TACACS and performed configuration changes, and later performed Apply/Save operations, the audit logs recorded another user ID and not the user who had logged in. | prod00260978 |
| 84. | In a virtualization environment, when the ADC-VX was version 30.5.x and the vADC was version 31.0.x, no applogs were generated. | prod00260946 |
| 85. | Using WBM, using \$PROTOCOL instead of http:// or https:// in the redirection URL for content rules action redirect or action redirect for a service did not work. | prod00260876 |
| 86. | In a DNS environment where DNS responses were received, and with VRRP or HA, performing a configuration sync ended with an FQDN error. | prod00260836 |
| 87. | In the SNMP Trap for certificate expiration altSwcertRevokedID, the description was incorrect. | prod00260830 |
| 88. | In a VRRP environment, after sync was performed, the server group setting was removed from the peer device. | prod00260808 |

| Item | Description | Bug ID |
|------|--|--------------|
| 89. | In an SLB environment with the round robin or least connections metric, and with a traffic pattern that had few connections that were opened with relatively long time periods between each other, after migrating all virtual servers from the 5208 platform to the 6420 platform, the round robin metric kept selecting only one specific real server from the server group and did not balance traffic to some servers. | prod00260669 |
| 90. | In WBM, the SLB Viewer user role was allowed to enable/disable physical ports, when this user role should only be able to view Alteon information, SLB statistics, and information, but should not be able to make any configuration changes. | prod00260641 |
| 91. | Using WBM, a real server's Description accepted 128 characters while only 31 characters are supported, causing the real server Description not to be synced from Active to Standby. | prod00260639 |
| 92. | In a virtualization environment, when accessing the device on an ADC-VX using REST API with an incorrect customized Authorization header value, a panic occurred. | prod00260598 |
| 93. | Alerts regarding DUAL PSU failure were generated, but after 6 seconds a notice was issued that the Status was Ok. This issue persisted even after changing to a new PSU. | prod00260597 |
| 94. | On a 6024 XL platform with 32 GB RAM, in Maximum vADC Density mode, you could not allocate the 12th CPU core (the fourth core for MP processing). | prod00260580 |
| 95. | Using REST API, image upload did not work. | prod00260564 |
| 96. | In an SLB environment, when a proxy IP address was defined in a network class, the proxy MAC address was sent with the gateway MAC address to those proxy IP addresses that were not present in the ARP table, causing the applications to fail. | prod00260562 |
| 97. | The load time of REST API calls was much slower than the load time in earlier Alteon versions. | prod00260509 |
| 98. | In an SLB environment with SSL Hello or HTTPS health checks configured, after upgrading to version 30.2.9.0, real servers configured with these health checks failed. | prod00260485 |
| 99. | In an SLB environment with the phash metric, the traffic load was unevenly distributed to real servers with random source IP addresses | prod00260470 |

| Item | Description | Bug ID |
|------|---|--------------|
| 100. | In an Outbound Link Load Balancing environment, LinkProof continued to send dispatching traffic towards WAN links whose bandwidth utilization was above 100%. | prod00260455 |
| 101. | You could not paste a geo network class configuration as taken from the configuration file and mandate it to add None for the Country and State fields. | prod00260454 |
| 102. | In a LinkProof environment configured with the bandwidth metric, Alteon did not select a WAN link based on the bandwidth metric configured on the DNS hostname and the DNS response included WAN links with the bandwidth overloaded. | prod00260453 |
| 103. | Using WBM with a WAN Link configuration, there were discrepancies between the upload bandwidth of the Per WAN Link IP and the Per WAN Link ID. | prod00260388 |
| 104. | Using WBM, when adding an IPv6 NAT IP address with the default prefix, because the IP address was added with prefix 0 instead of 128, the Apply operation failed. | prod00260360 |
| 105. | Using WBM, in a virtualization environment on an ADC-VX, the administrator could not change a vADC's administrator password. | prod00260333 |
| 106. | Using WBM or REST API with certificate repository management, you could not overwrite a certificate. | prod00260330 |
| 107. | In a BGP environment, after sending a BGP route update after a set of apply operations and a BGP toggle, a panic occurred. | prod00260322 |
| 108. | In a BGP environment, during BGP route update or when the BGP peer went down during BGP peer "cleanup," the platform hung. | prod00260321 |
| 109. | For unknown reasons, an unexpected reboot and a panic occurred. | prod00260320 |
| 110. | In an SLB environment, ESP traffic was not passed to the back-end servers. | prod00260297 |
| 111. | When using REST API to change the next image to boot, the correct image was not set. | prod00260261 |
| 112. | Using CLI, when configuring network classes, there were no validations when geo information was added for a network class as a one line command. | prod00260260 |
| 113. | Sometimes you could not configure a management port with an IPv6 address that was identical to one generated by SLAAC. | prod00260161 |

| Item | Description | Bug ID |
|------|---|--------------|
| 114. | In an SLB environment with delayed binding enabled and APM enabled, because Alteon did not create persistent entries for a few specific clients, Alteon sent the request from a specific Client IP address to a virtual service on Alteon to different real servers, even with the persistent binding Client IP address set on the virtual service. | prod00260097 |
| 115. | Using WBM, in an SSL environment, when enabling back-end SSL encryption and the back-end SSL cipher was selected as "user-defined," and then the back-end SSL encryption was disabled, the saved configuration was improper due to a malformed XML. | prod00260026 |
| 116. | In a virtualization environment on an ADC-VX, when using a REST API call to create a vADC, a panic occurred. | prod00259835 |
| 117. | In a virtualization environment on an ADC-VX, when a configuration import (putcfg) operation was performed via SNMP, a panic occurred on the ADC- VX. | prod00259831 |
| 118. | In an SLB environment with the health check configuration destination set as hostname, the health check failed after performing an apply operation. | prod00259830 |
| 119. | When SSH/Telnet connections exceeded the allowed limit, no syslog message generated. | prod00259797 |
| 120. | In a virtualization environment with vADCs on the same ADC-VX cross-connected, ARP responses were dropped, causing a gateway failure. | prod00259735 |
| 121. | In a failover scenario, when adding or updating more than 256 FDB entries from the MP to the SP, if the SP overloaded, the SP was not able to add the entries to the spfdb table, causing traffic disruptions in the network. | prod00259698 |
| 122. | In an AppWall for Alteon VA environment, techdata generation abruptly stopped and a reboot was required. | prod00259694 |
| 123. | When Alteon was accessed via SSH, the TCP connections opened for SSH sessions were not closed properly as the client continued to send data and caused stale TCP sessions. This led to SSH access failure to the device. | prod00259686 |

| Item | Description | Bug ID |
|------|---|--------------|
| 124. | In a virtualization environment, after manual reboot on a vADC and when the vADC was disabled/enabled using the ADC-VX, the Apply operation returned the following error message: vADC management changes due to a previous apply are currently under progress. Please try to apply the new changes after some time. | prod00259681 |
| 125. | Using WBM, in Monitoring > Network > High Availability , the VRRP labels were incorrect. | prod00259626 |
| 126. | <p>The vulnerability scan on the Alteon ADC-VX management IP address issued the following message: SSL/TLS Server supports TLSv1.0</p> <p>Note: Configuration for the TLS version was added (affecting management traffic only):</p> <p>In CLI: /cfg/sys/access/https/tlsver</p> <p>In WBM: System > Management Access > Management Protocol > HTTPS</p> | prod00259614 |
| 127. | In an SLB environment with persistent binding (pbind) configured with a cookie and Client IP, when Layer 4 sessions aged out, the reference count was decremented for the wrong persistent session, causing stale p-sessions. | prod00259581 |
| 128. | In a VRRP hot-standby environment, when the hot-standby port was designated as the next-hop port of the static ARP entry for a destination on the backup, a packet to the destination was sent out from that port even though it was in the Blocked state. | prod00259550 |
| 129. | In an SLB environment with FQDN real servers configured, on a virtual server with FQDN real servers, Alteon returned a 503 error even though the real servers were up. | prod00259492 |
| 130. | In an SLB environment with AppShape++ attached to a particular service, although always on was disabled, when the service went down, the request was forwarded to AppXcel. | prod00259436 |
| 131. | When attempting to upload a configuration to an RMA device, a panic occurred. | prod00259399 |
| 132. | In an SLB environment with AppShape++ configured, after aging, the TCP::close_type AppShape++ command returned an incorrect value in CLIENT_CLOSED, SERVER_CLOSED events. | prod00259384 |
| 133. | In an SLB environment with AppShape++ configured, after aging, TCP::close reset AppShape++ command did not send a reset when called from CLIENT_CLOSED, SERVER_CLOSED events. | prod00259334 |

| Item | Description | Bug ID |
|------|--|--------------|
| 134. | Using WBM, in a Layer 7 environment when a content class was deleted and a new one was created, some AX-related configuration errors displayed upon Apply/Revert Apply, leading to some AX traffic processing issues with the content class. | prod00259330 |
| 135. | In a VRRP environment, the backup Alteon did not change the source MAC and used the proxy MAC while routing the packet on the backup device. | prod00259179 |
| 136. | In a virtualization environment, after disabling a vADC, the vADC's internal syslogs were deleted from the ADC-VX. | prod00259152 |
| 137. | After generating a Tech Support dump or techdata, the resource allocation table information (/maint/debug/rsrddump) was missing. | prod00258995 |
| 138. | Outbound Telnet connections from ADC-VX/vADCs are not terminated when the respective inbound Telnet/SSH connections to the ADC-VX/vADCs are abruptly terminated, causing the user to not be able to access the ADC-VX after closing Telnet sessions abruptly. | prod00258970 |
| 139. | After configuring two interfaces, and not on same network, when a SNMP request was sent to one interface IP address, the response came from another interface. | prod00258932 |
| 140. | <p>In an HA environment, when the proxy IP range is configured under the network class and a failover occurs, a GARP was not sent for all the proxy IP addresses in the range.</p> <p>Note: The following new command was implemented: /cfg/l3/ha/nwclgarp ena/dis</p> <p>If the network class range is huge, then the GARP being sent affects the peers ARP table.</p> | prod00258850 |
| 141. | In an SLB environment with server groups, although the mhash configuration is only relevant for the minmisses metric, you could also configure it for other metrics (leastconn and svcleast), causing an Apply in these cases to fail. | prod00258826 |

AppWall

| Item | Description | Bug ID |
|------|---|---------|
| 1. | Could not add a Protected URI in CSRF with a double slash. | DE7213 |
| 2. | AppWall did not process an empty file with chunked transfer Encoding. | DE38763 |

| Item | Description | Bug ID |
|------|--|---------|
| 3. | The AppWall “Apply” RESTful API returned a failed code with the HTTPS tunnel in Monitor mode, even though the configuration was saved and applied. | DE38490 |
| 4. | Under certain conditions, JSON requests were not parsed correctly | DE38161 |
| 5. | The signature update did not update automatically. | DE37014 |
| 6. | AppWall identified a JSON parsing failure although the JSON was correct. | DE36913 |
| 7. | After a response parsing violation, the transaction ID in the security page did not display | DE36297 |
| 8. | The Max Reply header size was enforced to 1024 instead of being unlimited. | DE35625 |
| 9. | There was a conflict in the Policy Role importing policy Distribution file. | DE39462 |
| 10. | Under certain conditions, trimming failed to process. | DE39460 |
| 11. | When AppWall logged events about security violations of the Parameters filter, AppWall presented in the security events all the refinements related to the Web Application contain in the Parameter filter. This caused AppWall to log fewer Security events. Usually AppWall can log up to 350 000 events. The Parameters filter created a security event with a size of 53KB. After approximately 4,700 security events, the Security file reached the limit of 250 MB and AppWall deleted 20% of the database and generated new events in the system log. | DE21382 |

Fixed in 32.0.1.101

Version 32.0.1.101 includes all field bugs available in version 31.0.5.0.

| Item | Description | Bug ID |
|------|---|---------|
| 1. | GEL – An Alteon VA deployed by vDirect from a cloned image could not communicate with the License Server. | DE35719 |
| 2. | GEL – The license was rejected when the Local License Server (LLS) returned a busy status. | TA64369 |

Fixed in 32.0.1.100

Version 32.0.1.100 includes all field bugs available in version 31.0.5.0.

| Item | Description | Bug ID |
|------|--|---|
| 1. | In an SLB environment with delayed binding forceproxy and cookie insert persistency, when running traffic with a cookie header, a <code>503 service unavailable</code> message was returned without serving the request. | DE37403 (prod00262228, prod00262097) |

Fixed in 32.0.1.0

| Item | Description | Bug ID |
|------|--|--------------|
| 1. | Using WBM, it was not possible to add or edit vADCs | prod00261306 |
| 2. | In a Smart NAT environment, due to the sequence of validations in Global SLB, the warning messages for gmetric were confusing to the user. Note: The proximity metric for Inbound Link Load Balancing rules with Smart NAT is not yet supported. | prod00260963 |
| 3. | In a Smart NAT environment with Global SLB turned off and LinkProof turned on, the validations related to Smart NAT were skipped and no warning messages were issued. Note: Proximity is not yet supported for SmartNAT. | prod00260961 |
| 4. | In a DNS environment where DNS responses were received, and with VRRP or HA, performing a configuration sync ended with an FQDN error. | prod00260835 |
| 5. | In a VRRP environment, after sync was performed, the server group setting was removed from the peer device. | prod00260807 |
| 6. | In an SLB environment with the round robin or least connections metric, and with a traffic pattern that had few connections that were opened with relatively long time periods between each other, after migrating all virtual servers from the 5208 platform to the 6420 platform, the round robin metric kept selecting only one specific real server from the server group and did not balance traffic to some servers. | prod00260667 |
| 7. | In WBM, the SLB Viewer user role was allowed to enable/disable physical ports, when this user role should only be able to view Alteon information, SLB statistics, and information, but should not be able to make any configuration changes. | prod00260640 |

| Item | Description | Bug ID |
|------|--|--------------|
| 8. | Using WBM, a real server's Description accepted 128 characters while only 31 characters are supported, causing the real server Description not to be synced from Active to Standby. | prod00260637 |
| 9. | Alerts regarding DUAL PSU failure were generated, but after 6 seconds a notice was issued that the Status was Ok. This issue persisted even after changing to a new PSU. | prod00260596 |
| 10. | On a 6024 XL platform with 32 GB RAM, in Maximum vADC Density mode, you could not allocate the twelfth (12th) CPU core (the fourth core for MP processing). | prod00260579 |
| 11. | In a virtualization environment, when accessing the device on an ADC-VX using REST API with an incorrect customized Authorization header value, a panic occurred. | prod00260578 |
| 12. | Using REST API, image upload did not work. | prod00260563 |
| 13. | In an SLB environment, when a proxy IP address was defined in a network class, the proxy MAC address was sent with the gateway MAC address to those proxy IP addresses that were not present in the ARP table, causing the applications to fail. | prod00260560 |
| 14. | The load time of REST API calls was much slower than the load time in earlier Alteon versions. | prod00260508 |
| 15. | In an SLB environment with SSL Hello or HTTPS health checks configured, after upgrading to version 30.2.9.0, real servers configured with these health checks failed. | prod00260484 |
| 16. | In an SLB environment with the phash metric, the traffic load was unevenly distributed to real servers with random source IP addresses. | prod00260469 |
| 17. | In an Outbound Link Load Balancing environment, LinkProof continued to send dispatching traffic towards WAN links whose bandwidth utilization was above 100%. | prod00260451 |
| 18. | You could not paste a geo network class configuration as taken from the configuration file and mandate it to add None for the Country and State fields. | prod00260450 |
| 19. | In a LinkProof environment configured with the bandwidth metric, Alteon did not select a WAN link based on the bandwidth metric configured on the DNS hostname and the DNS response included WAN links with the bandwidth overloaded. | prod00260449 |
| 20. | Using WBM with a WAN Link configuration, there were discrepancies between the upload bandwidth of the Per WAN Link IP and the Per WAN Link ID . | prod00260386 |

| Item | Description | Bug ID |
|------|---|--------------|
| 21. | Using WBM, when adding an IPv6 NAT IP address with the default prefix, because the IP address was added with prefix 0 instead of 128, the Apply operation failed. | prod00260359 |
| 22. | Using WBM or REST API with certificate repository management, you could not overwrite a certificate. | prod00260329 |
| 23. | In a BGP environment, after sending a BGP route update after a set of apply operations and a BGP toggle, a panic occurred | prod00260319 |
| 24. | In a BGP environment, during BGP route update or when the BGP peer went down during BGP peer "cleanup," the platform hung. | prod00260318 |
| 25. | For unknown reasons, an unexpected reboot and a panic occurred. | prod00260317 |
| 26. | In an SLB environment, ESP traffic was not passed to the back-end servers. | prod00260296 |
| 27. | When using REST API to change the next image to boot, the correct image was not set. | prod00260259 |
| 28. | Using CLI, when configuring network classes, there were no validations when geo information was added for a network class as a one line command. | prod00260258 |
| 29. | In an SLB environment with delayed binding enabled and APM enabled, because Alteon did not create persistent entries for a few specific clients, Alteon sent the request from a specific Client IP address to a virtual service on Alteon to different real servers, even with the persistent binding Client IP address set on the virtual service. | prod00260096 |
| 30. | Due to a large file size, the techdata generation failed with the following message: <code>Unknown Error</code> | prod00260082 |
| 31. | Using WBM, in an SSL environment, when enabling back-end SSL encryption and the back-end SSL cipher was selected as "user-defined," and then the back-end SSL encryption was disabled, the saved configuration was improper due to a malformed XML. | prod00260025 |
| 32. | In a virtualization environment on an ADC-VX, when using a REST API call to create a vADC, a panic occurred. | prod00259834 |
| 33. | In an SLB environment with the health check configuration destination set as hostname, the health check failed after performing an apply operation. | prod00259829 |

| Item | Description | Bug ID |
|------|---|--------------|
| 34. | In a virtualization environment on an ADC-VX, when a configuration import (putcfg) operation was performed via SNMP, a panic occurred on the ADC- VX. | prod00259828 |
| 35. | When SSH/Telnet connections exceeded the allowed limit, no syslog message generated. | prod00259798 |
| 36. | In a virtualization environment with vADCs on the same ADC-VX cross-connected, ARP responses were dropped, causing a gateway failure. | prod00259734 |
| 37. | In an AppWall for Alteon VA environment, techdata generation abruptly stopped and a reboot was required. | prod00259693 |
| 38. | When Alteon was accessed via SSH, the TCP connections opened for SSH sessions were not closed properly as the client continued to send data and caused stale TCP sessions. This led to SSH access failure to the device. | prod00259684 |
| 39. | Using WBM, in Monitoring > Network > High Availability , the VRRP labels were incorrect. | prod00259625 |
| 40. | In an SLB environment with persistent binding (pbind) configured with a cookie and Client IP, when Layer 4 sessions aged out, the reference count was decremented for the wrong persistent session, causing stale p-sessions. | prod00259580 |
| 41. | Using WBM, using \$PROTOCOL instead of http:// or https:// in the redirection URL for content rules action redirect or action redirect for a service did not work. | prod00259520 |
| 42. | In an SLB environment with FQDN real servers configured, on a virtual server with FQDN real servers, Alteon returned a 503 error even though the real servers were up. | prod00259491 |
| 43. | In an HA environment, although synchronization was successful, the backup device issued the following error: HA : Configuration is not synchronized between the HA devices | prod00259438 |
| 44. | In a Geo proximity configuration, you could not set the country Niger in an Alteon GEO network class. | prod00259435 |
| 45. | In an SLB environment, when submitting a service (that supports non-standard ports) with a standard port, although the Alteon bank-end returned an error, due to the standard port, Alteon internally configured the corresponding service even after issuing the error without informing the user. | prod00259422 |

| Item | Description | Bug ID |
|------|--|--------------|
| 46. | In a virtualization environment, after manual reboot on a vADC and when the vADC was disabled/enabled using the ADC-VX, the Apply operation returned the following error message: vADC management changes due to a previous apply are currently under progress. Please try to apply the new changes after some time. | prod00259410 |
| 47. | When attempting to upload a configuration to an RMA device, a panic occurred. | prod00259398 |
| 48. | In an SLB environment with AppShape++ configured, after aging, the TCP::close_type AppShape++ command returned an incorrect value in CLIENT_CLOSED, SERVER_CLOSED events | prod00259383 |
| 49. | In an SLB environment with AppShape++ configured, after aging, TCP::close reset AppShape++ command did not send a reset when called from CLIENT_CLOSED, SERVER_CLOSED events. | prod00259333 |
| 50. | Using WBM, in a Layer 7 environment when a content class was deleted and a new one was created, some AX-related configuration errors displayed upon Apply/Revert Apply, leading to some AX traffic processing issues with the content class. | prod00259329 |
| 51. | In a VRRP environment, the backup Alteon did not change the source MAC address and used the proxy MAC address while routing the packet on the backup device. | prod00259178 |
| 52. | In a virtualization environment, after disabling a vADC, the vADC's internal syslogs were deleted from the ADC-VX. | prod00259151 |
| 53. | <p>The vulnerability scan on the Alteon ADC-VX management IP address issued the following message: SSL/TLS Server supports TLSv1.0</p> <p>Note: Configuration for the TLS version was added (affecting management traffic only):</p> <p>In CLI: <code>/cfg/sys/access/https/tlsver</code></p> <p>In WBM: System > Management Access > Management Protocol > HTTPS</p> | prod00258998 |
| 54. | Outbound Telnet connections from ADC-VX/vADCs are not terminated when the respective inbound Telnet/SSH connections to the ADC-VX/vADCs are abruptly terminated, causing the user to not be able to access the ADC-VX after closing Telnet sessions abruptly. | prod00258969 |

| Item | Description | Bug ID |
|------|--|--------------|
| 55. | After generating a Tech Support dump or techdata, the resource allocation table information (/maint/debug/rsrddump) was missing. | prod00258963 |
| 56. | After configuring two interfaces, and not on same network, when a SNMP request was sent to one interface IP address, the response came from another interface. | prod00258925 |
| 57. | <p>In an HA environment, when the proxy IP range is configured under the network class and a failover occurs, a GARP was not sent for all the proxy IP addresses in the range.</p> <p>Note: The following new command was implemented: <code>/cfg/l3/ha/nwclgarp ena/dis</code></p> <p>If the network class range is huge, then the GARP being sent affects the peers ARP table.</p> | prod00258854 |
| 58. | Sometimes you could not configure a management port with an IPv6 address that was identical to one generated by SLAAC. | prod00258853 |
| 59. | In an SLB environment with AppShape++ attached to a particular service, although always on was disabled, when the service went down, the request was forwarded to AppXcel. | prod00258825 |
| 60. | In an SLB environment with IPv4 and IPv6 services and IPv6 PIP configured, a panic occurred. | prod00258580 |
| 61. | In an SLB environment with server groups, although the mhash configuration is only relevant for the minmisses metric, you could also configure it for other metrics (leastconn and svcleast), causing an Apply in these cases to fail. | prod00258549 |
| 62. | In an AppWall for Alteon environment, when an APSolute Vision syslog came from AppWall through the proxy, and LDAP traffic also used the proxy, Web Authentication via AppWall stopped working. | prod00258525 |
| 63. | Using WBM, in a virtualization environment on an ADC-VX, the administrator could not change a vADC's administrator password. | prod00258405 |
| 64. | In an SLB environment with session mirroring enabled for virtual services, the session statistics were incorrect on the backup device compared to the primary device. | prod00258381 |
| 65. | For DNS Responder virtual servers with DNS over UDP only, DNS resolution failed. | prod00258374 |
| 66. | Using WBM, in an SLB monitoring environment, the real server IP addresses for a server group were displayed incorrectly. | prod00258332 |

| Item | Description | Bug ID |
|------|---|--------------------|
| 67. | When logging into WBM using TACACS and performing configuration changes and later performing Apply/Save operations, in the audit logs another user ID was recorded instead of the user who logged in. | prod00257825 |
| 68. | SSL Hello health checks using TLS (instead of SSL v2/v3) were not working on XL/Extreme platforms. | DE34416 |
| 69. | From WBM, you cannot change the vADC management IP address from within the ADC-VX environment. | prod00216388 |
| 70. | Parameter security events may cause excessive or high event size. | DE21382 |
| 71. | Details button was missing in the Database Security Filter view. | DE25177 |
| 72. | Under certain conditions, SSL termination causes SSL session traffic interruptions in passive mode. | DE30899 |
| 73. | Vulnerability security refinement in a defined Virtual Directory doesn't block traffic. | DE31063 |
| 74. | Failure in the Blocked Source table (Source Blocking) due to a failure in the Fingerprint hash value. | DE31964 |
| 75. | After multiple consecutive memory dumps, log partition becomes full. | DE32927 |
| 76. | Database security filter blocks legitimate HTTP requests. | DE33867 |
| 77. | Compatibility error message with web browser when using Activity Tracking fingerprint based with Vulnerabilities security filter. | DE34015 |
| 78. | Failure in the Database security filter after an upgrade with an AppWall version older than 5.7.2. | DE34070 |
| 79. | Refinement error message when trying to refine an HTTP reply size header. | DE34119 |
| 80. | Duplicate IP Group and Security WebApplication Role when using the API call with import option for policy distribution. | DE34185 DE34453 |
| 81. | Hosts based configurations that contain a wildcard are not taken into consideration. | DE35113 |
| 82. | Under certain conditions, Database security refinement disappears. | DE35457 |
| 83. | Under certain conditions, a failure occurs with huge HTTP response request. | DE32953 |
| 84. | After a failed Apply operation, the tunnel cannot be initialized. | DE21581 |

| Item | Description | Bug ID |
|------|--|---------|
| 85. | Failure occurs in Fast Upload | DE33520 |
| 86. | AppWall Management Application failures when refreshing the forensics view with a very high of events | DE30806 |
| 87. | Go to Policy button in Forensics view generate an AppWall Management Application exception for RFC Violated Security Events. | DE31200 |
| 88. | Failure in the AppWall Management Application occurred after creating a complex REGEX in the security policies settings | DE33872 |
| 89. | Wrong IP address in the syslog messages | DE34357 |

Fixed in 32.0.0.0

Version 32.0.0.0 includes all field bugs available in version 31.0.4.0.

KNOWN LIMITATIONS

The list of known limitations, available to customers only, is available at the following link:

https://support.radware.com/app/answers/answer_view/a_id/1021441

RELATED DOCUMENTATION

- *Alteon Installation and Maintenance Guide*
- *Alteon VA Installation and Maintenance Guide*
- *Alteon Getting Started Guide*
- *Alteon Web Based Management Application Guide*
- *Alteon Command Line Interface Application Guide*
- *Alteon Command Reference*
- *Alteon REST API User Guide*
- *Alteon AppShape++ SDK Guide*
- *AppWall for Alteon NG User Guide*
- *FastView for Alteon NG User Guide*
- *LinkProof for Alteon NG User Guide*
- *LinkProof NG User Guide*



North America
Radware Inc.
575 Corporate Drive
Mahwah, NJ 07430
Tel: +1-888-234-5763

International
Radware Ltd.
22 Raoul Wallenberg St.
Tel Aviv 69710, Israel
Tel: 972 3 766 8666

© 2022 Radware, Ltd. All Rights Reserved. Radware and all other Radware product and service names are registered trademarks of Radware in the U.S. and other countries. All other trademarks and names are the property of their respective owners. Printed in the U.S.A.